

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-3/29/06	030609740-0001	Southwest Area (sidewalk bridge level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST2-3/29/06	030609740-0002	Southeast Area (sidewalk bridge level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST4-3/29/06	030609740-0003	Northwest Area (street-level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST5-3/29/06	030609740-0004	Firehouse #10 (roof level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST10-3/29/06	030609740-0005	North Side Sidewalk Bridge	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST11-3/29/06	030609740-0006	90 Trinity Place (roof level)	3/29/06	1	2.820	Asbestos	PCME	EMSL	3/30/06	< 0.00088	No	No	
ASBESTOS-ST12-3/29/06	030609740-0007	110 Greenwich Street (roof level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST13-3/29/06	030609740-0008	Marriott Hotel, 38th Floor (roof level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST14-3/29/06	030609740-0009	West Face - South end at corner (scaffolding level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST15-3/29/06	030609740-0010	South Face - East end at corner (scaffolding level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST17-3/29/06	030609740-0012	North Face - West end at corner (scaffolding level)	3/29/06	1	3.000	Asbestos	PCME	EMSL	3/30/06	< 0.00082	No	No	
ASBESTOS-ST1-3/30/06	030609865-0001	Southwest Area (sidewalk bridge level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST2-3/30/06	030609865-0002	Southeast Area (sidewalk bridge level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST4-3/30/06	030609865-0003	Northwest Area (street-level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST5-3/30/06	030609865-0004	Firehouse #10 (roof level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST10-3/30/06	030609865-0005	North Side Sidewalk Bridge	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST11-3/30/06	030609865-0006	90 Trinity Place (roof level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00088	No	No	
ASBESTOS-ST12-3/30/06	030609865-0007	110 Greenwich Street (roof level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST13-3/30/06	030609865-0008	Marriott Hotel, 38th Floor (roof level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST14-3/30/06	030609865-0009	West Face - South end at corner (scaffolding level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST15-3/30/06	030609865-0010	South Face - East end at corner (scaffolding level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST16-3/30/06	030609865-0011	East Face - North end at corner (scaffolding level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	
ASBESTOS-ST17-3/30/06	030609865-0012	North Face - West end at corner (scaffolding level)	3/30/06	1	3.000	Asbestos	PCME	EMSL	3/31/06	< 0.00082	No	No	

Note:

1. The asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on March 29, 2006 was not available for analysis on account of filter damage.