

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-3/30/07	030710127-0001	Southwest Area (sidewalk bridge level)	3/30/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST2-3/30/07	030710127-0002	Southeast Area (sidewalk bridge level)	3/30/07	1	3.050	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST4-3/30/07	030710127-0003	Northwest Area (street-level)	3/30/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00075	No	No	
ASBESTOS-ST5-3/30/07	030710127-0004	Firehouse #10 (roof level)	3/30/07	1	3.090	Asbestos	PCME	EMSL	4/2/07	< 0.00080	No	No	
ASBESTOS-ST10-3/30/07	030710127-0005	North Side Sidewalk Bridge	3/30/07	1	3.060	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST11-3/30/07	030710127-0006	90 Trinity Place (roof level)	3/30/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST12-3/30/07	030710127-0007	110 Greenwich Street (roof level)	3/30/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST13-3/30/07	030710127-0008	Marriott Hotel, 38th Floor (roof level)	3/30/07	1	3.030	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST14-3/30/07	030710127-0009	West Face - South end at corner (scaffolding level)	3/30/07	1	3.100	Asbestos	PCME	EMSL	4/2/07	< 0.00080	No	No	
ASBESTOS-ST15-3/30/07	030710127-0010	South Face - East end at corner (scaffolding level)	3/30/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST16-3/30/07	030710127-0011	East Face - North end at corner (scaffolding level)	3/30/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST17-3/30/07	030710127-0012	North Face - West end at corner (scaffolding level)	3/30/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST1-3/31/07	030710122-0001	Southwest Area (sidewalk bridge level)	3/31/07	1	3.050	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST2-3/31/07	030710122-0002	Southeast Area (sidewalk bridge level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST4-3/31/07	030710122-0003	Northwest Area (street-level)	3/31/07	1	3.010	Asbestos	PCME	EMSL	4/2/07	< 0.00076	No	No	
ASBESTOS-ST5-3/31/07	030710122-0004	Firehouse #10 (roof level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST10-3/31/07	030710122-0005	North Side Sidewalk Bridge	3/31/07	1	3.060	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST11-3/31/07	030710122-0006	90 Trinity Place (roof level)	3/31/07	1	3.030	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST12-3/31/07	030710122-0007	110 Greenwich Street (roof level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST13-3/31/07	030710122-0008	Marriott Hotel, 38th Floor (roof level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST14-3/31/07	030710122-0009	West Face - South end at corner (scaffolding level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST15-3/31/07	030710122-0010	South Face - East end at corner (scaffolding level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST16-3/31/07	030710122-0011	East Face - North end at corner (scaffolding level)	3/31/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST17-3/31/07	030710122-0012	North Face - West end at corner (scaffolding level)	3/31/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST1-4/01/07	030710123-0001	Southwest Area (sidewalk bridge level)	4/1/07	1	3.150	Asbestos	PCME	EMSL	4/2/07	< 0.00078	No	No	
ASBESTOS-ST2-4/01/07	030710123-0002	Southeast Area (sidewalk bridge level)	4/1/07	1	3.050	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST4-4/01/07	030710123-0003	Northwest Area (street-level)	4/1/07	1	2.980	Asbestos	PCME	EMSL	4/2/07	< 0.00076	No	No	
ASBESTOS-ST5-4/01/07	030710123-0004	Firehouse #10 (roof level)	4/1/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST10-4/01/07	030710123-0005	North Side Sidewalk Bridge	4/1/07	1	3.020	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST11-4/01/07	030710123-0006	90 Trinity Place (roof level)	4/1/07	1	2.980	Asbestos	PCME	EMSL	4/2/07	< 0.00083	No	No	
ASBESTOS-ST12-4/01/07	030710123-0007	110 Greenwich Street (roof level)	4/1/07	1	3.010	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	
ASBESTOS-ST13-4/01/07	030710123-0008	Marriott Hotel, 38th Floor (roof level)	4/1/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST14-4/01/07	030710123-0009	West Face - South end at corner (scaffolding level)	4/1/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST15-4/01/07	030710123-0010	South Face - East end at corner (scaffolding level)	4/1/07	1	3.030	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST16-4/01/07	030710123-0011	East Face - North end at corner (scaffolding level)	4/1/07	1	3.040	Asbestos	PCME	EMSL	4/2/07	< 0.00081	No	No	
ASBESTOS-ST17-4/01/07	030710123-0012	North Face - West end at corner (scaffolding level)	4/1/07	1	3.010	Asbestos	PCME	EMSL	4/2/07	< 0.00082	No	No	