

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										<b>0.0009</b>	Air Quality Levels	Site Specific Trigger Levels		
										<b>NA</b>				
<b>Target Air Quality Levels</b>														
<b>EPA Site Specific Trigger Levels</b>														
ASBESTOS-ST1-3/30/09	030908176-0001	Southwest Area (sidewalk bridge level)	3/30/09	1	3.070	Asbestos	PCME	EMSL	3/31/09	< 0.00080	No	No		
ASBESTOS-ST2-3/30/09	030908176-0002	Southeast Area (sidewalk bridge level)	3/30/09	1	3.100	Asbestos	PCME	EMSL	3/31/09	< 0.00080	No	No		
ASBESTOS-ST4-3/30/09	030908176-0003	Northwest Area (street-level)	3/30/09	1	3.010	Asbestos	PCME	EMSL	3/31/09	< 0.00082	No	No		
ASBESTOS-ST5-3/30/09	030908176-0004	Firehouse #10 (roof level)	3/30/09	1	3.110	Asbestos	PCME	EMSL	3/31/09	< 0.00079	No	No		
ASBESTOS-ST10-3/30/09	030908176-0005	North Side Sidewalk Bridge	3/30/09	1	3.120	Asbestos	PCME	EMSL	3/31/09	< 0.00079	No	No		
ASBESTOS-ST11-3/30/09	030908176-0006	90 Trinity Place (roof level)	3/30/09	1	3.040	Asbestos	PCME	EMSL	3/31/09	< 0.00081	No	No		
ASBESTOS-ST12-3/30/09	030908176-0007	110 Greenwich Street (roof level)	3/30/09	1	3.030	Asbestos	PCME	EMSL	3/31/09	< 0.00081	No	No		
ASBESTOS-ST13-3/30/09	030908176-0008	Marriott Hotel, 38th Floor (roof level)	3/30/09	1	3.040	Asbestos	PCME	EMSL	3/31/09	< 0.00081	No	No		
ASBESTOS-ST14-3/30/09	030908176-0009	West Face - South end at corner (scaffolding level)	3/30/09	1	3.140	Asbestos	PCME	EMSL	3/31/09	< 0.00079	No	No		
ASBESTOS-ST15-3/30/09	030908176-0010	South Face - East end at corner (scaffolding level)	3/30/09	1	3.070	Asbestos	PCME	EMSL	3/31/09	< 0.00080	No	No		
ASBESTOS-ST16-3/30/09	030908176-0011	East Face - North end at corner (scaffolding level)	3/30/09	1	3.060	Asbestos	PCME	EMSL	3/31/09	< 0.00081	No	No		
ASBESTOS-ST17-3/30/09	030908176-0012	North Face - West end at corner (scaffolding level)	3/30/09	1	3.010	Asbestos	PCME	EMSL	3/31/09	< 0.00082	No	No		
ASBESTOS-ST1-3/31/09	030908304-0001	Southwest Area (sidewalk bridge level)	3/31/09	1	3.160	Asbestos	PCME	EMSL	4/1/09	< 0.00078	No	No		
ASBESTOS-ST2-3/31/09	030908304-0002	Southeast Area (sidewalk bridge level)	3/31/09	1	3.100	Asbestos	PCME	EMSL	4/1/09	< 0.00080	No	No		
ASBESTOS-ST4-3/31/09	030908304-0003	Northwest Area (street-level)	3/31/09	1	3.080	Asbestos	PCME	EMSL	4/1/09	< 0.00080	No	No		
ASBESTOS-ST5-3/31/09	030908304-0004	Firehouse #10 (roof level)	3/31/09	1	2.970	Asbestos	PCME	EMSL	4/1/09	< 0.00083	No	No		
ASBESTOS-ST10-3/31/09	030908304-0005	North Side Sidewalk Bridge	3/31/09	1	3.020	Asbestos	PCME	EMSL	4/1/09	< 0.00082	No	No		
ASBESTOS-ST100-3/31/09	030908304-0013	Station 10 Field Duplicate	3/31/09	1	3.170	Asbestos	PCME	EMSL	4/1/09	< 0.00078	No	No		
ASBESTOS-ST11-3/31/09	030908304-0006	90 Trinity Place (roof level)	3/31/09	1	3.040	Asbestos	PCME	EMSL	4/1/09	< 0.00081	No	No		
ASBESTOS-ST12-3/31/09	030908304-0007	110 Greenwich Street (roof level)	3/31/09	1	3.110	Asbestos	PCME	EMSL	4/1/09	< 0.00079	No	No		
ASBESTOS-ST13-3/31/09	030908304-0008	Marriott Hotel, 38th Floor (roof level)	3/31/09	1	2.990	Asbestos	PCME	EMSL	4/1/09	< 0.00083	No	No		
ASBESTOS-ST14-3/31/09	030908304-0009	West Face - South end at corner (scaffolding level)	3/31/09	1	3.120	Asbestos	PCME	EMSL	4/1/09	< 0.00079	No	No		
ASBESTOS-ST15-3/31/09	030908304-0010	South Face - East end at corner (scaffolding level)	3/31/09	1	3.020	Asbestos	PCME	EMSL	4/1/09	< 0.00082	No	No		
ASBESTOS-ST16-3/31/09	030908304-0011	East Face - North end at corner (scaffolding level)	3/31/09	1	2.980	Asbestos	PCME	EMSL	4/1/09	< 0.00083	No	No		
ASBESTOS-ST17-3/31/09	030908304-0012	North Face - West end at corner (scaffolding level)	3/31/09	1	3.020	Asbestos	PCME	EMSL	4/1/09	< 0.00082	No	No		