

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-3/31/06	030610050-0001	Southwest Area (sidewalk bridge level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST2-3/31/06	030610050-0002	Southeast Area (sidewalk bridge level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST4-3/31/06	030610050-0003	Northwest Area (street-level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST5-3/31/06	030610050-0004	Firehouse #10 (roof level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST10-3/31/06	030610050-0005	North Side Sidewalk Bridge	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00080	No	No	
ASBESTOS-ST11-3/31/06	030610050-0006	90 Trinity Place (roof level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00088	No	No	
ASBESTOS-ST12-3/31/06	030610050-0007	110 Greenwich Street (roof level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST13-3/31/06	030610050-0008	Marriott Hotel, 38th Floor (roof level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST14-3/31/06	030610050-0009	West Face - South end at corner (scaffolding level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST15-3/31/06	030610050-0010	South Face - East end at corner (scaffolding level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST16-3/31/06	030610050-0011	East Face - North end at corner (scaffolding level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST17-3/31/06	030610050-0012	North Face - West end at corner (scaffolding level)	3/31/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST1-4/1/06	030610055-0001	Southwest Area (sidewalk bridge level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST2-4/1/06	030610055-0002	Southeast Area (sidewalk bridge level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST4-4/1/06	030610055-0003	Northwest Area (street-level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST5-4/1/06	030610055-0004	Firehouse #10 (roof level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST10-4/1/06	030610055-0005	North Side Sidewalk Bridge	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST11-4/1/06	030610055-0006	90 Trinity Place (roof level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00088	No	No	
ASBESTOS-ST12-4/1/06	030610055-0007	110 Greenwich Street (roof level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST13-4/1/06	030610055-0008	Marriott Hotel, 38th Floor (roof level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST14-4/1/06	030610055-0009	West Face - South end at corner (scaffolding level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST15-4/1/06	030610055-0010	South Face - East end at corner (scaffolding level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST16-4/1/06	030610055-0011	East Face - North end at corner (scaffolding level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST17-4/1/06	030610055-0012	North Face - West end at corner (scaffolding level)	4/1/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST1-4/2/06	030610051-0001	Southwest Area (sidewalk bridge level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST2-4/2/06	030610051-0002	Southeast Area (sidewalk bridge level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST4-4/2/06	030610051-0003	Northwest Area (street-level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST5-4/2/06	030610051-0004	Firehouse #10 (roof level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST10-4/2/06	030610051-0005	North Side Sidewalk Bridge	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST11-4/2/06	030610051-0006	90 Trinity Place (roof level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST12-4/2/06	030610051-0007	110 Greenwich Street (roof level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST13-4/2/06	030610051-0008	Marriott Hotel, 38th Floor (roof level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST14-4/2/06	030610051-0009	West Face - South end at corner (scaffolding level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST15-4/2/06	030610051-0010	South Face - East end at corner (scaffolding level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	
ASBESTOS-ST17-4/2/06	030610051-0012	North Face - West end at corner (scaffolding level)	4/2/06	1	3.000	Asbestos	PCME	EMSL	4/3/06	< 0.00082	No	No	

Note:

1. Asbestos sample at Station 16 on April 2, 2006 was not available for analysis on account of filter damage.