

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-4/1/09	030908560-0001	Southwest Area (sidewalk bridge level)	4/1/09	1	3.840	Asbestos	PCME	EMSL	4/3/09	< 0.00064	No	No	Note 1, 2
ASBESTOS-ST2-4/1/09	030908402-0001	Southeast Area (sidewalk bridge level)	4/1/09	1	2.950	Asbestos	PCME	EMSL	4/2/09	< 0.00084	No	No	
ASBESTOS-ST4-4/1/09	030908402-0002	Northwest Area (street-level)	4/1/09	1	2.900	Asbestos	PCME	EMSL	4/2/09	< 0.00085	No	No	
ASBESTOS-ST5-4/1/09	030908402-0003	Firehouse #10 (roof level)	4/1/09	1	2.960	Asbestos	PCME	EMSL	4/2/09	< 0.00083	No	No	
ASBESTOS-ST10-4/1/09	030908402-0004	North Side Sidewalk Bridge	4/1/09	1	2.940	Asbestos	PCME	EMSL	4/2/09	< 0.00084	No	No	
ASBESTOS-ST11-4/1/09	030908402-0005	90 Trinity Place (roof level)	4/1/09	1	2.950	Asbestos	PCME	EMSL	4/2/09	< 0.00084	No	No	
ASBESTOS-ST12-4/1/09	030908402-0006	110 Greenwich Street (roof level)	4/1/09	1	3.010	Asbestos	PCME	EMSL	4/2/09	< 0.00082	No	No	
ASBESTOS-ST13-4/1/09	030908402-0007	Marriott Hotel, 38th Floor (roof level)	4/1/09	1	2.970	Asbestos	PCME	EMSL	4/2/09	< 0.00083	No	No	
ASBESTOS-ST14-4/1/09	030908402-0008	West Face - South end at corner (scaffolding level)	4/1/09	1	3.090	Asbestos	PCME	EMSL	4/2/09	< 0.00080	No	No	
ASBESTOS-ST15-4/1/09	030908402-0009	South Face - East end at corner (scaffolding level)	4/1/09	1	2.930	Asbestos	PCME	EMSL	4/2/09	< 0.00084	No	No	
ASBESTOS-ST16-4/1/09	030908402-0010	East Face - North end at corner (scaffolding level)	4/1/09	1	2.970	Asbestos	PCME	EMSL	4/2/09	< 0.00083	No	No	
ASBESTOS-ST17-4/1/09	030908402-0011	North Face - West end at corner (scaffolding level)	4/1/09	1	2.980	Asbestos	PCME	EMSL	4/2/09	< 0.00083	No	No	
ASBESTOS-ST2-4/2/09	030908560-0002	Southeast Area (sidewalk bridge level)	4/2/09	1	3.140	Asbestos	PCME	EMSL	4/3/09	< 0.00079	No	No	
ASBESTOS-ST4-4/2/09	030908560-0003	Northwest Area (street-level)	4/2/09	1	3.170	Asbestos	PCME	EMSL	4/3/09	< 0.00078	No	No	
ASBESTOS-ST5-4/2/09	030908560-0004	Firehouse #10 (roof level)	4/2/09	1	3.000	Asbestos	PCME	EMSL	4/3/09	< 0.00082	No	No	
ASBESTOS-ST10-4/2/09	030908560-0005	North Side Sidewalk Bridge	4/2/09	1	3.090	Asbestos	PCME	EMSL	4/3/09	< 0.00080	No	No	
ASBESTOS-ST11-4/2/09	030908560-0006	90 Trinity Place (roof level)	4/2/09	1	3.020	Asbestos	PCME	EMSL	4/3/09	< 0.00082	No	No	
ASBESTOS-ST12-4/2/09	030908560-0007	110 Greenwich Street (roof level)	4/2/09	1	2.960	Asbestos	PCME	EMSL	4/3/09	< 0.00083	No	No	
ASBESTOS-ST13-4/2/09	030908560-0008	Marriott Hotel, 38th Floor (roof level)	4/2/09	1	3.100	Asbestos	PCME	EMSL	4/3/09	< 0.00080	No	No	
ASBESTOS-ST14-4/2/09	030908560-0009	West Face - South end at corner (scaffolding level)	4/2/09	1	3.060	Asbestos	PCME	EMSL	4/3/09	< 0.00081	No	No	
ASBESTOS-ST15-4/2/09	030908560-0010	South Face - East end at corner (scaffolding level)	4/2/09	1	3.090	Asbestos	PCME	EMSL	4/3/09	< 0.00080	No	No	
ASBESTOS-ST16-4/2/09	030908560-0011	East Face - North end at corner (scaffolding level)	4/2/09	1	3.090	Asbestos	PCME	EMSL	4/3/09	< 0.00080	No	No	
ASBESTOS-ST17-4/2/09	030908560-0012	North Face - West end at corner (scaffolding level)	4/2/09	1	3.130	Asbestos	PCME	EMSL	4/3/09	< 0.00079	No	No	
ASBESTOS-ST1-4/3/09	030908597-0001	Southwest Area (sidewalk bridge level)	4/3/09	1	3.060	Asbestos	PCME	EMSL	4/4/09	< 0.00081	No	No	
ASBESTOS-ST2-4/3/09	030908597-0002	Southeast Area (sidewalk bridge level)	4/3/09	1	3.020	Asbestos	PCME	EMSL	4/4/09	< 0.00082	No	No	
ASBESTOS-ST4-4/3/09	030908597-0003	Northwest Area (street-level)	4/3/09	1	3.080	Asbestos	PCME	EMSL	4/4/09	< 0.00087	No	No	
ASBESTOS-ST5-4/3/09	030908597-0004	Firehouse #10 (roof level)	4/3/09	1	3.050	Asbestos	PCME	EMSL	4/4/09	< 0.00081	No	No	
ASBESTOS-ST10-4/3/09	030908597-0005	North Side Sidewalk Bridge	4/3/09	1	3.040	Asbestos	PCME	EMSL	4/4/09	< 0.00081	No	No	
ASBESTOS-ST11-4/3/09	030908597-0006	90 Trinity Place (roof level)	4/3/09	1	2.950	Asbestos	PCME	EMSL	4/4/09	< 0.00084	No	No	
ASBESTOS-ST12-4/3/09	030908597-0007	110 Greenwich Street (roof level)	4/3/09	1	2.980	Asbestos	PCME	EMSL	4/4/09	< 0.00083	No	No	
ASBESTOS-ST13-4/3/09	030908597-0008	Marriott Hotel, 38th Floor (roof level)	4/3/09	1	3.050	Asbestos	PCME	EMSL	4/4/09	< 0.00081	No	No	
ASBESTOS-ST14-4/3/09	030908597-0009	West Face - South end at corner (scaffolding level)	4/3/09	1	2.940	Asbestos	PCME	EMSL	4/4/09	< 0.00084	No	No	
ASBESTOS-ST15-4/3/09	030908597-0010	South Face - East end at corner (scaffolding level)	4/3/09	1	2.830	Asbestos	PCME	EMSL	4/4/09	< 0.00087	No	No	
ASBESTOS-ST16-4/3/09	030908597-0011	East Face - North end at corner (scaffolding level)	4/3/09	1	2.930	Asbestos	PCME	EMSL	4/4/09	< 0.00084	No	No	
ASBESTOS-ST17-4/3/09	030908597-0012	North Face - West end at corner (scaffolding level)	4/3/09	1	2.880	Asbestos	PCME	EMSL	4/4/09	< 0.00086	No	No	

- Note:
1. The asbestos sample volume at Station 1 (Southwest Area [sidewalk bridge level]) on April 1, 2009 represents approximately 1810 minutes sampled on April 1, 2009 and April 2, 2009 due to a power interruption.
 2. The asbestos sample at Station 1 (Southwest Area [sidewalk bridge level]) on April 2, 2009 was composited with the sample for April 1, 2009. Refer to the sample collected on April 1, 2009.