

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-4/2/08	030809489-0001	Southwest Area (sidewalk bridge level)	4/2/08	1	3.100	Asbestos	PCME	EMSL	4/3/08	< 0.00080	No	No	
ASBESTOS-ST2-4/2/08	030809489-0002	Southeast Area (sidewalk bridge level)	4/2/08	1	3.080	Asbestos	PCME	EMSL	4/3/08	< 0.00080	No	No	
ASBESTOS-ST4-4/2/08	030809489-0003	Northwest Area (street-level)	4/2/08	1	2.940	Asbestos	PCME	EMSL	4/3/08	< 0.00084	No	No	
ASBESTOS-ST5-4/2/08	030809489-0004	Firehouse #10 (roof level)	4/2/08	1	2.850	Asbestos	PCME	EMSL	4/3/08	< 0.00087	No	No	
ASBESTOS-ST10-4/2/08	030809489-0005	North Side Sidewalk Bridge	4/2/08	1	3.060	Asbestos	PCME	EMSL	4/3/08	< 0.00081	No	No	
ASBESTOS-ST11-4/2/08	030809489-0006	90 Trinity Place (roof level)	4/2/08	1	3.010	Asbestos	PCME	EMSL	4/3/08	< 0.00082	No	No	
ASBESTOS-ST12-4/2/08	030809489-0007	110 Greenwich Street (roof level)	4/2/08	1	3.050	Asbestos	PCME	EMSL	4/3/08	< 0.00081	No	No	
ASBESTOS-ST13-4/2/08	030809489-0008	Marriott Hotel, 38th Floor (roof level)	4/2/08	1	2.970	Asbestos	PCME	EMSL	4/3/08	< 0.00083	No	No	
ASBESTOS-ST14-4/2/08	030809489-0009	West Face - South end at corner (scaffolding level)	4/2/08	1	3.030	Asbestos	PCME	EMSL	4/3/08	< 0.00081	No	No	
ASBESTOS-ST15-4/2/08	030809489-0010	South Face - East end at corner (scaffolding level)	4/2/08	1	3.060	Asbestos	PCME	EMSL	4/3/08	< 0.00081	No	No	
ASBESTOS-ST16-4/2/08	030809489-0011	East Face - North end at corner (scaffolding level)	4/2/08	1	3.040	Asbestos	PCME	EMSL	4/3/08	< 0.00081	No	No	
ASBESTOS-ST17-4/2/08	030809489-0012	North Face - West end at corner (scaffolding level)	4/2/08	1	3.080	Asbestos	PCME	EMSL	4/3/08	< 0.00080	No	No	
ASBESTOS-ST1-4/3/08	030809672-0001	Southwest Area (sidewalk bridge level)	4/3/08	1	2.960	Asbestos	PCME	EMSL	4/4/08	< 0.00083	No	No	
ASBESTOS-ST2-4/3/08	030809672-0002	Southeast Area (sidewalk bridge level)	4/3/08	1	3.060	Asbestos	PCME	EMSL	4/4/08	< 0.00081	No	No	
ASBESTOS-ST4-4/3/08	030809672-0003	Northwest Area (street-level)	4/3/08	1	3.040	Asbestos	PCME	EMSL	4/4/08	< 0.00081	No	No	
ASBESTOS-ST5-4/3/08	030809672-0004	Firehouse #10 (roof level)	4/3/08	1	2.960	Asbestos	PCME	EMSL	4/4/08	< 0.00083	No	No	
ASBESTOS-ST10-4/3/08	030809672-0005	North Side Sidewalk Bridge	4/3/08	1	3.230	Asbestos	PCME	EMSL	4/4/08	< 0.00076	No	No	
ASBESTOS-ST11-4/3/08	030809672-0006	90 Trinity Place (roof level)	4/3/08	1	3.020	Asbestos	PCME	EMSL	4/4/08	< 0.00082	No	No	
ASBESTOS-ST12-4/3/08	030809672-0007	110 Greenwich Street (roof level)	4/3/08	1	3.090	Asbestos	PCME	EMSL	4/4/08	< 0.00080	No	No	
ASBESTOS-ST13-4/3/08	030809672-0008	Marriott Hotel, 38th Floor (roof level)	4/3/08	1	3.020	Asbestos	PCME	EMSL	4/4/08	< 0.00082	No	No	
ASBESTOS-ST14-4/3/08	030809672-0009	West Face - South end at corner (scaffolding level)	4/3/08	1	3.010	Asbestos	PCME	EMSL	4/4/08	< 0.00082	No	No	
ASBESTOS-ST15-4/3/08	030809672-0010	South Face - East end at corner (scaffolding level)	4/3/08	1	2.980	Asbestos	PCME	EMSL	4/4/08	< 0.00083	No	No	
ASBESTOS-ST16-4/3/08	030809672-0011	East Face - North end at corner (scaffolding level)	4/3/08	1	3.110	Asbestos	PCME	EMSL	4/4/08	< 0.00079	No	No	
ASBESTOS-ST17-4/3/08	030809672-0012	North Face - West end at corner (scaffolding level)	4/3/08	1	3.050	Asbestos	PCME	EMSL	4/4/08	< 0.00081	No	No	