

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-4/5/08	030809932-0001	Southwest Area (sidewalk bridge level)	4/5/08	1	3.080	Asbestos	PCME	EMSL	4/7/08	< 0.00080	No	No	
ASBESTOS-ST2-4/5/08	030809932-0002	Southeast Area (sidewalk bridge level)	4/5/08	1	3.000	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST4-4/5/08	030809932-0003	Northwest Area (street-level)	4/5/08	1	3.090	Asbestos	PCME	EMSL	4/7/08	< 0.00080	No	No	
ASBESTOS-ST5-4/5/08	030809932-0004	Firehouse #10 (roof level)	4/5/08	1	3.070	Asbestos	PCME	EMSL	4/7/08	< 0.00080	No	No	
ASBESTOS-ST10-4/5/08	030809932-0005	North Side Sidewalk Bridge	4/5/08	1	3.170	Asbestos	PCME	EMSL	4/7/08	< 0.00078	No	No	
ASBESTOS-ST11-4/5/08	030809932-0006	90 Trinity Place (roof level)	4/5/08	1	3.040	Asbestos	PCME	EMSL	4/7/08	< 0.00081	No	No	
ASBESTOS-ST12-4/5/08	030809932-0007	110 Greenwich Street (roof level)	4/5/08	1	3.040	Asbestos	PCME	EMSL	4/7/08	< 0.00081	No	No	
ASBESTOS-ST13-4/5/08	030809932-0008	Marriott Hotel, 38th Floor (roof level)	4/5/08	1	3.010	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST14-4/5/08	030809932-0009	West Face - South end at corner (scaffolding level)	4/5/08	1	3.010	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST15-4/5/08	030809932-0010	South Face - East end at corner (scaffolding level)	4/5/08	1	2.990	Asbestos	PCME	EMSL	4/7/08	< 0.00083	No	No	
ASBESTOS-ST16-4/5/08	030809932-0011	East Face - North end at corner (scaffolding level)	4/5/08	1	3.020	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST17-4/5/08	030809932-0012	North Face - West end at corner (scaffolding level)	4/5/08	1	3.040	Asbestos	PCME	EMSL	4/7/08	< 0.00081	No	No	
ASBESTOS-ST1-4/6/08	030809930-0001	Southwest Area (sidewalk bridge level)	4/6/08	1	3.120	Asbestos	PCME	EMSL	4/7/08	< 0.00086	No	No	
ASBESTOS-ST2-4/6/08	030809930-0002	Southeast Area (sidewalk bridge level)	4/6/08	1	3.110	Asbestos	PCME	EMSL	4/7/08	< 0.00087	No	No	
ASBESTOS-ST4-4/6/08	030809930-0003	Northwest Area (street-level)	4/6/08	1	3.060	Asbestos	PCME	EMSL	4/7/08	< 0.00088	No	No	
ASBESTOS-ST5-4/6/08	030809930-0004	Firehouse #10 (roof level)	4/6/08	1	3.050	Asbestos	PCME	EMSL	4/7/08	< 0.00088	No	No	
ASBESTOS-ST10-4/6/08	030809930-0005	North Side Sidewalk Bridge	4/6/08	1	3.150	Asbestos	PCME	EMSL	4/7/08	< 0.00085	No	No	
ASBESTOS-ST11-4/6/08	030809930-0006	90 Trinity Place (roof level)	4/6/08	1	3.000	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST12-4/6/08	030809930-0007	110 Greenwich Street (roof level)	4/6/08	1	2.990	Asbestos	PCME	EMSL	4/7/08	< 0.00083	No	No	
ASBESTOS-ST13-4/6/08	030809930-0008	Marriott Hotel, 38th Floor (roof level)	4/6/08	1	3.070	Asbestos	PCME	EMSL	4/7/08	< 0.00080	No	No	
ASBESTOS-ST14-4/6/08	030809930-0009	West Face - South end at corner (scaffolding level)	4/6/08	1	3.110	Asbestos	PCME	EMSL	4/7/08	< 0.00087	No	No	
ASBESTOS-ST15-4/6/08	030809930-0010	South Face - East end at corner (scaffolding level)	4/6/08	1	3.010	Asbestos	PCME	EMSL	4/7/08	< 0.00082	No	No	
ASBESTOS-ST16-4/6/08	030809930-0011	East Face - North end at corner (scaffolding level)	4/6/08	1	2.990	Asbestos	PCME	EMSL	4/7/08	< 0.00083	No	No	
ASBESTOS-ST17-4/6/08	030809930-0012	North Face - West end at corner (scaffolding level)	4/6/08	1	3.020	Asbestos	PCME	EMSL	4/7/08	< 0.00089	No	No	
ASBESTOS-ST1-4/7/08	030810057-0001	Southwest Area (sidewalk bridge level)	4/7/08	1	3.000	Asbestos	PCME	EMSL	4/8/08	< 0.00082	No	No	
ASBESTOS-ST2-4/7/08	030810057-0002	Southeast Area (sidewalk bridge level)	4/7/08	1	3.010	Asbestos	PCME	EMSL	4/8/08	< 0.00082	No	No	
ASBESTOS-ST4-4/7/08	030810057-0003	Northwest Area (street-level)	4/7/08	1	3.060	Asbestos	PCME	EMSL	4/8/08	< 0.00081	No	No	
ASBESTOS-ST5-4/7/08	030810057-0004	Firehouse #10 (roof level)	4/7/08	1	3.160	Asbestos	PCME	EMSL	4/8/08	< 0.00078	No	No	
ASBESTOS-ST10-4/7/08	030810057-0005	North Side Sidewalk Bridge	4/7/08	1	2.940	Asbestos	PCME	EMSL	4/8/08	< 0.00084	No	No	
ASBESTOS-ST100-4/7/08	030810057-0013	Station 10 Field Duplicate	4/7/08	1	2.950	Asbestos	PCME	EMSL	4/8/08	< 0.00084	No	No	
ASBESTOS-ST11-4/7/08	030810057-0006	90 Trinity Place (roof level)	4/7/08	1	2.990	Asbestos	PCME	EMSL	4/8/08	< 0.00083	No	No	
ASBESTOS-ST12-4/7/08	030810057-0007	110 Greenwich Street (roof level)	4/7/08	1	2.990	Asbestos	PCME	EMSL	4/8/08	< 0.00083	No	No	
ASBESTOS-ST13-4/7/08	030810057-0008	Marriott Hotel, 38th Floor (roof level)	4/7/08	1	2.560	Asbestos	PCME	EMSL	4/8/08	< 0.00089	No	No	
ASBESTOS-ST14-4/7/08	030810057-0009	West Face - South end at corner (scaffolding level)	4/7/08	1	3.040	Asbestos	PCME	EMSL	4/8/08	< 0.00081	No	No	
ASBESTOS-ST15-4/7/08	030810057-0010	South Face - East end at corner (scaffolding level)	4/7/08	1	3.090	Asbestos	PCME	EMSL	4/8/08	< 0.00080	No	No	
ASBESTOS-ST16-4/7/08	030810057-0011	East Face - North end at corner (scaffolding level)	4/7/08	1	3.010	Asbestos	PCME	EMSL	4/8/08	< 0.00082	No	No	
ASBESTOS-ST17-4/7/08	030810057-0012	North Face - West end at corner (scaffolding level)	4/7/08	1	3.070	Asbestos	PCME	EMSL	4/8/08	< 0.00080	No	No	