

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										NA	Levels	Trigger Levels	
ASBESTOS-ST1-4/8/08	030810219-0001	Southwest Area (sidewalk bridge level)	4/8/08	1	2.970	Asbestos	PCME	EMSL	4/9/08	< 0.00083	No	No	
ASBESTOS-ST2-4/8/08	030810219-0002	Southeast Area (sidewalk bridge level)	4/8/08	1	3.020	Asbestos	PCME	EMSL	4/9/08	< 0.00082	No	No	
ASBESTOS-ST4-4/8/08	030810219-0003	Northwest Area (street-level)	4/8/08	1	3.060	Asbestos	PCME	EMSL	4/9/08	< 0.00081	No	No	
ASBESTOS-ST5-4/8/08	030810219-0004	Firehouse #10 (roof level)	4/8/08	1	3.090	Asbestos	PCME	EMSL	4/9/08	< 0.00080	No	No	
ASBESTOS-ST10-4/8/08	030810219-0005	North Side Sidewalk Bridge	4/8/08	1	2.970	Asbestos	PCME	EMSL	4/9/08	< 0.00083	No	No	
ASBESTOS-ST11-4/8/08	030810219-0006	90 Trinity Place (roof level)	4/8/08	1	3.020	Asbestos	PCME	EMSL	4/9/08	< 0.00082	No	No	
ASBESTOS-ST12-4/8/08	030810219-0007	110 Greenwich Street (roof level)	4/8/08	1	3.070	Asbestos	PCME	EMSL	4/9/08	< 0.00080	No	No	
ASBESTOS-ST13-4/8/08	030810219-0008	Marriott Hotel, 38th Floor (roof level)	4/8/08	1	2.950	Asbestos	PCME	EMSL	4/9/08	< 0.00084	No	No	
ASBESTOS-ST14-4/8/08	030810219-0009	West Face - South end at corner (scaffolding level)	4/8/08	1	3.010	Asbestos	PCME	EMSL	4/9/08	< 0.00082	No	No	
ASBESTOS-ST15-4/8/08	030810219-0010	South Face - East end at corner (scaffolding level)	4/8/08	1	2.990	Asbestos	PCME	EMSL	4/9/08	< 0.00083	No	No	
ASBESTOS-ST16-4/8/08	030810219-0011	East Face - North end at corner (scaffolding level)	4/8/08	1	3.020	Asbestos	PCME	EMSL	4/9/08	< 0.00082	No	No	
ASBESTOS-ST17-4/8/08	030810219-0012	North Face - West end at corner (scaffolding level)	4/8/08	1	3.030	Asbestos	PCME	EMSL	4/9/08	< 0.00081	No	No	
ASBESTOS-ST1-4/9/08	030810388-0001	Southwest Area (sidewalk bridge level)	4/9/08	1	2.970	Asbestos	PCME	EMSL	4/10/08	< 0.00083	No	No	
ASBESTOS-ST2-4/9/08	030810388-0002	Southeast Area (sidewalk bridge level)	4/9/08	1	3.090	Asbestos	PCME	EMSL	4/10/08	< 0.00087	No	No	
ASBESTOS-ST4-4/9/08	030810388-0003	Northwest Area (street-level)	4/9/08	1	3.060	Asbestos	PCME	EMSL	4/10/08	< 0.00088	No	No	
ASBESTOS-ST5-4/9/08	030810388-0004	Firehouse #10 (roof level)	4/9/08	1	3.340	Asbestos	PCME	EMSL	4/10/08	< 0.00081	No	No	
ASBESTOS-ST10-4/9/08	030810388-0005	North Side Sidewalk Bridge	4/9/08	1	3.020	Asbestos	PCME	EMSL	4/10/08	< 0.00082	No	No	
ASBESTOS-ST11-4/9/08	030810388-0006	90 Trinity Place (roof level)	4/9/08	1	3.080	Asbestos	PCME	EMSL	4/10/08	< 0.00087	No	No	
ASBESTOS-ST12-4/9/08	030810388-0007	110 Greenwich Street (roof level)	4/9/08	1	3.040	Asbestos	PCME	EMSL	4/10/08	< 0.00089	No	No	
ASBESTOS-ST13-4/9/08	030810388-0008	Marriott Hotel, 38th Floor (roof level)	4/9/08	1	3.060	Asbestos	PCME	EMSL	4/10/08	< 0.00088	No	No	
ASBESTOS-ST14-4/9/08	030810388-0009	West Face - South end at corner (scaffolding level)	4/9/08	1	3.040	Asbestos	PCME	EMSL	4/10/08	< 0.00089	No	No	
ASBESTOS-ST15-4/9/08	030810388-0010	South Face - East end at corner (scaffolding level)	4/9/08	1	3.000	Asbestos	PCME	EMSL	4/10/08	< 0.00082	No	No	
ASBESTOS-ST16-4/9/08	030810388-0011	East Face - North end at corner (scaffolding level)	4/9/08	1	3.010	Asbestos	PCME	EMSL	4/10/08	< 0.00082	No	No	
ASBESTOS-ST17-4/9/08	030810388-0012	North Face - West end at corner (scaffolding level)	4/9/08	1	3.080	Asbestos	PCME	EMSL	4/10/08	< 0.00087	No	No	
ASBESTOS-ST1-4/10/08	030810507-0001	Southwest Area (sidewalk bridge level)	4/10/08	1	3.310	Asbestos	PCME	EMSL	4/11/08	< 0.00089	No	No	
ASBESTOS-ST2-4/10/08	030810507-0002	Southeast Area (sidewalk bridge level)	4/10/08	1	3.140	Asbestos	PCME	EMSL	4/11/08	< 0.00086	No	No	
ASBESTOS-ST4-4/10/08	030810507-0003	Northwest Area (street-level)	4/10/08	1	3.090	Asbestos	PCME	EMSL	4/11/08	< 0.00087	No	No	
ASBESTOS-ST5-4/10/08	030810507-0004	Firehouse #10 (roof level)	4/10/08	1	3.090	Asbestos	PCME	EMSL	4/11/08	< 0.00087	No	No	
ASBESTOS-ST10-4/10/08	030810507-0005	North Side Sidewalk Bridge	4/10/08	1	3.110	Asbestos	PCME	EMSL	4/11/08	< 0.00087	No	No	
ASBESTOS-ST11-4/10/08	030810507-0006	90 Trinity Place (roof level)	4/10/08	1	3.060	Asbestos	PCME	EMSL	4/11/08	< 0.00088	No	No	
ASBESTOS-ST12-4/10/08	030810507-0007	110 Greenwich Street (roof level)	4/10/08	1	3.060	Asbestos	PCME	EMSL	4/11/08	< 0.00088	No	No	
ASBESTOS-ST13-4/10/08	030810507-0008	Marriott Hotel, 38th Floor (roof level)	4/10/08	1	3.020	Asbestos	PCME	EMSL	4/11/08	< 0.00089	No	No	
ASBESTOS-ST14-4/10/08	030810507-0009	West Face - South end at corner (scaffolding level)	4/10/08	1	3.030	Asbestos	PCME	EMSL	4/11/08	< 0.00089	No	No	
ASBESTOS-ST15-4/10/08	030810507-0010	South Face - East end at corner (scaffolding level)	4/10/08	1	3.110	Asbestos	PCME	EMSL	4/11/08	< 0.00087	No	No	
ASBESTOS-ST16-4/10/08	030810507-0011	East Face - North end at corner (scaffolding level)	4/10/08	1	3.090	Asbestos	PCME	EMSL	4/11/08	< 0.00087	No	No	
ASBESTOS-ST17-4/10/08	030810507-0012	North Face - West end at corner (scaffolding level)	4/10/08	1	3.190	Asbestos	PCME	EMSL	4/11/08	< 0.00084	No	No	
ASBESTOS-ST1-4/11/08	030810650-0001	Southwest Area (sidewalk bridge level)	4/11/08	1	3.230	Asbestos	PCME	EMSL	4/12/08	< 0.00076	No	No	
ASBESTOS-ST2-4/11/08	030810650-0002	Southeast Area (sidewalk bridge level)	4/11/08	1	3.260	Asbestos	PCME	EMSL	4/12/08	< 0.00076	No	No	
ASBESTOS-ST4-4/11/08	030810650-0003	Northwest Area (street-level)	4/11/08	1	3.040	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST5-4/11/08	030810650-0004	Firehouse #10 (roof level)	4/11/08	1	3.090	Asbestos	PCME	EMSL	4/12/08	< 0.00080	No	No	
ASBESTOS-ST10-4/11/08	030810650-0005	North Side Sidewalk Bridge	4/11/08	1	3.060	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST11-4/11/08	030810650-0006	90 Trinity Place (roof level)	4/11/08	1	3.040	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST12-4/11/08	030810650-0007	110 Greenwich Street (roof level)	4/11/08	1	3.040	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST13-4/11/08	030810650-0008	Marriott Hotel, 38th Floor (roof level)	4/11/08	1	3.000	Asbestos	PCME	EMSL	4/12/08	< 0.00082	No	No	
ASBESTOS-ST14-4/11/08	030810650-0009	West Face - South end at corner (scaffolding level)	4/11/08	1	3.070	Asbestos	PCME	EMSL	4/12/08	< 0.00080	No	No	
ASBESTOS-ST15-4/11/08	030810650-0010	South Face - East end at corner (scaffolding level)	4/11/08	1	3.040	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST16-4/11/08	030810650-0011	East Face - North end at corner (scaffolding level)	4/11/08	1	3.010	Asbestos	PCME	EMSL	4/12/08	< 0.00082	No	No	
ASBESTOS-ST17-4/11/08	030810650-0012	North Face - West end at corner (scaffolding level)	4/11/08	1	3.050	Asbestos	PCME	EMSL	4/12/08	< 0.00081	No	No	
ASBESTOS-ST1-4/12/08	030810813-0001	Southwest Area (sidewalk bridge level)	4/12/08	1	3.030	Asbestos	PCME	EMSL	4/14/08	< 0.00081	No	No	
ASBESTOS-ST2-4/12/08	030810813-0002	Southeast Area (sidewalk bridge level)	4/12/08	1	2.990	Asbestos	PCME	EMSL	4/14/08	< 0.00083	No	No	
ASBESTOS-ST4-4/12/08	030810813-0003	Northwest Area (street-level)	4/12/08	1	3.030	Asbestos	PCME	EMSL	4/14/08	< 0.00081	No	No	
ASBESTOS-ST5-4/12/08	030810813-0004	Firehouse #10 (roof level)	4/12/08	1	3.050	Asbestos	PCME	EMSL	4/14/08	< 0.00081	No	No	
ASBESTOS-ST10-4/12/08	030810813-0005	North Side Sidewalk Bridge	4/12/08	1	3.150	Asbestos	PCME	EMSL	4/14/08	< 0.00078	No	No	
ASBESTOS-ST11-4/12/08	030810813-0006	90 Trinity Place (roof level)	4/12/08	1	3.000	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST12-4/12/08	030810813-0007	110 Greenwich Street (roof level)	4/12/08	1	3.000	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST13-4/12/08	030810813-0008	Marriott Hotel, 38th Floor (roof level)	4/12/08	1	3.020	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST14-4/12/08	030810813-0009	West Face - South end at corner (scaffolding level)	4/12/08	1	3.010	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST15-4/12/08	030810813-0010	South Face - East end at corner (scaffolding level)	4/12/08	1	3.020	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST16-4/12/08	030810813-0011	East Face - North end at corner (scaffolding level)	4/12/08	1	3.070	Asbestos	PCME	EMSL	4/14/08	< 0.00080	No	No	
ASBESTOS-ST17-4/12/08	030810813-0012	North Face - West end at corner (scaffolding level)	4/12/08	1	3.030	Asbestos	PCME	EMSL	4/14/08	< 0.00081	No	No	
ASBESTOS-ST1-4/13/08	030810823-0001	Southwest Area (sidewalk bridge level)	4/13/08	1	2.840	Asbestos	PCME	EMSL	4/14/08	< 0.00087	No	No	
ASBESTOS-ST2-4/13/08	030810823-0002	Southeast Area (sidewalk bridge level)	4/13/08	1	2.770	Asbestos	PCME	EMSL	4/14/08	< 0.00089	No	No	
ASBESTOS-ST4-4/13/08	030810823-0003	Northwest Area (street-level)	4/13/08	1	2.980	Asbestos	PCME	EMSL	4/14/08	< 0.00083	No	No	
ASBESTOS-ST5-4/13/08	030810823-0004	Firehouse #10 (roof level)	4/13/08	1	3.010	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST10-4/13/08	030810823-0005	North Side Sidewalk Bridge	4/13/08	1	3.140	Asbestos	PCME	EMSL	4/14/08	< 0.00079	No	No	
ASBESTOS-ST11-4/13/08	030810823-0006	90 Trinity Place (roof level)	4/13/08	1	3.000	Asbestos	PCME	EMSL	4/14/08	< 0.00082	No	No	
ASBESTOS-ST12-4/13/08	030810823-0007	110 Greenwich Street (roof level)	4/13/08	1	2.990	Asbestos	PCME	EMSL	4/14/08	< 0.00083	No	No	
ASBESTOS-ST13-4/13/08	030810823-0008	Marriott Hotel, 38th Floor (roof level)	4/13/08	1	3.040	Asbestos	PCME	EMSL	4/14/08	< 0.00081	No	No	
ASBESTOS-ST14-4/13/08	030810823-0009	West Face - South end at corner (scaffolding level)	4/13/08	1	2.940	Asbestos	PCME	EMSL	4/14/08	< 0.00084	No	No	
ASBESTOS-ST15-4/13/08	030810823-0010	South Face - East end at corner (scaffolding level)	4/13/08	1	2.980	Asbestos	PCME	EMSL	4/14/08	< 0.00083	No	No	
ASBESTOS-ST16-4/13/08	030810823-0011	East Face - North end at corner (scaffolding level)	4/13/08	1	2.990	Asbestos	PCME	EMSL	4/14/08	< 0.00083	No	No	
ASBESTOS-ST17-4/13/08	030810823-0012	North Face - West end at corner (scaffolding level)	4/13/08	1	3.120	Asbestos	PCME	EMSL	4/14/08	< 0.00079	No	No	
ASBESTOS-ST1-4/14/08	030810993-0001	Southwest Area (sidewalk bridge level)	4/14/08	1	3.190	Asbestos	PCME	EMSL	4/15/08	< 0.00084	No	No	
ASBESTOS-ST2-4/14/08	030810993-0002	Southeast Area (sidewalk bridge level)	4/14/08	1	2.970	Asbestos	PCME	EMSL	4/15/08	< 0.00083	No	No	
ASBESTOS-ST4-4/14/08	030810993-0003	Northwest Area (street-level)	4/14/08	1	2.950								