

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST2-4/13/07	030711556-0001	Southeast Area (sidewalk bridge level)	4/13/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST4-4/13/07	030711556-0002	Northwest Area (street-level)	4/13/07	1	3.050	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST5-4/13/07	030711556-0003	Firehouse #10 (roof level)	4/13/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST10-4/13/07	030711556-0004	North Side Sidewalk Bridge	4/13/07	1	3.090	Asbestos	PCME	EMSL	4/16/07	< 0.00080	No	No	
ASBESTOS-ST11-4/13/07	030711556-0005	90 Trinity Place (roof level)	4/13/07	1	3.030	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST12-4/13/07	030711556-0006	110 Greenwich Street (roof level)	4/13/07	1	3.030	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST13-4/13/07	030711556-0007	Marriott Hotel, 38th Floor (roof level)	4/13/07	1	3.020	Asbestos	PCME	EMSL	4/16/07	< 0.00082	No	No	
ASBESTOS-ST1-4/14/07	030711537-0001	Southwest Area (sidewalk bridge level)	4/14/07	1	3.030	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST2-4/14/07	030711537-0002	Southeast Area (sidewalk bridge level)	4/14/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST4-4/14/07	030711537-0003	Northwest Area (street-level)	4/14/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST5-4/14/07	030711537-0004	Firehouse #10 (roof level)	4/14/07	1	3.010	Asbestos	PCME	EMSL	4/16/07	< 0.00082	No	No	
ASBESTOS-ST10-4/14/07	030711537-0005	North Side Sidewalk Bridge	4/14/07	1	3.030	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST11-4/14/07	030711537-0006	90 Trinity Place (roof level)	4/14/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST12-4/14/07	030711537-0007	110 Greenwich Street (roof level)	4/14/07	1	3.020	Asbestos	PCME	EMSL	4/16/07	< 0.00082	No	No	
ASBESTOS-ST13-4/14/07	030711537-0008	Marriott Hotel, 38th Floor (roof level)	4/14/07	1	3.040	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST1-4/15/07	030711557-0001	Southwest Area (sidewalk bridge level)	4/15/07	1	2.990	Asbestos	PCME	EMSL	4/16/07	< 0.00083	No	No	
ASBESTOS-ST2-4/15/07	030711557-0002	Southeast Area (sidewalk bridge level)	4/15/07	1	3.190	Asbestos	PCME	EMSL	4/16/07	< 0.00077	No	No	
ASBESTOS-ST4-4/15/07	030711557-0003	Northwest Area (street-level)	4/15/07	1	3.010	Asbestos	PCME	EMSL	4/16/07	< 0.00082	No	No	
ASBESTOS-ST5-4/15/07	030711557-0004	Firehouse #10 (roof level)	4/15/07	1	3.010	Asbestos	PCME	EMSL	4/16/07	< 0.00082	No	No	
ASBESTOS-ST10-4/15/07	030711557-0005	North Side Sidewalk Bridge	4/15/07	1	2.940	Asbestos	PCME	EMSL	4/16/07	< 0.00084	No	No	
ASBESTOS-ST11-4/15/07	030711557-0006	90 Trinity Place (roof level)	4/15/07	1	3.050	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST12-4/15/07	030711557-0007	110 Greenwich Street (roof level)	4/15/07	1	3.030	Asbestos	PCME	EMSL	4/16/07	< 0.00081	No	No	
ASBESTOS-ST1-4/16/07	030711692-0001	Southwest Area (sidewalk bridge level)	4/16/07	1	2.940	Asbestos	PCME	EMSL	4/17/07	< 0.00084	No	No	
ASBESTOS-ST2-4/16/07	030711692-0002	Southeast Area (sidewalk bridge level)	4/16/07	1	2.990	Asbestos	PCME	EMSL	4/17/07	< 0.00083	No	No	
ASBESTOS-ST4-4/16/07	030711692-0003	Northwest Area (street-level)	4/16/07	1	3.280	Asbestos	PCME	EMSL	4/17/07	< 0.00082	No	No	
ASBESTOS-ST5-4/16/07	030711692-0004	Firehouse #10 (roof level)	4/16/07	1	3.040	Asbestos	PCME	EMSL	4/17/07	< 0.00081	No	No	
ASBESTOS-ST10-4/16/07	030711692-0005	North Side Sidewalk Bridge	4/16/07	1	3.070	Asbestos	PCME	EMSL	4/17/07	< 0.00080	No	No	
ASBESTOS-ST11-4/16/07	030711692-0006	90 Trinity Place (roof level)	4/16/07	1	2.970	Asbestos	PCME	EMSL	4/17/07	< 0.00083	No	No	
ASBESTOS-ST12-4/16/07	030711692-0007	110 Greenwich Street (roof level)	4/16/07	1	3.060	Asbestos	PCME	EMSL	4/17/07	< 0.00081	No	No	
ASBESTOS-ST13-4/16/07	030711692-0008	Marriott Hotel, 38th Floor (roof level)	4/16/07	1	3.020	Asbestos	PCME	EMSL	4/17/07	< 0.00082	No	No	

Note:

1. Asbestos sample at Station 1 (Southwest Area [sidewalk bridge level]) on April 13, 2007 was not available due to a timer failure.
2. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on April 15, 2007 was not analyzed due to receipt of a wet filter.
3. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on April 13, 14, 15 and 16, 2007 were not available for analysis. Heavy rain and gusting winds made the scaffolding stations inaccessible.