

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										<b>Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-4/16/08	030811295-0001	Southwest Area (sidewalk bridge level)	4/16/08	1	3.170	Asbestos	PCME	EMSL	4/17/08	< 0.00078	No	No	
ASBESTOS-ST2-4/16/08	030811295-0002	Southeast Area (sidewalk bridge level)	4/16/08	1	3.090	Asbestos	PCME	EMSL	4/17/08	< 0.00080	No	No	
ASBESTOS-ST4-4/16/08	030811295-0003	Northwest Area (street-level)	4/16/08	1	3.210	Asbestos	PCME	EMSL	4/17/08	< 0.00077	No	No	
ASBESTOS-ST5-4/16/08	030811295-0004	Firehouse #10 (roof level)	4/16/08	1	2.950	Asbestos	PCME	EMSL	4/17/08	< 0.00084	No	No	
ASBESTOS-ST10-4/16/08	030811295-0005	North Side Sidewalk Bridge	4/16/08	1	3.010	Asbestos	PCME	EMSL	4/17/08	< 0.00082	No	No	
ASBESTOS-ST11-4/16/08	030811295-0006	90 Trinity Place (roof level)	4/16/08	1	3.020	Asbestos	PCME	EMSL	4/17/08	< 0.00082	No	No	
ASBESTOS-ST12-4/16/08	030811295-0007	110 Greenwich Street (roof level)	4/16/08	1	3.060	Asbestos	PCME	EMSL	4/17/08	< 0.00081	No	No	
ASBESTOS-ST13-4/16/08	030811295-0008	Marriott Hotel, 38th Floor (roof level)	4/16/08	1	3.010	Asbestos	PCME	EMSL	4/17/08	< 0.00082	No	No	
ASBESTOS-ST14-4/16/08	030811295-0009	West Face - South end at corner (scaffolding level)	4/16/08	1	3.000	Asbestos	PCME	EMSL	4/17/08	< 0.00082	No	No	
ASBESTOS-ST15-4/16/08	030811295-0010	South Face - East end at corner (scaffolding level)	4/16/08	1	3.040	Asbestos	PCME	EMSL	4/17/08	< 0.00081	No	No	
ASBESTOS-ST16-4/16/08	030811295-0011	East Face - North end at corner (scaffolding level)	4/16/08	1	3.090	Asbestos	PCME	EMSL	4/17/08	< 0.00080	No	No	
ASBESTOS-ST17-4/16/08	030811295-0012	North Face - West end at corner (scaffolding level)	4/16/08	1	3.090	Asbestos	PCME	EMSL	4/17/08	< 0.00080	No	No	
ASBESTOS-ST1-4/17/08	030811430-0001	Southwest Area (sidewalk bridge level)	4/17/08	1	3.230	Asbestos	PCME	EMSL	4/18/08	< 0.00076	No	No	
ASBESTOS-ST2-4/17/08	030811430-0002	Southeast Area (sidewalk bridge level)	4/17/08	1	3.080	Asbestos	PCME	EMSL	4/18/08	< 0.00080	No	No	
ASBESTOS-ST4-4/17/08	030811430-0003	Northwest Area (street-level)	4/17/08	1	3.080	Asbestos	PCME	EMSL	4/18/08	< 0.00080	No	No	
ASBESTOS-ST5-4/17/08	030811430-0004	Firehouse #10 (roof level)	4/17/08	1	3.020	Asbestos	PCME	EMSL	4/18/08	< 0.00082	No	No	
ASBESTOS-ST10-4/17/08	030811430-0005	North Side Sidewalk Bridge	4/17/08	1	3.150	Asbestos	PCME	EMSL	4/18/08	< 0.00078	No	No	
ASBESTOS-ST11-4/17/08	030811430-0006	90 Trinity Place (roof level)	4/17/08	1	3.160	Asbestos	PCME	EMSL	4/18/08	< 0.00078	No	No	
ASBESTOS-ST12-4/17/08	030811430-0007	110 Greenwich Street (roof level)	4/17/08	1	2.990	Asbestos	PCME	EMSL	4/18/08	< 0.00083	No	No	
ASBESTOS-ST13-4/17/08	030811430-0008	Marriott Hotel, 38th Floor (roof level)	4/17/08	1	3.070	Asbestos	PCME	EMSL	4/18/08	< 0.00080	No	No	
ASBESTOS-ST14-4/17/08	030811430-0009	West Face - South end at corner (scaffolding level)	4/17/08	1	3.180	Asbestos	PCME	EMSL	4/18/08	< 0.00078	No	No	
ASBESTOS-ST15-4/17/08	030811430-0010	South Face - East end at corner (scaffolding level)	4/17/08	1	3.110	Asbestos	PCME	EMSL	4/18/08	< 0.00079	No	No	
ASBESTOS-ST16-4/17/08	030811430-0011	East Face - North end at corner (scaffolding level)	4/17/08	1	3.180	Asbestos	PCME	EMSL	4/18/08	< 0.00078	No	No	
ASBESTOS-ST17-4/17/08	030811430-0012	North Face - West end at corner (scaffolding level)	4/17/08	1	3.030	Asbestos	PCME	EMSL	4/18/08	< 0.00081	No	No	