

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-4/18/06	030611794-0001	Southwest Area (sidewalk bridge level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST2-4/18/06	030611794-0002	Southeast Area (sidewalk bridge level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST4-4/18/06	030611794-0003	Northwest Area (street-level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST5-4/18/06	030611794-0004	Firehouse #10 (roof level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST10-4/18/06	030611794-0005	North Side Sidewalk Bridge	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST11-4/18/06	030611794-0006	90 Trinity Place (roof level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST12-4/18/06	030611794-0007	110 Greenwich Street (roof level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST13-4/18/06	030611794-0008	Marriott Hotel, 38th Floor (roof level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST14-4/18/06	030611794-0009	West Face - South end at corner (scaffolding level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST15-4/18/06	030611794-0010	South Face - East end at corner (scaffolding level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST17-4/18/06	030611794-0012	North Face - West end at corner (scaffolding level)	4/18/06	1	3.000	Asbestos	PCME	EMSL	4/19/06	< 0.00082	No	No	
ASBESTOS-ST1-4/19/06	030611947-0001	Southwest Area (sidewalk bridge level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST2-4/19/06	030611947-0002	Southeast Area (sidewalk bridge level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST4-4/19/06	030611947-0003	Northwest Area (street-level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST5-4/19/06	030611947-0004	Firehouse #10 (roof level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST10-4/19/06	030611947-0005	North Side Sidewalk Bridge	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST11-4/19/06	030611947-0006	90 Trinity Place (roof level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST12-4/19/06	030611947-0007	110 Greenwich Street (roof level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST13-4/19/06	030611947-0008	Marriott Hotel, 38th Floor (roof level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST14-4/19/06	030611947-0009	West Face - South end at corner (scaffolding level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST15-4/19/06	030611947-0010	South Face - East end at corner (scaffolding level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST16-4/19/06	030611947-0011	East Face - North end at corner (scaffolding level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	
ASBESTOS-ST17-4/19/06	030611947-0012	North Face - West end at corner (scaffolding level)	4/19/06	1	3.000	Asbestos	PCME	EMSL	4/20/06	< 0.00082	No	No	

Note:

1. Asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on April 18, 2006 was not available for analysis on account of filter damage.