

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										0.0009	Air Quality Levels	Site Specific Trigger Levels		
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-4/18/09	030910026-0001	Southwest Area (sidewalk bridge level)	4/18/09	1	3.060	Asbestos	PCME	EMSL	4/20/09	< 0.00081	No	No		
ASBESTOS-ST2-4/18/09	030910026-0002	Southeast Area (sidewalk bridge level)	4/18/09	1	2.980	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST4-4/18/09	030910026-0003	Northwest Area (street-level)	4/18/09	1	3.100	Asbestos	PCME	EMSL	4/20/09	< 0.00080	No	No		
ASBESTOS-ST5-4/18/09	030910026-0004	Firehouse #10 (roof level)	4/18/09	1	3.010	Asbestos	PCME	EMSL	4/20/09	< 0.00082	No	No		
ASBESTOS-ST10-4/18/09	030910026-0005	North Side Sidewalk Bridge	4/18/09	1	3.010	Asbestos	PCME	EMSL	4/20/09	< 0.00082	No	No		
ASBESTOS-ST11-4/18/09	030910026-0006	90 Trinity Place (roof level)	4/18/09	1	2.980	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST12-4/18/09	030910026-0007	110 Greenwich Street (roof level)	4/18/09	1	2.990	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST13-4/18/09	030910026-0008	Marriott Hotel, 38th Floor (roof level)	4/18/09	1	3.090	Asbestos	PCME	EMSL	4/20/09	< 0.00080	No	No		
ASBESTOS-ST14-4/18/09	030910026-0009	West Face - South end at corner (scaffolding level)	4/18/09	1	3.080	Asbestos	PCME	EMSL	4/20/09	< 0.00080	No	No		
ASBESTOS-ST15-4/18/09	030910026-0010	South Face - East end at corner (scaffolding level)	4/18/09	1	3.050	Asbestos	PCME	EMSL	4/20/09	< 0.00081	No	No		
ASBESTOS-ST16-4/18/09	030910026-0011	East Face - North end at corner (scaffolding level)	4/18/09	1	2.960	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST17-4/18/09	030910026-0012	North Face - West end at corner (scaffolding level)	4/18/09	1	3.050	Asbestos	PCME	EMSL	4/20/09	< 0.00081	No	No		
ASBESTOS-ST1-4/19/09	030910025-0001	Southwest Area (sidewalk bridge level)	4/19/09	1	3.150	Asbestos	PCME	EMSL	4/20/09	< 0.00078	No	No		
ASBESTOS-ST2-4/19/09	030910025-0002	Southeast Area (sidewalk bridge level)	4/19/09	1	3.110	Asbestos	PCME	EMSL	4/20/09	< 0.00079	No	No		
ASBESTOS-ST4-4/19/09	030910025-0003	Northwest Area (street-level)	4/19/09	1	2.970	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST5-4/19/09	030910025-0004	Firehouse #10 (roof level)	4/19/09	1	3.090	Asbestos	PCME	EMSL	4/20/09	< 0.00080	No	No		
ASBESTOS-ST10-4/19/09	030910025-0005	North Side Sidewalk Bridge	4/19/09	1	3.030	Asbestos	PCME	EMSL	4/20/09	< 0.00081	No	No		
ASBESTOS-ST11-4/19/09	030910025-0006	90 Trinity Place (roof level)	4/19/09	1	2.990	Asbestos	PCME	EMSL	4/20/09	< 0.00083	No	No		
ASBESTOS-ST12-4/19/09	030910025-0007	110 Greenwich Street (roof level)	4/19/09	1	3.000	Asbestos	PCME	EMSL	4/20/09	< 0.00082	No	No		
ASBESTOS-ST13-4/19/09	030910025-0008	Marriott Hotel, 38th Floor (roof level)	4/19/09	1	3.060	Asbestos	PCME	EMSL	4/20/09	< 0.00081	No	No		
ASBESTOS-ST14-4/19/09	030910025-0009	West Face - South end at corner (scaffolding level)	4/19/09	1	3.170	Asbestos	PCME	EMSL	4/20/09	< 0.00078	No	No		
ASBESTOS-ST15-4/19/09	030910025-0010	South Face - East end at corner (scaffolding level)	4/19/09	1	3.150	Asbestos	PCME	EMSL	4/20/09	< 0.00078	No	No		
ASBESTOS-ST16-4/19/09	030910025-0011	East Face - North end at corner (scaffolding level)	4/19/09	1	3.110	Asbestos	PCME	EMSL	4/20/09	< 0.00079	No	No		
ASBESTOS-ST17-4/19/09	030910025-0012	North Face - West end at corner (scaffolding level)	4/19/09	1	3.160	Asbestos	PCME	EMSL	4/20/09	< 0.00078	No	No		