

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-4/27/07	030713414-0001	Southwest Area (sidewalk bridge level)	4/27/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST2-4/27/07	030713414-0002	Southeast Area (sidewalk bridge level)	4/27/07	1	3.040	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST4-4/27/07	030713414-0003	Northwest Area (street-level)	4/27/07	1	3.100	Asbestos	PCME	EMSL	4/30/07	< 0.00087	No	No	
ASBESTOS-ST5-4/27/07	030713414-0004	Firehouse #10 (roof level)	4/27/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST10-4/27/07	030713414-0005	North Side Sidewalk Bridge	4/27/07	1	2.960	Asbestos	PCME	EMSL	4/30/07	< 0.00083	No	No	
ASBESTOS-ST100-4/27/07	030713414-0013	Station 10 Field Duplicate	4/27/07	1	3.180	Asbestos	PCME	EMSL	4/30/07	< 0.00085	No	No	
ASBESTOS-ST11-4/27/07	030713414-0006	90 Trinity Place (roof level)	4/27/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST12-4/27/07	030713414-0007	110 Greenwich Street (roof level)	4/27/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST13-4/27/07	030713414-0008	Marriott Hotel, 38th Floor (roof level)	4/27/07	1	2.990	Asbestos	PCME	EMSL	4/30/07	< 0.00083	No	No	
ASBESTOS-ST14-4/27/07	030713414-0009	West Face - South end at corner (scaffolding level)	4/27/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST15-4/27/07	030713414-0010	South Face - East end at corner (scaffolding level)	4/27/07	1	2.950	Asbestos	PCME	EMSL	4/30/07	< 0.00084	No	No	
ASBESTOS-ST16-4/27/07	030713414-0011	East Face - North end at corner (scaffolding level)	4/27/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST17-4/27/07	030713414-0012	North Face - West end at corner (scaffolding level)	4/27/07	1	3.040	Asbestos	PCME	EMSL	4/30/07	< 0.00089	No	No	
ASBESTOS-ST1-4/28/07	030713407-0001	Southwest Area (sidewalk bridge level)	4/28/07	1	2.990	Asbestos	PCME	EMSL	4/30/07	< 0.00076	No	No	
ASBESTOS-ST2-4/28/07	030713407-0002	Southeast Area (sidewalk bridge level)	4/28/07	1	2.990	Asbestos	PCME	EMSL	4/30/07	< 0.00076	No	No	
ASBESTOS-ST4-4/28/07	030713407-0003	Northwest Area (street-level)	4/28/07	1	3.120	Asbestos	PCME	EMSL	4/30/07	< 0.00068	No	No	
ASBESTOS-ST5-4/28/07	030713407-0004	Firehouse #10 (roof level)	4/28/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00082	No	No	
ASBESTOS-ST10-4/28/07	030713407-0005	North Side Sidewalk Bridge	4/28/07	1	3.120	Asbestos	PCME	EMSL	4/30/07	< 0.00079	No	No	
ASBESTOS-ST11-4/28/07	030713407-0006	90 Trinity Place (roof level)	4/28/07	1	3.040	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST12-4/28/07	030713407-0007	110 Greenwich Street (roof level)	4/28/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00070	No	No	
ASBESTOS-ST13-4/28/07	030713407-0008	Marriott Hotel, 38th Floor (roof level)	4/28/07	1	2.990	Asbestos	PCME	EMSL	4/30/07	< 0.00076	No	No	
ASBESTOS-ST14-4/28/07	030713407-0009	West Face - South end at corner (scaffolding level)	4/28/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00082	No	No	
ASBESTOS-ST15-4/28/07	030713407-0010	South Face - East end at corner (scaffolding level)	4/28/07	1	2.970	Asbestos	PCME	EMSL	4/30/07	< 0.00077	No	No	
ASBESTOS-ST16-4/28/07	030713407-0011	East Face - North end at corner (scaffolding level)	4/28/07	1	3.040	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST17-4/28/07	030713407-0012	North Face - West end at corner (scaffolding level)	4/28/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00082	No	No	
ASBESTOS-ST1-4/29/07	030713405-0001	Southwest Area (sidewalk bridge level)	4/29/07	1	3.060	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST2-4/29/07	030713405-0002	Southeast Area (sidewalk bridge level)	4/29/07	1	3.060	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST4-4/29/07	030713405-0003	Northwest Area (street-level)	4/29/07	1	2.840	Asbestos	PCME	EMSL	4/30/07	< 0.00087	No	No	
ASBESTOS-ST5-4/29/07	030713405-0004	Firehouse #10 (roof level)	4/29/07	1	3.030	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST10-4/29/07	030713405-0005	North Side Sidewalk Bridge	4/29/07	1	3.050	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST11-4/29/07	030713405-0006	90 Trinity Place (roof level)	4/29/07	1	3.050	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST12-4/29/07	030713405-0007	110 Greenwich Street (roof level)	4/29/07	1	3.090	Asbestos	PCME	EMSL	4/30/07	< 0.00080	No	No	
ASBESTOS-ST13-4/29/07	030713405-0008	Marriott Hotel, 38th Floor (roof level)	4/29/07	1	3.010	Asbestos	PCME	EMSL	4/30/07	< 0.00082	No	No	
ASBESTOS-ST14-4/29/07	030713405-0009	West Face - South end at corner (scaffolding level)	4/29/07	1	3.070	Asbestos	PCME	EMSL	4/30/07	< 0.00080	No	No	
ASBESTOS-ST15-4/29/07	030713405-0010	South Face - East end at corner (scaffolding level)	4/29/07	1	3.020	Asbestos	PCME	EMSL	4/30/07	< 0.00082	No	No	
ASBESTOS-ST16-4/29/07	030713405-0011	East Face - North end at corner (scaffolding level)	4/29/07	1	3.040	Asbestos	PCME	EMSL	4/30/07	< 0.00081	No	No	
ASBESTOS-ST17-4/29/07	030713405-0012	North Face - West end at corner (scaffolding level)	4/29/07	1	3.090	Asbestos	PCME	EMSL	4/30/07	< 0.00080	No	No	