

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-5/1/06	030613199-0001	Southwest Area (sidewalk bridge level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST2-5/1/06	030613199-0002	Southeast Area (sidewalk bridge level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST4-5/1/06	030613199-0003	Northwest Area (street-level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST5-5/1/06	030613199-0004	Firehouse #10 (roof level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST10-5/1/06	030613199-0005	North Side Sidewalk Bridge	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST11-5/1/06	030613199-0006	90 Trinity Place (roof level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST12-5/1/06	030613199-0007	110 Greenwich Street (roof level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST13-5/1/06	030613199-0008	Marriott Hotel, 38th Floor (roof level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST14-5/1/06	030613199-0009	West Face - South end at corner (scaffolding level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST15-5/1/06	030613199-0010	South Face - East end at corner (scaffolding level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST16-5/1/06	030613199-0011	East Face - North end at corner (scaffolding level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST17-5/1/06	030613199-0012	North Face - West end at corner (scaffolding level)	5/1/06	1	3.000	Asbestos	PCME	EMSL	5/2/06	< 0.00082	No	No	
ASBESTOS-ST1-5/2/06	030613374-0001	Southwest Area (sidewalk bridge level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST2-5/2/06	030613374-0002	Southeast Area (sidewalk bridge level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST4-5/2/06	030613374-0003	Northwest Area (street-level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST5-5/2/06	030613374-0004	Firehouse #10 (roof level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST10-5/2/06	030613374-0005	North Side Sidewalk Bridge	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST11-5/2/06	030613374-0006	90 Trinity Place (roof level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST12-5/2/06	030613374-0007	110 Greenwich Street (roof level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST13-5/2/06	030613374-0008	Marriott Hotel, 38th Floor (roof level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST14-5/2/06	030613374-0009	West Face - South end at corner (scaffolding level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST15-5/2/06	030613374-0010	South Face - East end at corner (scaffolding level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST16-5/2/06	030613374-0011	East Face - North end at corner (scaffolding level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST17-5/2/06	030613374-0012	North Face - West end at corner (scaffolding level)	5/2/06	1	3.000	Asbestos	PCME	EMSL	5/3/06	< 0.00082	No	No	
ASBESTOS-ST1-5/3/06	030613482-0001	Southwest Area (sidewalk bridge level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST2-5/3/06	030613482-0002	Southeast Area (sidewalk bridge level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST4-5/3/06	030613482-0003	Northwest Area (street-level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST5-5/3/06	030613482-0004	Firehouse #10 (roof level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST10-5/3/06	030613482-0005	North Side Sidewalk Bridge	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST11-5/3/06	030613482-0006	90 Trinity Place (roof level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST12-5/3/06	030613482-0007	110 Greenwich Street (roof level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST13-5/3/06	030613482-0008	Marriott Hotel, 38th Floor (roof level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST14-5/3/06	030613482-0009	West Face - South end at corner (scaffolding level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST15-5/3/06	030613482-0010	South Face - East end at corner (scaffolding level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST16-5/3/06	030613482-0011	East Face - North end at corner (scaffolding level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	
ASBESTOS-ST17-5/3/06	030613482-0012	North Face - West end at corner (scaffolding level)	5/3/06	1	3.000	Asbestos	PCME	EMSL	5/4/06	< 0.00082	No	No	