

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-5/4/07	030714331-0001	Southwest Area (sidewalk bridge level)	5/4/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST2-5/4/07	030714331-0002	Southeast Area (sidewalk bridge level)	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST4-5/4/07	030714331-0003	Northwest Area (street-level)	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST5-5/4/07	030714331-0004	Firehouse #10 (roof level)	5/4/07	1	3.020	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST10-5/4/07	030714331-0005	North Side Sidewalk Bridge	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST11-5/4/07	030714331-0006	90 Trinity Place (roof level)	5/4/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST12-5/4/07	030714331-0007	110 Greenwich Street (roof level)	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST13-5/4/07	030714331-0008	Marriott Hotel, 38th Floor (roof level)	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST14-5/4/07	030714331-0009	West Face - South end at corner (scaffolding level)	5/4/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST15-5/4/07	030714331-0010	South Face - East end at corner (scaffolding level)	5/4/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST16-5/4/07	030714331-0011	East Face - North end at corner (scaffolding level)	5/4/07	1	3.020	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST17-5/4/07	030714331-0012	North Face - West end at corner (scaffolding level)	5/4/07	1	3.000	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST1-5/5/07	030714332-0001	Southwest Area (sidewalk bridge level)	5/5/07	1	2.990	Asbestos	PCME	EMSL	5/7/07	< 0.00083	No	No	
ASBESTOS-ST2-5/5/07	030714332-0002	Southeast Area (sidewalk bridge level)	5/5/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST4-5/5/07	030714332-0003	Northwest Area (street-level)	5/5/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST5-5/5/07	030714332-0004	Firehouse #10 (roof level)	5/5/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST10-5/5/07	030714332-0005	North Side Sidewalk Bridge	5/5/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST11-5/5/07	030714332-0006	90 Trinity Place (roof level)	5/5/07	1	3.030	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST12-5/5/07	030714332-0007	110 Greenwich Street (roof level)	5/5/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST13-5/5/07	030714332-0008	Marriott Hotel, 38th Floor (roof level)	5/5/07	1	3.030	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST14-5/5/07	030714332-0009	West Face - South end at corner (scaffolding level)	5/5/07	1	3.050	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST15-5/5/07	030714332-0010	South Face - East end at corner (scaffolding level)	5/5/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST16-5/5/07	030714332-0011	East Face - North end at corner (scaffolding level)	5/5/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST17-5/5/07	030714332-0012	North Face - West end at corner (scaffolding level)	5/5/07	1	3.050	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST1-5/6/07	030714333-0001	Southwest Area (sidewalk bridge level)	5/6/07	1	3.040	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST2-5/6/07	030714333-0002	Southeast Area (sidewalk bridge level)	5/6/07	1	2.970	Asbestos	PCME	EMSL	5/7/07	< 0.00083	No	No	
ASBESTOS-ST4-5/6/07	030714333-0003	Northwest Area (street-level)	5/6/07	1	3.060	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST5-5/6/07	030714333-0004	Firehouse #10 (roof level)	5/6/07	1	3.010	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST10-5/6/07	030714333-0005	North Side Sidewalk Bridge	5/6/07	1	3.050	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST11-5/6/07	030714333-0006	90 Trinity Place (roof level)	5/6/07	1	3.050	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST12-5/6/07	030714333-0007	110 Greenwich Street (roof level)	5/6/07	1	3.070	Asbestos	PCME	EMSL	5/7/07	< 0.00080	No	No	
ASBESTOS-ST13-5/6/07	030714333-0008	Marriott Hotel, 38th Floor (roof level)	5/6/07	1	3.030	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST14-5/6/07	030714333-0009	West Face - South end at corner (scaffolding level)	5/6/07	1	3.070	Asbestos	PCME	EMSL	5/7/07	< 0.00080	No	No	
ASBESTOS-ST15-5/6/07	030714333-0010	South Face - East end at corner (scaffolding level)	5/6/07	1	3.030	Asbestos	PCME	EMSL	5/7/07	< 0.00081	No	No	
ASBESTOS-ST16-5/6/07	030714333-0011	East Face - North end at corner (scaffolding level)	5/6/07	1	3.020	Asbestos	PCME	EMSL	5/7/07	< 0.00082	No	No	
ASBESTOS-ST17-5/6/07	030714333-0012	North Face - West end at corner (scaffolding level)	5/6/07	1	3.070	Asbestos	PCME	EMSL	5/7/07	< 0.00080	No	No	