

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-5/10/07	030714981-0001	Southwest Area (sidewalk bridge level)	5/10/07	1	3.050	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST2-5/10/07	030714981-0002	Southeast Area (sidewalk bridge level)	5/10/07	1	3.010	Asbestos	PCME	EMSL	5/11/07	< 0.00082	No	No	
ASBESTOS-ST4-5/10/07	030714981-0003	Northwest Area (street-level)	5/10/07	1	2.990	Asbestos	PCME	EMSL	5/11/07	< 0.00083	No	No	
ASBESTOS-ST5-5/10/07	030714981-0004	Firehouse #10 (roof level)	5/10/07	1	3.040	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST10-5/10/07	030714981-0005	North Side Sidewalk Bridge	5/10/07	1	3.050	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST11-5/10/07	030714981-0006	90 Trinity Place (roof level)	5/10/07	1	3.040	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST12-5/10/07	030714981-0007	110 Greenwich Street (roof level)	5/10/07	1	3.040	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST13-5/10/07	030714981-0008	Marriott Hotel, 38th Floor (roof level)	5/10/07	1	3.020	Asbestos	PCME	EMSL	5/11/07	< 0.00082	No	No	
ASBESTOS-ST14-5/10/07	030714981-0009	West Face - South end at corner (scaffolding level)	5/10/07	1	3.280	Asbestos	PCME	EMSL	5/11/07	< 0.00082	No	No	
ASBESTOS-ST15-5/10/07	030714981-0010	South Face - East end at corner (scaffolding level)	5/10/07	1	3.050	Asbestos	PCME	EMSL	5/11/07	< 0.00081	No	No	
ASBESTOS-ST16-5/10/07	030714981-0011	East Face - North end at corner (scaffolding level)	5/10/07	1	3.010	Asbestos	PCME	EMSL	5/11/07	< 0.00082	No	No	
ASBESTOS-ST17-5/10/07	030714981-0012	North Face - West end at corner (scaffolding level)	5/10/07	1	3.010	Asbestos	PCME	EMSL	5/11/07	< 0.00082	No	No	
ASBESTOS-ST1-5/11/07	030715322-0001	Southwest Area (sidewalk bridge level)	5/11/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST2-5/11/07	030715322-0002	Southeast Area (sidewalk bridge level)	5/11/07	1	3.050	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST4-5/11/07	030715322-0003	Northwest Area (street-level)	5/11/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST5-5/11/07	030715322-0004	Firehouse #10 (roof level)	5/11/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST10-5/11/07	030715322-0005	North Side Sidewalk Bridge	5/11/07	1	3.160	Asbestos	PCME	EMSL	5/14/07	< 0.00078	No	No	
ASBESTOS-ST11-5/11/07	030715322-0006	90 Trinity Place (roof level)	5/11/07	1	3.050	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST12-5/11/07	030715322-0007	110 Greenwich Street (roof level)	5/11/07	1	3.070	Asbestos	PCME	EMSL	5/14/07	< 0.00080	No	No	
ASBESTOS-ST13-5/11/07	030715322-0008	Marriott Hotel, 38th Floor (roof level)	5/11/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST14-5/11/07	030715322-0009	West Face - South end at corner (scaffolding level)	5/11/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST15-5/11/07	030715322-0010	South Face - East end at corner (scaffolding level)	5/11/07	1	3.030	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST16-5/11/07	030715322-0011	East Face - North end at corner (scaffolding level)	5/11/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST17-5/11/07	030715322-0012	North Face - West end at corner (scaffolding level)	5/11/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST1-5/12/07	030715323-0001	Southwest Area (sidewalk bridge level)	5/12/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST2-5/12/07	030715323-0002	Southeast Area (sidewalk bridge level)	5/12/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST4-5/12/07	030715323-0003	Northwest Area (street-level)	5/12/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST5-5/12/07	030715323-0004	Firehouse #10 (roof level)	5/12/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST10-5/12/07	030715323-0005	North Side Sidewalk Bridge	5/12/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST11-5/12/07	030715323-0006	90 Trinity Place (roof level)	5/12/07	1	2.940	Asbestos	PCME	EMSL	5/14/07	< 0.00084	No	No	
ASBESTOS-ST12-5/12/07	030715323-0007	110 Greenwich Street (roof level)	5/12/07	1	2.970	Asbestos	PCME	EMSL	5/14/07	< 0.00083	No	No	
ASBESTOS-ST13-5/12/07	030715323-0008	Marriott Hotel, 38th Floor (roof level)	5/12/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST14-5/12/07	030715323-0009	West Face - South end at corner (scaffolding level)	5/12/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST15-5/12/07	030715323-0010	South Face - East end at corner (scaffolding level)	5/12/07	1	3.070	Asbestos	PCME	EMSL	5/14/07	< 0.00088	No	No	
ASBESTOS-ST16-5/12/07	030715323-0011	East Face - North end at corner (scaffolding level)	5/12/07	1	3.050	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST17-5/12/07	030715323-0012	North Face - West end at corner (scaffolding level)	5/12/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST1-5/13/07	030715324-0001	Southwest Area (sidewalk bridge level)	5/13/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST2-5/13/07	030715324-0002	Southeast Area (sidewalk bridge level)	5/13/07	1	3.060	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST4-5/13/07	030715324-0003	Northwest Area (street-level)	5/13/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST5-5/13/07	030715324-0004	Firehouse #10 (roof level)	5/13/07	1	3.020	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST10-5/13/07	030715324-0005	North Side Sidewalk Bridge	5/13/07	1	3.040	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST11-5/13/07	030715324-0006	90 Trinity Place (roof level)	5/13/07	1	2.910	Asbestos	PCME	EMSL	5/14/07	< 0.00085	No	No	
ASBESTOS-ST12-5/13/07	030715324-0007	110 Greenwich Street (roof level)	5/13/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST13-5/13/07	030715324-0008	Marriott Hotel, 38th Floor (roof level)	5/13/07	1	3.030	Asbestos	PCME	EMSL	5/14/07	< 0.00081	No	No	
ASBESTOS-ST14-5/13/07	030715324-0009	West Face - South end at corner (scaffolding level)	5/13/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST15-5/13/07	030715324-0010	South Face - East end at corner (scaffolding level)	5/13/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST16-5/13/07	030715324-0011	East Face - North end at corner (scaffolding level)	5/13/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	
ASBESTOS-ST17-5/13/07	030715324-0012	North Face - West end at corner (scaffolding level)	5/13/07	1	3.010	Asbestos	PCME	EMSL	5/14/07	< 0.00082	No	No	