

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels		
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-5/17/06	03061522-0001	Southwest Area (sidewalk bridge level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST2-5/17/06	03061522-0002	Southeast Area (sidewalk bridge level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST4-5/17/06	03061522-0003	Northwest Area (street-level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST5-5/17/06	03061522-0004	Firehouse #10 (roof level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST10-5/17/06	03061522-0005	North Side Sidewalk Bridge	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST11-5/17/06	03061522-0006	90 Trinity Place (roof level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST12-5/17/06	03061522-0007	110 Greenwich Street (roof level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST13-5/17/06	03061522-0008	Marriott Hotel, 38th Floor (roof level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST14-5/17/06	03061522-0009	West Face - South end at corner (scaffolding level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST15-5/17/06	03061522-0010	South Face - East end at corner (scaffolding level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST16-5/17/06	03061522-0011	East Face - North end at corner (scaffolding level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST17-5/17/06	03061522-0012	North Face - West end at corner (scaffolding level)	5/17/06	1	2.970	Asbestos	PCME	EMSL	5/18/06	< 0.00083	No	No		
ASBESTOS-ST1-5/18/06	030615349-0001	Southwest Area (sidewalk bridge level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST2-5/18/06	030615349-0002	Southeast Area (sidewalk bridge level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST4-5/18/06	030615349-0003	Northwest Area (street-level)	5/18/06	1	2.920	Asbestos	PCME	EMSL	5/19/06	< 0.00085	No	No		
ASBESTOS-ST5-5/18/06	030615349-0004	Firehouse #10 (roof level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST10-5/18/06	030615349-0005	North Side Sidewalk Bridge	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST11-5/18/06	030615349-0006	90 Trinity Place (roof level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST12-5/18/06	030615349-0007	110 Greenwich Street (roof level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST13-5/18/06	030615349-0008	Marriott Hotel, 38th Floor (roof level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST14-5/18/06	030615349-0009	West Face - South end at corner (scaffolding level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST15-5/18/06	030615349-0010	South Face - East end at corner (scaffolding level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST16-5/18/06	030615349-0011	East Face - North end at corner (scaffolding level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		
ASBESTOS-ST17-5/18/06	030615349-0012	North Face - West end at corner (scaffolding level)	5/18/06	1	2.970	Asbestos	PCME	EMSL	5/19/06	< 0.00083	No	No		