

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-5/19/06	030615640-0001	Southwest Area (sidewalk bridge level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST2-5/19/06	030615640-0002	Southeast Area (sidewalk bridge level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST4-5/19/06	030615640-0003	Northwest Area (street-level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST5-5/19/06	030615640-0004	Firehouse #10 (roof level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST10-5/19/06	030615640-0005	North Side Sidewalk Bridge	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST11-5/19/06	030615640-0006	90 Trinity Place (roof level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST12-5/19/06	030615640-0007	110 Greenwich Street (roof level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST13-5/19/06	030615640-0008	Marriott Hotel, 38th Floor (roof level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST14-5/19/06	030615640-0009	West Face - South end at corner (scaffolding level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST15-5/19/06	030615640-0010	South Face - East end at corner (scaffolding level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST16-5/19/06	030615640-0011	East Face - North end at corner (scaffolding level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST17-5/19/06	030615640-0012	North Face - West end at corner (scaffolding level)	5/19/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST1-5/20/06	030615642-0001	Southwest Area (sidewalk bridge level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST2-5/20/06	030615642-0002	Southeast Area (sidewalk bridge level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST4-5/20/06	030615642-0003	Northwest Area (street-level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST5-5/20/06	030615642-0004	Firehouse #10 (roof level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST10-5/20/06	030615642-0005	North Side Sidewalk Bridge	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST11-5/20/06	030615642-0006	90 Trinity Place (roof level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST12-5/20/06	030615642-0007	110 Greenwich Street (roof level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST13-5/20/06	030615642-0008	Marriott Hotel, 38th Floor (roof level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST14-5/20/06	030615642-0009	West Face - South end at corner (scaffolding level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST15-5/20/06	030615642-0010	South Face - East end at corner (scaffolding level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST16-5/20/06	030615642-0011	East Face - North end at corner (scaffolding level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST17-5/20/06	030615642-0012	North Face - West end at corner (scaffolding level)	5/20/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST1-5/21/06	030615641-0001	Southwest Area (sidewalk bridge level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST2-5/21/06	030615641-0002	Southeast Area (sidewalk bridge level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST4-5/21/06	030615641-0003	Northwest Area (street-level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST5-5/21/06	030615641-0004	Firehouse #10 (roof level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST10-5/21/06	030615641-0005	North Side Sidewalk Bridge	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST11-5/21/06	030615641-0006	90 Trinity Place (roof level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST12-5/21/06	030615641-0007	110 Greenwich Street (roof level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST13-5/21/06	030615641-0008	Marriott Hotel, 38th Floor (roof level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST14-5/21/06	030615641-0009	West Face - South end at corner (scaffolding level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST15-5/21/06	030615641-0010	South Face - East end at corner (scaffolding level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST16-5/21/06	030615641-0011	East Face - North end at corner (scaffolding level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	
ASBESTOS-ST17-5/21/06	030615641-0012	North Face - West end at corner (scaffolding level)	5/21/06	1	2.970	Asbestos	PCME	EMSL	5/22/06	< 0.00083	No	No	