

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|------------------------------|----------|
| Target Air Quality Levels | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | |
| EPA Site Specific Trigger Levels | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-5/26/06 | 030616432-0001 | Southwest Area (sidewalk bridge level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST2-5/26/06 | 030616432-0002 | Southeast Area (sidewalk bridge level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST4-5/26/06 | 030616432-0003 | Northwest Area (street-level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST5-5/26/06 | 030616432-0004 | Firehouse #10 (roof level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST10-5/26/06 | 030616432-0005 | North Side Sidewalk Bridge | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST11-5/26/06 | 030616432-0006 | 90 Trinity Place (roof level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/26/06 | 030616432-0007 | 110 Greenwich Street (roof level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST13-5/26/06 | 030616432-0008 | Marriott Hotel, 38th Floor (roof level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/26/06 | 030616432-0009 | West Face - South end at corner (scaffolding level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST15-5/26/06 | 030616432-0010 | South Face - East end at corner (scaffolding level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/26/06 | 030616432-0011 | East Face - North end at corner (scaffolding level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/26/06 | 030616432-0012 | North Face - West end at corner (scaffolding level) | 5/26/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST1-5/27/06 | 030616433-0001 | Southwest Area (sidewalk bridge level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST2-5/27/06 | 030616433-0002 | Southeast Area (sidewalk bridge level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST4-5/27/06 | 030616433-0003 | Northwest Area (street-level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST5-5/27/06 | 030616433-0004 | Firehouse #10 (roof level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST10-5/27/06 | 030616433-0005 | North Side Sidewalk Bridge | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST11-5/27/06 | 030616433-0006 | 90 Trinity Place (roof level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/27/06 | 030616433-0007 | 110 Greenwich Street (roof level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST13-5/27/06 | 030616433-0008 | Marriott Hotel, 38th Floor (roof level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/27/06 | 030616433-0009 | West Face - South end at corner (scaffolding level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST15-5/27/06 | 030616433-0010 | South Face - East end at corner (scaffolding level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/27/06 | 030616433-0011 | East Face - North end at corner (scaffolding level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/27/06 | 030616433-0012 | North Face - West end at corner (scaffolding level) | 5/27/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST1-5/28/06 | 030616434-0001 | Southwest Area (sidewalk bridge level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST2-5/28/06 | 030616434-0002 | Southeast Area (sidewalk bridge level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST4-5/28/06 | 030616434-0003 | Northwest Area (street-level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST5-5/28/06 | 030616434-0004 | Firehouse #10 (roof level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST10-5/28/06 | 030616434-0005 | North Side Sidewalk Bridge | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST11-5/28/06 | 030616434-0006 | 90 Trinity Place (roof level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/28/06 | 030616434-0007 | 110 Greenwich Street (roof level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST13-5/28/06 | 030616434-0008 | Marriott Hotel, 38th Floor (roof level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/28/06 | 030616434-0009 | West Face - South end at corner (scaffolding level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST15-5/28/06 | 030616434-0010 | South Face - East end at corner (scaffolding level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/28/06 | 030616434-0011 | East Face - North end at corner (scaffolding level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/28/06 | 030616434-0012 | North Face - West end at corner (scaffolding level) | 5/28/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST1-5/29/06 | 030616435-0001 | Southwest Area (sidewalk bridge level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST2-5/29/06 | 030616435-0002 | Southeast Area (sidewalk bridge level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST4-5/29/06 | 030616435-0003 | Northwest Area (street-level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST5-5/29/06 | 030616435-0004 | Firehouse #10 (roof level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST10-5/29/06 | 030616435-0005 | North Side Sidewalk Bridge | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST11-5/29/06 | 030616435-0006 | 90 Trinity Place (roof level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/29/06 | 030616435-0007 | 110 Greenwich Street (roof level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/29/06 | 030616435-0009 | West Face - South end at corner (scaffolding level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST15-5/29/06 | 030616435-0010 | South Face - East end at corner (scaffolding level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/29/06 | 030616435-0011 | East Face - North end at corner (scaffolding level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/29/06 | 030616435-0012 | North Face - West end at corner (scaffolding level) | 5/29/06 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/30/06 | < 0.00083 | No | No | |

Note:

1. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on May 29, 2006 was not available for analysis on account of a damaged filter.