

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ASBESTOS-ST1-6/4/07	030717984-0001	Southwest Area (sidewalk bridge level)	6/4/07	1	2.900	Asbestos	PCME	EMSL	6/5/07	< 0.00085	No	No	
ASBESTOS-ST2-6/4/07	030717984-0002	Southeast Area (sidewalk bridge level)	6/4/07	1	3.150	Asbestos	PCME	EMSL	6/5/07	< 0.00078	No	No	
ASBESTOS-ST4-6/4/07	030717984-0003	Northwest Area (street-level)	6/4/07	1	3.400	Asbestos	PCME	EMSL	6/5/07	< 0.00073	No	No	Note 1
ASBESTOS-ST5-6/4/07	030717984-0004	Firehouse #10 (roof level)	6/4/07	1	3.040	Asbestos	PCME	EMSL	6/5/07	< 0.00081	No	No	
ASBESTOS-ST10-6/4/07	030717984-0005	North Side Sidewalk Bridge	6/4/07	1	2.920	Asbestos	PCME	EMSL	6/5/07	< 0.00085	No	No	
ASBESTOS-ST11-6/4/07	030717984-0006	90 Trinity Place (roof level)	6/4/07	1	3.090	Asbestos	PCME	EMSL	6/5/07	< 0.00080	No	No	
ASBESTOS-ST12-6/4/07	030717984-0007	110 Greenwich Street (roof level)	6/4/07	1	3.010	Asbestos	PCME	EMSL	6/5/07	< 0.00082	No	No	
ASBESTOS-ST13-6/4/07	030717984-0008	Marriott Hotel, 38th Floor (roof level)	6/4/07	1	3.010	Asbestos	PCME	EMSL	6/5/07	< 0.00082	No	No	
ASBESTOS-ST14-6/4/07	030717984-0009	West Face - South end at corner (scaffolding level)	6/4/07	1	2.870	Asbestos	PCME	EMSL	6/5/07	< 0.00086	No	No	
ASBESTOS-ST15-6/4/07	030717984-0010	South Face - East end at corner (scaffolding level)	6/4/07	1	3.010	Asbestos	PCME	EMSL	6/5/07	< 0.00082	No	No	
ASBESTOS-ST16-6/4/07	030717984-0011	East Face - North end at corner (scaffolding level)	6/4/07	1	3.020	Asbestos	PCME	EMSL	6/5/07	< 0.00082	No	No	
ASBESTOS-ST17-6/4/07	030717984-0012	North Face - West end at corner (scaffolding level)	6/4/07	1	3.070	Asbestos	PCME	EMSL	6/5/07	< 0.00080	No	No	
ASBESTOS-ST1-6/5/07	030718131-0001	Southwest Area (sidewalk bridge level)	6/5/07	1	3.070	Asbestos	PCME	EMSL	6/6/07	< 0.00080	No	No	
ASBESTOS-ST2-6/5/07	030718131-0002	Southeast Area (sidewalk bridge level)	6/5/07	1	3.090	Asbestos	PCME	EMSL	6/6/07	< 0.00080	No	No	
ASBESTOS-ST4-6/5/07	030718131-0003	Northwest Area (street-level)	6/5/07	1	3.060	Asbestos	PCME	EMSL	6/6/07	< 0.00081	No	No	
ASBESTOS-ST5-6/5/07	030718131-0004	Firehouse #10 (roof level)	6/5/07	1	3.190	Asbestos	PCME	EMSL	6/6/07	< 0.00077	No	No	
ASBESTOS-ST10-6/5/07	030718131-0005	North Side Sidewalk Bridge	6/5/07	1	3.040	Asbestos	PCME	EMSL	6/6/07	< 0.00081	No	No	
ASBESTOS-ST11-6/5/07	030718131-0006	90 Trinity Place (roof level)	6/5/07	1	2.850	Asbestos	PCME	EMSL	6/6/07	< 0.00087	No	No	
ASBESTOS-ST12-6/5/07	030718131-0007	110 Greenwich Street (roof level)	6/5/07	1	2.520	Asbestos	PCME	EMSL	6/6/07	< 0.00084	No	No	Note 2
ASBESTOS-ST13-6/5/07	030718131-0008	Marriott Hotel, 38th Floor (roof level)	6/5/07	1	3.010	Asbestos	PCME	EMSL	6/6/07	< 0.00082	No	No	
ASBESTOS-ST14-6/5/07	030718131-0009	West Face - South end at corner (scaffolding level)	6/5/07	1	3.040	Asbestos	PCME	EMSL	6/6/07	< 0.00081	No	No	
ASBESTOS-ST15-6/5/07	030718131-0010	South Face - East end at corner (scaffolding level)	6/5/07	1	3.030	Asbestos	PCME	EMSL	6/6/07	< 0.00081	No	No	
ASBESTOS-ST16-6/5/07	030718131-0011	East Face - North end at corner (scaffolding level)	6/5/07	1	2.970	Asbestos	PCME	EMSL	6/6/07	< 0.00083	No	No	
ASBESTOS-ST17-6/5/07	030718131-0012	North Face - West end at corner (scaffolding level)	6/5/07	1	2.360	Asbestos	PCME	EMSL	6/6/07	< 0.00084	No	No	

Note:

1. Due to flow rate RPD exceedance (22.2%) for asbestos at Station 4 (Northwest Area [street-level]) on June 4, 2007, the sample volume and subsequent sample result are estimated.
2. Due to flow rate RPD exceedance (40.0%) for asbestos at Station 12 (110 Greenwich Street [roof level]) on June 5, 2007, the sample volume and subsequent sample result are estimated.