

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1- 6/6/09	030914140-0001	Southwest Area (sidewalk bridge level)	6/6/09	1	2.940	Asbestos	PCME	EMSL	6/8/09	< 0.00084	No	No	
ASBESTOS-ST2-6/6/09	030914140-0002	Southeast Area (sidewalk bridge level)	6/6/09	1	3.060	Asbestos	PCME	EMSL	6/8/09	< 0.00081	No	No	
ASBESTOS-ST4-6/6/09	030914140-0003	Northwest Area (street-level)	6/6/09	1	3.190	Asbestos	PCME	EMSL	6/8/09	< 0.00077	No	No	
ASBESTOS-ST5-6/6/09	030914140-0004	Firehouse #10 (roof level)	6/6/09	1	3.160	Asbestos	PCME	EMSL	6/8/09	< 0.00078	No	No	
ASBESTOS-ST10-6/6/09	030914140-0005	North Side Sidewalk Bridge	6/6/09	1	3.130	Asbestos	PCME	EMSL	6/8/09	< 0.00079	No	No	
ASBESTOS-ST11-6/6/09	030914140-0006	90 Trinity Place (roof level)	6/6/09	1	2.980	Asbestos	PCME	EMSL	6/8/09	< 0.00076	No	No	
ASBESTOS-ST12-6/6/09	030914140-0007	110 Greenwich Street (roof level)	6/6/09	1	3.010	Asbestos	PCME	EMSL	6/8/09	< 0.00082	No	No	
ASBESTOS-ST13-6/6/09	030914140-0008	Marriott Hotel, 38th Floor (roof level)	6/6/09	1	3.140	Asbestos	PCME	EMSL	6/8/09	< 0.00079	No	No	
ASBESTOS-ST1-6/7/09	030914139-0001	Southwest Area (sidewalk bridge level)	6/7/09	1	3.100	Asbestos	PCME	EMSL	6/8/09	< 0.00080	No	No	
ASBESTOS-ST2-6/7/09	030914139-0002	Southeast Area (sidewalk bridge level)	6/7/09	1	3.150	Asbestos	PCME	EMSL	6/8/09	< 0.00078	No	No	
ASBESTOS-ST4-6/7/09	030914139-0003	Northwest Area (street-level)	6/7/09	1	2.950	Asbestos	PCME	EMSL	6/8/09	< 0.00084	No	No	
ASBESTOS-ST5-6/7/09	030914139-0004	Firehouse #10 (roof level)	6/7/09	1	3.030	Asbestos	PCME	EMSL	6/8/09	< 0.00081	No	No	
ASBESTOS-ST10-6/7/09	030914139-0005	North Side Sidewalk Bridge	6/7/09	1	3.250	Asbestos	PCME	EMSL	6/8/09	< 0.00076	No	No	
ASBESTOS-ST11-6/7/09	030914139-0006	90 Trinity Place (roof level)	6/7/09	1	3.030	Asbestos	PCME	EMSL	6/8/09	< 0.00081	No	No	
ASBESTOS-ST12-6/7/09	030914139-0007	110 Greenwich Street (roof level)	6/7/09	1	3.230	Asbestos	PCME	EMSL	6/8/09	< 0.00076	No	No	
ASBESTOS-ST13-6/7/09	030914139-0008	Marriott Hotel, 38th Floor (roof level)	6/7/09	1	2.900	Asbestos	PCME	EMSL	6/8/09	< 0.00085	No	No	
ASBESTOS-ST1-6/8/09	030914208-0001	Southwest Area (sidewalk bridge level)	6/8/09	1	2.970	Asbestos	PCME	EMSL	6/9/09	< 0.00083	No	No	
ASBESTOS-ST2-6/8/09	030914208-0002	Southeast Area (sidewalk bridge level)	6/8/09	1	3.020	Asbestos	PCME	EMSL	6/9/09	< 0.00082	No	No	
ASBESTOS-ST4-6/8/09	030914208-0003	Northwest Area (street-level)	6/8/09	1	2.980	Asbestos	PCME	EMSL	6/9/09	< 0.00083	No	No	
ASBESTOS-ST5-6/8/09	030914208-0004	Firehouse #10 (roof level)	6/8/09	1	3.030	Asbestos	PCME	EMSL	6/9/09	< 0.00081	No	No	
ASBESTOS-ST10-6/8/09	030914208-0005	North Side Sidewalk Bridge	6/8/09	1	2.950	Asbestos	PCME	EMSL	6/9/09	< 0.00084	No	No	
ASBESTOS-ST11-6/8/09	030914208-0006	90 Trinity Place (roof level)	6/8/09	1	3.030	Asbestos	PCME	EMSL	6/9/09	< 0.00081	No	No	
ASBESTOS-ST12-6/8/09	030914208-0007	110 Greenwich Street (roof level)	6/8/09	1	3.130	Asbestos	PCME	EMSL	6/9/09	< 0.00079	No	No	
ASBESTOS-ST13-6/8/09	030914208-0008	Marriott Hotel, 38th Floor (roof level)	6/8/09	1	3.010	Asbestos	PCME	EMSL	6/9/09	< 0.00082	No	No	