

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-6/9/06	030617797-0001	Southwest Area (sidewalk bridge level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST2-6/9/06	030617797-0002	Southeast Area (sidewalk bridge level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST4-6/9/06	030617797-0003	Northwest Area (street-level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST5-6/9/06	030617797-0004	Firehouse #10 (roof level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST10-6/9/06	030617797-0005	North Side Sidewalk Bridge	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST100-6/9/06	030617797-0013	Station 10 Field Duplicate	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST11-6/9/06	030617797-0006	90 Trinity Place (roof level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST12-6/9/06	030617797-0007	110 Greenwich Street (roof level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST13-6/9/06	030617797-0008	Marriott Hotel, 38th Floor (roof level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST14-6/9/06	030617797-0009	West Face - South end at corner (scaffolding level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST15-6/9/06	030617797-0010	South Face - East end at corner (scaffolding level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST16-6/9/06	030617797-0011	East Face - North end at corner (scaffolding level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST17-6/9/06	030617797-0012	North Face - West end at corner (scaffolding level)	6/9/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST1-6/10/06	030617798-0001	Southwest Area (sidewalk bridge level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST2-6/10/06	030617798-0002	Southeast Area (sidewalk bridge level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST4-6/10/06	030617798-0003	Northwest Area (street-level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST5-6/10/06	030617798-0004	Firehouse #10 (roof level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST10-6/10/06	030617798-0005	North Side Sidewalk Bridge	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST11-6/10/06	030617798-0006	90 Trinity Place (roof level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST12-6/10/06	030617798-0007	110 Greenwich Street (roof level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST13-6/10/06	030617798-0008	Marriott Hotel, 38th Floor (roof level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST14-6/10/06	030617798-0009	West Face - South end at corner (scaffolding level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST15-6/10/06	030617798-0010	South Face - East end at corner (scaffolding level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST16-6/10/06	030617798-0011	East Face - North end at corner (scaffolding level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST17-6/10/06	030617798-0012	North Face - West end at corner (scaffolding level)	6/10/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST1-6/11/06	030617799-0001	Southwest Area (sidewalk bridge level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST2-6/11/06	030617799-0002	Southeast Area (sidewalk bridge level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST4-6/11/06	030617799-0003	Northwest Area (street-level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST5-6/11/06	030617799-0004	Firehouse #10 (roof level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST10-6/11/06	030617799-0005	North Side Sidewalk Bridge	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST11-6/11/06	030617799-0006	90 Trinity Place (roof level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST12-6/11/06	030617799-0007	110 Greenwich Street (roof level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST13-6/11/06	030617799-0008	Marriott Hotel, 38th Floor (roof level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST14-6/11/06	030617799-0009	West Face - South end at corner (scaffolding level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST15-6/11/06	030617799-0010	South Face - East end at corner (scaffolding level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST16-6/11/06	030617799-0011	East Face - North end at corner (scaffolding level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST17-6/11/06	030617799-0012	North Face - West end at corner (scaffolding level)	6/11/06	1	2.970	Asbestos	PCME	EMSL	6/12/06	< 0.00083	No	No	
ASBESTOS-ST1-06/12/06	030617961-0001	Southwest Area (sidewalk bridge level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST2-06/12/06	030617961-0002	Southeast Area (sidewalk bridge level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST4-06/12/06	030617961-0003	Northwest Area (street-level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST5-06/12/06	030617961-0004	Firehouse #10 (roof level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST10-06/12/06	030617961-0005	North Side Sidewalk Bridge	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST11-06/12/06	030617961-0006	90 Trinity Place (roof level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST12-06/12/06	030617961-0007	110 Greenwich Street (roof level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST13-06/12/06	030617961-0008	Marriott Hotel, 38th Floor (roof level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST14-06/12/06	030617961-0009	West Face - South end at corner (scaffolding level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST15-06/12/06	030617961-0010	South Face - East end at corner (scaffolding level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST16-06/12/06	030617961-0011	East Face - North end at corner (scaffolding level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	
ASBESTOS-ST17-06/12/06	030617961-0012	North Face - West end at corner (scaffolding level)	6/12/06	1	2.970	Asbestos	PCME	EMSL	6/13/06	< 0.00083	No	No	