

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-6/10/07	030718739-0001	Southwest Area (sidewalk bridge level)	6/10/07	1	3.140	Asbestos	PCME	EMSL	6/11/07	< 0.00079	No	No	
ASBESTOS-ST2-6/10/07	030718739-0002	Southeast Area (sidewalk bridge level)	6/10/07	1	3.090	Asbestos	PCME	EMSL	6/11/07	< 0.00080	No	No	
ASBESTOS-ST4-6/10/07	030718739-0003	Northwest Area (street-level)	6/10/07	1	3.210	Asbestos	PCME	EMSL	6/11/07	< 0.00077	No	No	
ASBESTOS-ST5-6/10/07	030718739-0004	Firehouse #10 (roof level)	6/10/07	1	3.010	Asbestos	PCME	EMSL	6/11/07	< 0.00082	No	No	
ASBESTOS-ST10-6/10/07	030718739-0005	North Side Sidewalk Bridge	6/10/07	1	3.090	Asbestos	PCME	EMSL	6/11/07	< 0.00080	No	No	
ASBESTOS-ST11-6/10/07	030718739-0006	90 Trinity Place (roof level)	6/10/07	1	3.060	Asbestos	PCME	EMSL	6/11/07	< 0.00081	No	No	
ASBESTOS-ST12-6/10/07	030718739-0007	110 Greenwich Street (roof level)	6/10/07	1	3.030	Asbestos	PCME	EMSL	6/11/07	< 0.00081	No	No	
ASBESTOS-ST13-6/10/07	030718739-0008	Marriott Hotel, 38th Floor (roof level)	6/10/07	1	3.010	Asbestos	PCME	EMSL	6/11/07	< 0.00082	No	No	
ASBESTOS-ST14-6/10/07	030718739-0009	West Face - South end at corner (scaffolding level)	6/10/07	1	3.010	Asbestos	PCME	EMSL	6/11/07	< 0.00082	No	No	
ASBESTOS-ST15-6/10/07	030718739-0010	South Face - East end at corner (scaffolding level)	6/10/07	1	3.400	Asbestos	PCME	EMSL	6/11/07	< 0.00073	No	No	
ASBESTOS-ST16-6/10/07	030718739-0011	East Face - North end at corner (scaffolding level)	6/10/07	1	3.010	Asbestos	PCME	EMSL	6/11/07	< 0.00082	No	No	
ASBESTOS-ST17-6/10/07	030718739-0012	North Face - West end at corner (scaffolding level)	6/10/07	1	3.060	Asbestos	PCME	EMSL	6/11/07	< 0.00081	No	No	
ASBESTOS-ST1-6/11/07	030718921-0001	Southwest Area (sidewalk bridge level)	6/11/07	1	3.060	Asbestos	PCME	EMSL	6/12/07	< 0.00081	No	No	
ASBESTOS-ST2-6/11/07	030718921-0002	Southeast Area (sidewalk bridge level)	6/11/07	1	3.070	Asbestos	PCME	EMSL	6/12/07	< 0.00080	No	No	
ASBESTOS-ST4-6/11/07	030718921-0004	Northwest Area (street-level)	6/11/07	1	3.040	Asbestos	PCME	EMSL	6/12/07	< 0.00081	No	No	
ASBESTOS-ST5-6/11/07	030718921-0003	Firehouse #10 (roof level)	6/11/07	1	2.960	Asbestos	PCME	EMSL	6/12/07	< 0.00077	No	No	
ASBESTOS-ST10-6/11/07	030718921-0005	North Side Sidewalk Bridge	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST11-6/11/07	030718921-0006	90 Trinity Place (roof level)	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST12-6/11/07	030718921-0007	110 Greenwich Street (roof level)	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST13-6/11/07	030718921-0008	Marriott Hotel, 38th Floor (roof level)	6/11/07	1	3.000	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST14-6/11/07	030718921-0009	West Face - South end at corner (scaffolding level)	6/11/07	1	3.190	Asbestos	PCME	EMSL	6/12/07	< 0.00077	No	No	
ASBESTOS-ST15-6/11/07	030718921-0010	South Face - East end at corner (scaffolding level)	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST16-6/11/07	030718921-0011	East Face - North end at corner (scaffolding level)	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST17-6/11/07	030718921-0012	North Face - West end at corner (scaffolding level)	6/11/07	1	3.020	Asbestos	PCME	EMSL	6/12/07	< 0.00082	No	No	
ASBESTOS-ST1-6/12/07	030719065-0001	Southwest Area (sidewalk bridge level)	6/12/07	1	3.070	Asbestos	PCME	EMSL	6/13/07	< 0.00080	No	No	
ASBESTOS-ST2-6/12/07	030719065-0002	Southeast Area (sidewalk bridge level)	6/12/07	1	3.140	Asbestos	PCME	EMSL	6/13/07	< 0.00079	No	No	
ASBESTOS-ST4-6/12/07	030719065-0003	Northwest Area (street-level)	6/12/07	1	3.150	Asbestos	PCME	EMSL	6/13/07	< 0.00078	No	No	
ASBESTOS-ST5-6/12/07	030719065-0004	Firehouse #10 (roof level)	6/12/07	1	3.060	Asbestos	PCME	EMSL	6/13/07	< 0.00081	No	No	
ASBESTOS-ST10-6/12/07	030719065-0005	North Side Sidewalk Bridge	6/12/07	1	3.020	Asbestos	PCME	EMSL	6/13/07	< 0.00082	No	No	
ASBESTOS-ST11-6/12/07	030719065-0006	90 Trinity Place (roof level)	6/12/07	1	3.100	Asbestos	PCME	EMSL	6/13/07	< 0.00080	No	No	
ASBESTOS-ST12-6/12/07	030719065-0007	110 Greenwich Street (roof level)	6/12/07	1	3.050	Asbestos	PCME	EMSL	6/13/07	< 0.00081	No	No	
ASBESTOS-ST13-6/12/07	030719065-0008	Marriott Hotel, 38th Floor (roof level)	6/12/07	1	3.040	Asbestos	PCME	EMSL	6/13/07	< 0.00081	No	No	
ASBESTOS-ST14-6/12/07	030719065-0009	West Face - South end at corner (scaffolding level)	6/12/07	1	3.120	Asbestos	PCME	EMSL	6/13/07	< 0.00079	No	No	
ASBESTOS-ST15-6/12/07	030719065-0010	South Face - East end at corner (scaffolding level)	6/12/07	1	3.020	Asbestos	PCME	EMSL	6/13/07	< 0.00082	No	No	
ASBESTOS-ST16-6/12/07	030719065-0011	East Face - North end at corner (scaffolding level)	6/12/07	1	3.040	Asbestos	PCME	EMSL	6/13/07	< 0.00081	No	No	
ASBESTOS-ST17-6/12/07	030719065-0012	North Face - West end at corner (scaffolding level)	6/12/07	1	3.020	Asbestos	PCME	EMSL	6/13/07	< 0.00082	No	No	