

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-6/10/09	030914413-0001	Southwest Area (sidewalk bridge level)	6/10/09	1	3.070	Asbestos	PCME	EMSL	6/11/09	< 0.00080	No	No	
ASBESTOS-ST2-6/10/09	030914413-0002	Southeast Area (sidewalk bridge level)	6/10/09	1	3.050	Asbestos	PCME	EMSL	6/11/09	< 0.00081	No	No	
ASBESTOS-ST4-6/10/09	030914413-0003	Northwest Area (street-level)	6/10/09	1	2.960	Asbestos	PCME	EMSL	6/11/09	< 0.00077	No	No	
ASBESTOS-ST5-6/10/09	030914413-0004	Firehouse #10 (roof level)	6/10/09	1	3.010	Asbestos	PCME	EMSL	6/11/09	< 0.00082	No	No	
ASBESTOS-ST10-6/10/09	030914413-0005	North Side Sidewalk Bridge	6/10/09	1	2.970	Asbestos	PCME	EMSL	6/11/09	< 0.00083	No	No	
ASBESTOS-ST11-6/10/09	030914413-0006	90 Trinity Place (roof level)	6/10/09	1	3.120	Asbestos	PCME	EMSL	6/11/09	< 0.00079	No	No	
ASBESTOS-ST12-6/10/09	030914413-0007	110 Greenwich Street (roof level)	6/10/09	1	3.090	Asbestos	PCME	EMSL	6/11/09	< 0.00080	No	No	
ASBESTOS-ST13-6/10/09	030914413-0008	Marriott Hotel, 38th Floor (roof level)	6/10/09	1	3.080	Asbestos	PCME	EMSL	6/11/09	< 0.00080	No	No	
ASBESTOS-ST1-6/11/09	030914569-0001	Southwest Area (sidewalk bridge level)	6/11/09	1	2.970	Asbestos	PCME	EMSL	6/12/09	< 0.00083	No	No	
ASBESTOS-ST2-6/11/09	030914569-0002	Southeast Area (sidewalk bridge level)	6/11/09	1	3.070	Asbestos	PCME	EMSL	6/12/09	< 0.00080	No	No	
ASBESTOS-ST4-6/11/09	030914569-0003	Northwest Area (street-level)	6/11/09	1	3.040	Asbestos	PCME	EMSL	6/12/09	< 0.00081	No	No	
ASBESTOS-ST5-6/11/09	030914569-0004	Firehouse #10 (roof level)	6/11/09	1	3.110	Asbestos	PCME	EMSL	6/12/09	< 0.00079	No	No	
ASBESTOS-ST10-6/11/09	030914569-0005	North Side Sidewalk Bridge	6/11/09	1	3.080	Asbestos	PCME	EMSL	6/12/09	< 0.00080	No	No	
ASBESTOS-ST11-6/11/09	030914569-0006	90 Trinity Place (roof level)	6/11/09	1	3.040	Asbestos	PCME	EMSL	6/12/09	< 0.00081	No	No	
ASBESTOS-ST12-6/11/09	030914569-0007	110 Greenwich Street (roof level)	6/11/09	1	3.090	Asbestos	PCME	EMSL	6/12/09	< 0.00080	No	No	
ASBESTOS-ST13-6/11/09	030914569-0008	Marriott Hotel, 38th Floor (roof level)	6/11/09	1	2.970	Asbestos	PCME	EMSL	6/12/09	< 0.00083	No	No	
ASBESTOS-ST1-6/12/09	030914640-0001	Southwest Area (sidewalk bridge level)	6/12/09	1	3.030	Asbestos	PCME	EMSL	6/13/09	< 0.00081	No	No	
ASBESTOS-ST2-6/12/09	030914640-0002	Southeast Area (sidewalk bridge level)	6/12/09	1	2.970	Asbestos	PCME	EMSL	6/13/09	< 0.00083	No	No	
ASBESTOS-ST4-6/12/09	030914640-0003	Northwest Area (street-level)	6/12/09	1	2.940	Asbestos	PCME	EMSL	6/13/09	< 0.00084	No	No	
ASBESTOS-ST5-6/12/09	030914640-0004	Firehouse #10 (roof level)	6/12/09	1	3.090	Asbestos	PCME	EMSL	6/13/09	< 0.00080	No	No	
ASBESTOS-ST10-6/12/09	030914640-0005	North Side Sidewalk Bridge	6/12/09	1	2.950	Asbestos	PCME	EMSL	6/13/09	< 0.00084	No	No	
ASBESTOS-ST11-6/12/09	030914640-0006	90 Trinity Place (roof level)	6/12/09	1	3.030	Asbestos	PCME	EMSL	6/13/09	< 0.00081	No	No	
ASBESTOS-ST12-6/12/09	030914640-0007	110 Greenwich Street (roof level)	6/12/09	1	2.990	Asbestos	PCME	EMSL	6/13/09	< 0.00083	No	No	
ASBESTOS-ST13-6/12/09	030914640-0008	Marriott Hotel, 38th Floor (roof level)	6/12/09	1	3.050	Asbestos	PCME	EMSL	6/13/09	< 0.00081	No	No	