

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-7/6/07	030722470-0001	Southwest Area (sidewalk bridge level)	7/6/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST2-7/6/07	030722470-0002	Southeast Area (sidewalk bridge level)	7/6/07	1	3.010	Asbestos	PCME	EMSL	7/9/07	< 0.00082	No	No	
ASBESTOS-ST4-7/6/07	030722470-0003	Northwest Area (street-level)	7/6/07	1	3.070	Asbestos	PCME	EMSL	7/9/07	< 0.00080	No	No	
ASBESTOS-ST5-7/6/07	030722470-0004	Firehouse #10 (roof level)	7/6/07	1	3.060	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST10-7/6/07	030722470-0005	North Side Sidewalk Bridge	7/6/07	1	3.050	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST11-7/6/07	030722470-0006	90 Trinity Place (roof level)	7/6/07	1	3.050	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST12-7/6/07	030722470-0007	110 Greenwich Street (roof level)	7/6/07	1	2.960	Asbestos	PCME	EMSL	7/9/07	< 0.00083	No	No	
ASBESTOS-ST13-7/6/07	030722470-0008	Marriott Hotel, 38th Floor (roof level)	7/6/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST14-7/6/07	030722470-0009	West Face - South end at corner (scaffolding level)	7/6/07	1	3.030	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST15-7/6/07	030722470-0010	South Face - East end at corner (scaffolding level)	7/6/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST16-7/6/07	030722470-0011	East Face - North end at corner (scaffolding level)	7/6/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST17-7/6/07	030722470-0012	North Face - West end at corner (scaffolding level)	7/6/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST1-7/7/07	030722479-0001	Southwest Area (sidewalk bridge level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST2-7/7/07	030722479-0002	Southeast Area (sidewalk bridge level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST4-7/7/07	030722479-0003	Northwest Area (street-level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST5-7/7/07	030722479-0004	Firehouse #10 (roof level)	7/7/07	1	3.060	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST10-7/7/07	030722479-0005	North Side Sidewalk Bridge	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST11-7/7/07	030722479-0006	90 Trinity Place (roof level)	7/7/07	1	3.020	Asbestos	PCME	EMSL	7/9/07	< 0.00082	No	No	
ASBESTOS-ST12-7/7/07	030722479-0007	110 Greenwich Street (roof level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST13-7/7/07	030722479-0008	Marriott Hotel, 38th Floor (roof level)	7/7/07	1	3.020	Asbestos	PCME	EMSL	7/9/07	< 0.00082	No	No	
ASBESTOS-ST14-7/7/07	030722479-0009	West Face - South end at corner (scaffolding level)	7/7/07	1	3.020	Asbestos	PCME	EMSL	7/9/07	< 0.00082	No	No	
ASBESTOS-ST15-7/7/07	030722479-0010	South Face - East end at corner (scaffolding level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST16-7/7/07	030722479-0011	East Face - North end at corner (scaffolding level)	7/7/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST17-7/7/07	030722479-0012	North Face - West end at corner (scaffolding level)	7/7/07	1	3.030	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST1-7/8/07	030722468-0001	Southwest Area (sidewalk bridge level)	7/8/07	1	3.040	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST2-7/8/07	030722468-0002	Southeast Area (sidewalk bridge level)	7/8/07	1	3.060	Asbestos	PCME	EMSL	7/9/07	< 0.00088	No	No	
ASBESTOS-ST4-7/8/07	030722468-0003	Northwest Area (street-level)	7/8/07	1	3.150	Asbestos	PCME	EMSL	7/9/07	< 0.00085	No	No	
ASBESTOS-ST5-7/8/07	030722468-0004	Firehouse #10 (roof level)	7/8/07	1	3.060	Asbestos	PCME	EMSL	7/9/07	< 0.00088	No	No	
ASBESTOS-ST10-7/8/07	030722468-0005	North Side Sidewalk Bridge	7/8/07	1	2.990	Asbestos	PCME	EMSL	7/9/07	< 0.00083	No	No	
ASBESTOS-ST11-7/8/07	030722468-0006	90 Trinity Place (roof level)	7/8/07	1	3.090	Asbestos	PCME	EMSL	7/9/07	< 0.00087	No	No	
ASBESTOS-ST12-7/8/07	030722468-0007	110 Greenwich Street (roof level)	7/8/07	1	3.030	Asbestos	PCME	EMSL	7/9/07	< 0.00081	No	No	
ASBESTOS-ST13-7/8/07	030722468-0008	Marriott Hotel, 38th Floor (roof level)	7/8/07	1	3.000	Asbestos	PCME	EMSL	7/9/07	< 0.00082	No	No	
ASBESTOS-ST14-7/8/07	030722468-0009	West Face - South end at corner (scaffolding level)	7/8/07	1	2.950	Asbestos	PCME	EMSL	7/9/07	< 0.00084	No	No	
ASBESTOS-ST15-7/8/07	030722468-0010	South Face - East end at corner (scaffolding level)	7/8/07	1	3.210	Asbestos	PCME	EMSL	7/9/07	< 0.00084	No	No	
ASBESTOS-ST16-7/8/07	030722468-0011	East Face - North end at corner (scaffolding level)	7/8/07	1	3.180	Asbestos	PCME	EMSL	7/9/07	< 0.00085	No	No	
ASBESTOS-ST17-7/8/07	030722468-0012	North Face - West end at corner (scaffolding level)	7/8/07	1	3.090	Asbestos	PCME	EMSL	7/9/07	< 0.00087	No	No	