

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-7/6/09	030916898-0001	Southwest Area (sidewalk bridge level)	7/6/09	1	3.110	Asbestos	PCME	EMSL	7/7/09	< 0.00079	No	No	
ASBESTOS-ST2-7/6/09	030916898-0002	Southeast Area (sidewalk bridge level)	7/6/09	1	3.060	Asbestos	PCME	EMSL	7/7/09	< 0.00081	No	No	
ASBESTOS-ST4-7/6/09	030916898-0003	Northwest Area (street-level)	7/6/09	1	3.130	Asbestos	PCME	EMSL	7/7/09	< 0.00079	No	No	
ASBESTOS-ST5-7/6/09	030916898-0004	Firehouse #10 (roof level)	7/6/09	1	3.040	Asbestos	PCME	EMSL	7/7/09	< 0.00081	No	No	
ASBESTOS-ST10-7/6/09	030916898-0005	North Side Sidewalk Bridge	7/6/09	1	3.020	Asbestos	PCME	EMSL	7/7/09	< 0.00082	No	No	
ASBESTOS-ST11-7/6/09	030916898-0006	90 Trinity Place (roof level)	7/6/09	1	3.030	Asbestos	PCME	EMSL	7/7/09	< 0.00081	No	No	
ASBESTOS-ST12-7/6/09	030916898-0007	110 Greenwich Street (roof level)	7/6/09	1	3.080	Asbestos	PCME	EMSL	7/7/09	< 0.00080	No	No	
ASBESTOS-ST13-7/6/09	030916898-0008	Marriott Hotel, 38th Floor (roof level)	7/6/09	1	3.050	Asbestos	PCME	EMSL	7/7/09	< 0.00081	No	No	
ASBESTOS-ST1-7/7/09	030917025-0001	Southwest Area (sidewalk bridge level)	7/7/09	1	3.000	Asbestos	PCME	EMSL	7/8/09	< 0.00082	No	No	
ASBESTOS-ST2-7/7/09	030917025-0002	Southeast Area (sidewalk bridge level)	7/7/09	1	3.080	Asbestos	PCME	EMSL	7/8/09	< 0.00080	No	No	
ASBESTOS-ST4-7/7/09	030917025-0003	Northwest Area (street-level)	7/7/09	1	3.030	Asbestos	PCME	EMSL	7/8/09	< 0.00081	No	No	
ASBESTOS-ST5-7/7/09	030917025-0004	Firehouse #10 (roof level)	7/7/09	1	3.030	Asbestos	PCME	EMSL	7/8/09	< 0.00081	No	No	
ASBESTOS-ST10-7/7/09	030917025-0005	North Side Sidewalk Bridge	7/7/09	1	3.080	Asbestos	PCME	EMSL	7/8/09	< 0.00080	No	No	
ASBESTOS-ST11-7/7/09	030917025-0006	90 Trinity Place (roof level)	7/7/09	1	3.030	Asbestos	PCME	EMSL	7/8/09	< 0.00081	No	No	
ASBESTOS-ST12-7/7/09	030917025-0007	110 Greenwich Street (roof level)	7/7/09	1	3.010	Asbestos	PCME	EMSL	7/8/09	< 0.00082	No	No	
ASBESTOS-ST13-7/7/09	030917025-0008	Marriott Hotel, 38th Floor (roof level)	7/7/09	1	3.000	Asbestos	PCME	EMSL	7/8/09	< 0.00082	No	No	
ASBESTOS-ST1-7/8/09	030917150-0001	Southwest Area (sidewalk bridge level)	7/8/09	1	3.090	Asbestos	PCME	EMSL	7/9/09	< 0.00080	No	No	
ASBESTOS-ST2-7/8/09	030917150-0002	Southeast Area (sidewalk bridge level)	7/8/09	1	3.070	Asbestos	PCME	EMSL	7/9/09	< 0.00080	No	No	
ASBESTOS-ST4-7/8/09	030917150-0003	Northwest Area (street-level)	7/8/09	1	3.240	Asbestos	PCME	EMSL	7/9/09	< 0.00076	No	No	
ASBESTOS-ST5-7/8/09	030917150-0004	Firehouse #10 (roof level)	7/8/09	1	3.120	Asbestos	PCME	EMSL	7/9/09	< 0.00079	No	No	
ASBESTOS-ST10-7/8/09	030917150-0005	North Side Sidewalk Bridge	7/8/09	1	3.010	Asbestos	PCME	EMSL	7/9/09	< 0.00082	No	No	
ASBESTOS-ST11-7/8/09	030917150-0006	90 Trinity Place (roof level)	7/8/09	1	3.020	Asbestos	PCME	EMSL	7/9/09	< 0.00082	No	No	
ASBESTOS-ST12-7/8/09	030917150-0007	110 Greenwich Street (roof level)	7/8/09	1	3.010	Asbestos	PCME	EMSL	7/9/09	< 0.00082	No	No	
ASBESTOS-ST13-7/8/09	030917150-0008	Marriott Hotel, 38th Floor (roof level)	7/8/09	1	2.990	Asbestos	PCME	EMSL	7/9/09	< 0.00083	No	No	
ASBESTOS-ST1-7/9/09	030917293-0001	Southwest Area (sidewalk bridge level)	7/9/09	1	2.960	Asbestos	PCME	EMSL	7/10/09	< 0.00083	No	No	
ASBESTOS-ST2-7/9/09	030917293-0002	Southeast Area (sidewalk bridge level)	7/9/09	1	3.050	Asbestos	PCME	EMSL	7/10/09	< 0.00081	No	No	
ASBESTOS-ST4-7/9/09	030917293-0003	Northwest Area (street-level)	7/9/09	1	3.100	Asbestos	PCME	EMSL	7/10/09	< 0.00080	No	No	
ASBESTOS-ST5-7/9/09	030917293-0004	Firehouse #10 (roof level)	7/9/09	1	3.100	Asbestos	PCME	EMSL	7/10/09	< 0.00080	No	No	
ASBESTOS-ST10-7/9/09	030917293-0005	North Side Sidewalk Bridge	7/9/09	1	3.010	Asbestos	PCME	EMSL	7/10/09	< 0.00082	No	No	
ASBESTOS-ST100-7/9/09	030917293-0009	Station 10 Field Duplicate	7/9/09	1	2.910	Asbestos	PCME	EMSL	7/10/09	< 0.00085	No	No	
ASBESTOS-ST11-7/9/09	030917293-0006	90 Trinity Place (roof level)	7/9/09	1	3.030	Asbestos	PCME	EMSL	7/10/09	< 0.00081	No	No	
ASBESTOS-ST12-7/9/09	030917293-0007	110 Greenwich Street (roof level)	7/9/09	1	3.040	Asbestos	PCME	EMSL	7/10/09	< 0.00081	No	No	
ASBESTOS-ST13-7/9/09	030917293-0008	Marriott Hotel, 38th Floor (roof level)	7/9/09	1	3.070	Asbestos	PCME	EMSL	7/10/09	< 0.00080	No	No	
ASBESTOS-ST1-7/10/09	030917353-0001	Southwest Area (sidewalk bridge level)	7/10/09	1	3.030	Asbestos	PCME	EMSL	7/11/09	< 0.00081	No	No	
ASBESTOS-ST2-7/10/09	030917353-0002	Southeast Area (sidewalk bridge level)	7/10/09	1	2.950	Asbestos	PCME	EMSL	7/11/09	< 0.00084	No	No	
ASBESTOS-ST4-7/10/09	030917353-0003	Northwest Area (street-level)	7/10/09	1	3.060	Asbestos	PCME	EMSL	7/11/09	< 0.00081	No	No	
ASBESTOS-ST5-7/10/09	030917353-0004	Firehouse #10 (roof level)	7/10/09	1	3.080	Asbestos	PCME	EMSL	7/11/09	< 0.00080	No	No	
ASBESTOS-ST10-7/10/09	030917353-0005	North Side Sidewalk Bridge	7/10/09	1	2.980	Asbestos	PCME	EMSL	7/11/09	< 0.00083	No	No	
ASBESTOS-ST11-7/10/09	030917353-0006	90 Trinity Place (roof level)	7/10/09	1	3.020	Asbestos	PCME	EMSL	7/11/09	< 0.00082	No	No	
ASBESTOS-ST12-7/10/09	030917353-0007	110 Greenwich Street (roof level)	7/10/09	1	2.950	Asbestos	PCME	EMSL	7/11/09	< 0.00084	No	No	
ASBESTOS-ST13-7/10/09	030917353-0008	Marriott Hotel, 38th Floor (roof level)	7/10/09	1	3.030	Asbestos	PCME	EMSL	7/11/09	< 0.00081	No	No	