

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality	Exceeds EPA	
EPA Site Specific Trigger Levels										NA	Levels	Site Specific	Trigger Levels
ASBESTOS-ST1-7/07/06	030621038-0001	Southwest Area (sidewalk bridge level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST2-7/07/06	030621038-0002	Southeast Area (sidewalk bridge level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST4-7/07/06	030621038-0003	Northwest Area (street-level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST5-7/07/06	030621038-0004	Firehouse #10 (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST6-7/7/06	030621041-0001	Southwest Area (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST7-7/7/06	030621041-0002	Southeast Area (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST8-7/7/06	030621041-0003	Northeast Area (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST9-7/7/06	030621041-0004	Northwest Area (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST10-7/07/06	030621038-0005	North Side Sidewalk Bridge	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST11-7/07/06	030621038-0006	90 Trinity Place (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST12-7/07/06	030621038-0007	110 Greenwich Street (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST13-7/07/06	030621038-0008	Marriott Hotel, 38th Floor (roof level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST14-7/07/06	030621038-0009	West Face - South end at corner (scaffolding level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST15-7/07/06	030621038-0010	South Face - East end at corner (scaffolding level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST16-7/07/06	030621038-0011	East Face - North end at corner (scaffolding level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST17-7/07/06	030621038-0012	North Face - West end at corner (scaffolding level)	7/7/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST1-7/8/06	030621037-0001	Southwest Area (sidewalk bridge level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST2-7/8/06	030621037-0002	Southeast Area (sidewalk bridge level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST4-7/8/06	030621037-0003	Northwest Area (street-level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST5-7/8/06	030621037-0004	Firehouse #10 (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST6-7/8/06	030621039-0001	Southwest Area (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST7-7/8/06	030621039-0002	Southeast Area (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST8-7/8/06	030621039-0003	Northeast Area (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST9-7/8/06	030621039-0004	Northwest Area (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST10-7/8/06	030621037-0005	North Side Sidewalk Bridge	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST11-7/8/06	030621037-0006	90 Trinity Place (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST12-7/8/06	030621037-0007	110 Greenwich Street (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST13-7/8/06	030621037-0008	Marriott Hotel, 38th Floor (roof level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST14-7/8/06	030621037-0009	West Face - South end at corner (scaffolding level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST15-7/8/06	030621037-0010	South Face - East end at corner (scaffolding level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST16-7/8/06	030621037-0011	East Face - North end at corner (scaffolding level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST17-7/8/06	030621037-0012	North Face - West end at corner (scaffolding level)	7/8/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST1-7/09/06	030621036-0001	Southwest Area (sidewalk bridge level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST2-7/09/06	030621036-0002	Southeast Area (sidewalk bridge level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST4-7/09/06	030621036-0003	Northwest Area (street-level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST5-7/09/06	030621036-0004	Firehouse #10 (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST6-7/9/06	030621042-0001	Southwest Area (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST7-7/9/06	030621042-0002	Southeast Area (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST8-7/9/06	030621042-0003	Northeast Area (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST9-7/9/06	030621042-0004	Northwest Area (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST10-7/09/06	030621036-0005	North Side Sidewalk Bridge	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST11-7/09/06	030621036-0006	90 Trinity Place (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST12-7/09/06	030621036-0007	110 Greenwich Street (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST13-7/09/06	030621036-0008	Marriott Hotel, 38th Floor (roof level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST14-7/09/06	030621036-0009	West Face - South end at corner (scaffolding level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST15-7/09/06	030621036-0010	South Face - East end at corner (scaffolding level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST16-7/09/06	030621036-0011	East Face - North end at corner (scaffolding level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	
ASBESTOS-ST17-7/09/06	030621036-0012	North Face - West end at corner (scaffolding level)	7/9/06	1	2.940	Asbestos	PCME	EMSL	7/10/06	< 0.00084	No	No	