

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-7/13/07	030723239-0001	Southwest Area (sidewalk bridge level)	7/13/07	1	3.070	Asbestos	PCME	EMSL	7/14/07	< 0.00080	No	No	
ASBESTOS-ST2-7/13/07	030723239-0002	Southeast Area (sidewalk bridge level)	7/13/07	1	3.020	Asbestos	PCME	EMSL	7/14/07	< 0.00082	No	No	
ASBESTOS-ST4-7/13/07	030723239-0003	Northwest Area (street-level)	7/13/07	1	2.940	Asbestos	PCME	EMSL	7/14/07	< 0.00084	No	No	
ASBESTOS-ST5-7/13/07	030723239-0004	Firehouse #10 (roof level)	7/13/07	1	3.040	Asbestos	PCME	EMSL	7/14/07	< 0.00081	No	No	
ASBESTOS-ST10-7/13/07	030723239-0005	North Side Sidewalk Bridge	7/13/07	1	2.960	Asbestos	PCME	EMSL	7/14/07	< 0.00083	No	No	
ASBESTOS-ST100-7/13/07	030723239-0013	Station 10 Field Duplicate	7/13/07	1	3.150	Asbestos	PCME	EMSL	7/14/07	< 0.00078	No	No	
ASBESTOS-ST11-7/13/07	030723239-0006	90 Trinity Place (roof level)	7/13/07	1	3.040	Asbestos	PCME	EMSL	7/14/07	< 0.00081	No	No	
ASBESTOS-ST12-7/13/07	030723239-0007	110 Greenwich Street (roof level)	7/13/07	1	3.150	Asbestos	PCME	EMSL	7/14/07	< 0.00078	No	No	
ASBESTOS-ST13-7/13/07	030723239-0008	Marriott Hotel, 38th Floor (roof level)	7/13/07	1	3.040	Asbestos	PCME	EMSL	7/14/07	< 0.00081	No	No	
ASBESTOS-ST14-7/13/07	030723239-0009	West Face - South end at corner (scaffolding level)	7/13/07	1	3.090	Asbestos	PCME	EMSL	7/14/07	0.00080	No	No	
ASBESTOS-ST15-7/13/07	030723239-0010	South Face - East end at corner (scaffolding level)	7/13/07	1	3.050	Asbestos	PCME	EMSL	7/14/07	< 0.00081	No	No	
ASBESTOS-ST16-7/13/07	030723239-0011	East Face - North end at corner (scaffolding level)	7/13/07	1	3.060	Asbestos	PCME	EMSL	7/14/07	< 0.00081	No	No	
ASBESTOS-ST17-7/13/07	030723239-0012	North Face - West end at corner (scaffolding level)	7/13/07	1	2.960	Asbestos	PCME	EMSL	7/14/07	< 0.00083	No	No	
ASBESTOS-ST1-7/14/07	030723413-0001	Southwest Area (sidewalk bridge level)	7/14/07	1	3.150	Asbestos	PCME	EMSL	7/16/07	< 0.00078	No	No	
ASBESTOS-ST2-7/14/07	030723413-0002	Southeast Area (sidewalk bridge level)	7/14/07	1	3.040	Asbestos	PCME	EMSL	7/16/07	< 0.00081	No	No	
ASBESTOS-ST5-7/14/07	030723413-0003	Firehouse #10 (roof level)	7/14/07	1	3.040	Asbestos	PCME	EMSL	7/16/07	< 0.00081	No	No	
ASBESTOS-ST10-7/14/07	030723413-0004	North Side Sidewalk Bridge	7/14/07	1	2.950	Asbestos	PCME	EMSL	7/16/07	< 0.00084	No	No	
ASBESTOS-ST11-7/14/07	030723413-0005	90 Trinity Place (roof level)	7/14/07	1	2.900	Asbestos	PCME	EMSL	7/16/07	< 0.00085	No	No	
ASBESTOS-ST12-7/14/07	030723413-0006	110 Greenwich Street (roof level)	7/14/07	1	2.970	Asbestos	PCME	EMSL	7/16/07	< 0.00083	No	No	
ASBESTOS-ST13-7/14/07	030723413-0007	Marriott Hotel, 38th Floor (roof level)	7/14/07	1	3.010	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST14-7/14/07	030723413-0008	West Face - South end at corner (scaffolding level)	7/14/07	1	2.960	Asbestos	PCME	EMSL	7/16/07	< 0.00083	No	No	
ASBESTOS-ST15-7/14/07	030723413-0009	South Face - East end at corner (scaffolding level)	7/14/07	1	3.020	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST16-7/14/07	030723413-0010	East Face - North end at corner (scaffolding level)	7/14/07	1	3.010	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST17-7/14/07	030723413-0011	North Face - West end at corner (scaffolding level)	7/14/07	1	2.370	Asbestos	PCME	EMSL	7/16/07	< 0.00089	No	No	
ASBESTOS-ST1-7/15/07	030723415-0001	Southwest Area (sidewalk bridge level)	7/15/07	1	3.060	Asbestos	PCME	EMSL	7/16/07	< 0.00081	No	No	
ASBESTOS-ST2-7/15/07	030723415-0002	Southeast Area (sidewalk bridge level)	7/15/07	1	3.100	Asbestos	PCME	EMSL	7/16/07	< 0.00080	No	No	
ASBESTOS-ST5-7/15/07	030723415-0003	Firehouse #10 (roof level)	7/15/07	1	2.900	Asbestos	PCME	EMSL	7/16/07	< 0.00085	No	No	
ASBESTOS-ST10-7/15/07	030723415-0004	North Side Sidewalk Bridge	7/15/07	1	3.090	Asbestos	PCME	EMSL	7/16/07	< 0.00080	No	No	
ASBESTOS-ST11-7/15/07	030723415-0005	90 Trinity Place (roof level)	7/15/07	1	3.120	Asbestos	PCME	EMSL	7/16/07	< 0.00079	No	No	
ASBESTOS-ST13-7/15/07	030723415-0006	Marriott Hotel, 38th Floor (roof level)	7/15/07	1	3.010	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST14-7/15/07	030723415-0007	West Face - South end at corner (scaffolding level)	7/15/07	1	3.050	Asbestos	PCME	EMSL	7/16/07	< 0.00081	No	No	
ASBESTOS-ST15-7/15/07	030723415-0008	South Face - East end at corner (scaffolding level)	7/15/07	1	3.020	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST16-7/15/07	030723415-0009	East Face - North end at corner (scaffolding level)	7/15/07	1	3.020	Asbestos	PCME	EMSL	7/16/07	< 0.00082	No	No	
ASBESTOS-ST17-7/15/07	030723415-0010	North Face - West end at corner (scaffolding level)	7/15/07	1	3.230	Asbestos	PCME	EMSL	7/16/07	< 0.00076	No	No	

Note:

1. Asbestos samples at Station 4 (Northwest Area [street-level]) on July 14 and 15, 2007 were not available for analysis on account of power failure.
2. Asbestos sample at Station 12 (110 Greenwich Street (roof level)) on July 15, 2007 was not available for analysis. The station was not accessible and the sample could not be collected.