

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										<b>NA</b>			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-7/14/09	030917844-0001	Southwest Area (sidewalk bridge level)	7/14/09	1	3.040	Asbestos	PCME	EMSL	7/15/09	< 0.00081	No	No	
ASBESTOS-ST2-7/14/09	030917844-0002	Southeast Area (sidewalk bridge level)	7/14/09	1	3.070	Asbestos	PCME	EMSL	7/15/09	< 0.00080	No	No	
ASBESTOS-ST4-7/14/09	030917844-0003	Northwest Area (street-level)	7/14/09	1	3.070	Asbestos	PCME	EMSL	7/15/09	< 0.00080	No	No	
ASBESTOS-ST5-7/14/09	030917844-0004	Firehouse #10 (roof level)	7/14/09	1	3.010	Asbestos	PCME	EMSL	7/15/09	< 0.00082	No	No	
ASBESTOS-ST10-7/14/09	030917844-0005	North Side Sidewalk Bridge	7/14/09	1	3.100	Asbestos	PCME	EMSL	7/15/09	< 0.00080	No	No	
ASBESTOS-ST11-7/14/09	030917844-0006	90 Trinity Place (roof level)	7/14/09	1	2.980	Asbestos	PCME	EMSL	7/15/09	< 0.00083	No	No	
ASBESTOS-ST12-7/14/09	030917844-0007	110 Greenwich Street (roof level)	7/14/09	1	3.110	Asbestos	PCME	EMSL	7/15/09	< 0.00079	No	No	
ASBESTOS-ST13-7/14/09	030917844-0008	Marriott Hotel, 38th Floor (roof level)	7/14/09	1	3.030	Asbestos	PCME	EMSL	7/15/09	< 0.00081	No	No	
ASBESTOS-ST1-7/15/09	030918053-0001	Southwest Area (sidewalk bridge level)	7/15/09	1	3.050	Asbestos	PCME	EMSL	7/16/09	< 0.00081	No	No	
ASBESTOS-ST2-7/15/09	030918053-0002	Southeast Area (sidewalk bridge level)	7/15/09	1	3.020	Asbestos	PCME	EMSL	7/16/09	< 0.00082	No	No	
ASBESTOS-ST4-7/15/09	030918053-0003	Northwest Area (street-level)	7/15/09	1	3.000	Asbestos	PCME	EMSL	7/16/09	< 0.00082	No	No	
ASBESTOS-ST5-7/15/09	030918053-0004	Firehouse #10 (roof level)	7/15/09	1	3.070	Asbestos	PCME	EMSL	7/16/09	< 0.00080	No	No	
ASBESTOS-ST10-7/15/09	030918053-0005	North Side Sidewalk Bridge	7/15/09	1	3.000	Asbestos	PCME	EMSL	7/16/09	< 0.00082	No	No	
ASBESTOS-ST11-7/15/09	030918053-0006	90 Trinity Place (roof level)	7/15/09	1	3.020	Asbestos	PCME	EMSL	7/16/09	< 0.00082	No	No	
ASBESTOS-ST12-7/15/09	030918053-0007	110 Greenwich Street (roof level)	7/15/09	1	2.990	Asbestos	PCME	EMSL	7/16/09	< 0.00083	No	No	
ASBESTOS-ST13-7/15/09	030918053-0008	Marriott Hotel, 38th Floor (roof level)	7/15/09	1	3.050	Asbestos	PCME	EMSL	7/16/09	< 0.00081	No	No	
ASBESTOS-ST1-7/16/09	030918179-0001	Southwest Area (sidewalk bridge level)	7/16/09	1	3.080	Asbestos	PCME	EMSL	7/17/09	< 0.00087	No	No	
ASBESTOS-ST2-7/16/09	030918179-0002	Southeast Area (sidewalk bridge level)	7/16/09	1	2.910	Asbestos	PCME	EMSL	7/17/09	< 0.00085	No	No	
ASBESTOS-ST4-7/16/09	030918179-0003	Northwest Area (street-level)	7/16/09	1	3.060	Asbestos	PCME	EMSL	7/17/09	< 0.00081	No	No	
ASBESTOS-ST5-7/16/09	030918179-0004	Firehouse #10 (roof level)	7/16/09	1	2.940	Asbestos	PCME	EMSL	7/17/09	< 0.00084	No	No	
ASBESTOS-ST10-7/16/09	030918179-0005	North Side Sidewalk Bridge	7/16/09	1	3.180	Asbestos	PCME	EMSL	7/17/09	< 0.00085	No	No	
ASBESTOS-ST11-7/16/09	030918179-0006	90 Trinity Place (roof level)	7/16/09	1	3.050	Asbestos	PCME	EMSL	7/17/09	< 0.00081	No	No	
ASBESTOS-ST12-7/16/09	030918179-0007	110 Greenwich Street (roof level)	7/16/09	1	3.080	Asbestos	PCME	EMSL	7/17/09	< 0.00087	No	No	
ASBESTOS-ST13-7/16/09	030918179-0008	Marriott Hotel, 38th Floor (roof level)	7/16/09	1	3.080	Asbestos	PCME	EMSL	7/17/09	< 0.00087	No	No	
ASBESTOS-ST1-7/17/09	030918242-0001	Southwest Area (sidewalk bridge level)	7/17/09	1	3.040	Asbestos	PCME	EMSL	7/18/09	< 0.00081	No	No	
ASBESTOS-ST2-7/17/09	030918242-0002	Southeast Area (sidewalk bridge level)	7/17/09	1	2.990	Asbestos	PCME	EMSL	7/18/09	< 0.00083	No	No	
ASBESTOS-ST4-7/17/09	030918242-0003	Northwest Area (street-level)	7/17/09	1	3.010	Asbestos	PCME	EMSL	7/18/09	< 0.00082	No	No	
ASBESTOS-ST5-7/17/09	030918242-0004	Firehouse #10 (roof level)	7/17/09	1	3.070	Asbestos	PCME	EMSL	7/18/09	< 0.00080	No	No	
ASBESTOS-ST10-7/17/09	030918242-0005	North Side Sidewalk Bridge	7/17/09	1	2.910	Asbestos	PCME	EMSL	7/18/09	< 0.00085	No	No	
ASBESTOS-ST100-7/17/09	030918242-0009	Station 10 Field Duplicate	7/17/09	1	2.960	Asbestos	PCME	EMSL	7/18/09	< 0.00083	No	No	
ASBESTOS-ST11-7/17/09	030918242-0006	90 Trinity Place (roof level)	7/17/09	1	3.000	Asbestos	PCME	EMSL	7/18/09	< 0.00082	No	No	
ASBESTOS-ST12-7/17/09	030918242-0007	110 Greenwich Street (roof level)	7/17/09	1	3.040	Asbestos	PCME	EMSL	7/18/09	< 0.00081	No	No	
ASBESTOS-ST13-7/17/09	030918242-0008	Marriott Hotel, 38th Floor (roof level)	7/17/09	1	3.010	Asbestos	PCME	EMSL	7/18/09	< 0.00082	No	No	