

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-7/29/09	030919552-0001	Southwest Area (sidewalk bridge level)	7/29/09	1	3.230	Asbestos	PCME	EMSL	7/30/09	< 0.00083	No	No	
ASBESTOS-ST2-7/29/09	030919552-0002	Southeast Area (sidewalk bridge level)	7/29/09	1	3.050	Asbestos	PCME	EMSL	7/30/09	< 0.00081	No	No	
ASBESTOS-ST4-7/29/09	030919552-0003	Northwest Area (street-level)	7/29/09	1	3.020	Asbestos	PCME	EMSL	7/30/09	< 0.00082	No	No	
ASBESTOS-ST5-7/29/09	030919552-0004	Firehouse #10 (roof level)	7/29/09	1	3.030	Asbestos	PCME	EMSL	7/30/09	< 0.00081	No	No	
ASBESTOS-ST10-7/29/09	030919552-0005	North Side Sidewalk Bridge	7/29/09	1	3.050	Asbestos	PCME	EMSL	7/30/09	< 0.00081	No	No	
ASBESTOS-ST11-7/29/09	030919552-0006	90 Trinity Place (roof level)	7/29/09	1	3.010	Asbestos	PCME	EMSL	7/30/09	< 0.00082	No	No	
ASBESTOS-ST12-7/29/09	030919552-0007	110 Greenwich Street (roof level)	7/29/09	1	3.010	Asbestos	PCME	EMSL	7/30/09	< 0.00082	No	No	
ASBESTOS-ST13-7/29/09	030919552-0008	Marriott Hotel, 38th Floor (roof level)	7/29/09	1	3.070	Asbestos	PCME	EMSL	7/30/09	< 0.00080	No	No	
ASBESTOS-ST1-7/30/09	030919678-0001	Southwest Area (sidewalk bridge level)	7/30/09	1	3.030	Asbestos	PCME	EMSL	7/31/09	< 0.00081	No	No	
ASBESTOS-ST2-7/30/09	030919678-0002	Southeast Area (sidewalk bridge level)	7/30/09	1	3.020	Asbestos	PCME	EMSL	7/31/09	< 0.00082	No	No	
ASBESTOS-ST4-7/30/09	030919678-0003	Northwest Area (street-level)	7/30/09	1	3.060	Asbestos	PCME	EMSL	7/31/09	< 0.00081	No	No	
ASBESTOS-ST5-7/30/09	030919678-0004	Firehouse #10 (roof level)	7/30/09	1	3.000	Asbestos	PCME	EMSL	7/31/09	< 0.00082	No	No	
ASBESTOS-ST10-7/30/09	030919678-0005	North Side Sidewalk Bridge	7/30/09	1	3.020	Asbestos	PCME	EMSL	7/31/09	< 0.00082	No	No	
ASBESTOS-ST11-7/30/09	030919678-0006	90 Trinity Place (roof level)	7/30/09	1	3.020	Asbestos	PCME	EMSL	7/31/09	< 0.00082	No	No	
ASBESTOS-ST12-7/30/09	030919678-0007	110 Greenwich Street (roof level)	7/30/09	1	3.040	Asbestos	PCME	EMSL	7/31/09	< 0.00081	No	No	
ASBESTOS-ST13-7/30/09	030919678-0008	Marriott Hotel, 38th Floor (roof level)	7/30/09	1	3.040	Asbestos	PCME	EMSL	7/31/09	< 0.00081	No	No	
ASBESTOS-ST1-7/31/09	030919776-0001	Southwest Area (sidewalk bridge level)	7/31/09	1	2.980	Asbestos	PCME	EMSL	8/1/09	< 0.00083	No	No	
ASBESTOS-ST2-7/31/09	030919776-0002	Southeast Area (sidewalk bridge level)	7/31/09	1	2.960	Asbestos	PCME	EMSL	8/1/09	< 0.00083	No	No	
ASBESTOS-ST4-7/31/09	030919776-0003	Northwest Area (street-level)	7/31/09	1	3.020	Asbestos	PCME	EMSL	8/1/09	< 0.00082	No	No	
ASBESTOS-ST5-7/31/09	030919776-0004	Firehouse #10 (roof level)	7/31/09	1	3.010	Asbestos	PCME	EMSL	8/1/09	< 0.00082	No	No	
ASBESTOS-ST10-7/31/09	030919776-0005	North Side Sidewalk Bridge	7/31/09	1	3.060	Asbestos	PCME	EMSL	8/1/09	< 0.00081	No	No	
ASBESTOS-ST11-7/31/09	030919776-0006	90 Trinity Place (roof level)	7/31/09	1	3.010	Asbestos	PCME	EMSL	8/1/09	< 0.00082	No	No	
ASBESTOS-ST12-7/31/09	030919776-0007	110 Greenwich Street (roof level)	7/31/09	1	3.030	Asbestos	PCME	EMSL	8/1/09	< 0.00081	No	No	
ASBESTOS-ST13-7/31/09	030919776-0008	Marriott Hotel, 38th Floor (roof level)	7/31/09	1	2.960	Asbestos	PCME	EMSL	8/1/09	< 0.00083	No	No	