

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-7/31/06	030624362-0001	Southwest Area (sidewalk bridge level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST2-7/31/06	030624362-0002	Southeast Area (sidewalk bridge level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST4-7/31/06	030624362-0003	Northwest Area (street-level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST5-7/31/06	030624362-0004	Firehouse #10 (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST7-7/31/06	030624363-0001	Southeast Area (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST8-7/31/06	030624363-0002	Northeast Area (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST9-7/3/06	030624363-0003	Northwest Area (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST10-7/31/06	030624362-0005	North Side Sidewalk Bridge	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST100-7/31/06	030624362-0013	Station 10 Field Duplicate	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST11-7/31/06	030624362-0006	90 Trinity Place (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST12-7/31/06	030624362-0007	110 Greenwich Street (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST13-7/31/06	030624362-0008	Marriott Hotel, 38th Floor (roof level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST14-7/31/06	030624362-0009	West Face - South end at corner (scaffolding level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST15-7/31/06	030624362-0010	South Face - East end at corner (scaffolding level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST16-7/31/06	030624362-0011	East Face - North end at corner (scaffolding level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST17-7/31/06	030624362-0012	North Face - West end at corner (scaffolding level)	7/31/06	1	2.970	Asbestos	PCME	EMSL	8/1/06	< 0.00083	No	No	
ASBESTOS-ST1-8/1/06	030624558-0001	Southwest Area (sidewalk bridge level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST2-8/1/06	030624558-0002	Southeast Area (sidewalk bridge level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST4-8/1/06	030624558-0003	Northwest Area (street-level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST5-8/1/06	030624558-0004	Firehouse #10 (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST6-8/1/06	030624559-0001	Southwest Area (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST7-8/1/06	030624559-0002	Southeast Area (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST8-8/1/06	030624559-0003	Northeast Area (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST9-8/1/06	030624559-0004	Northwest Area (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST10-8/1/06	030624558-0005	North Side Sidewalk Bridge	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST11-8/1/06	030624558-0006	90 Trinity Place (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST12-8/1/06	030624558-0007	110 Greenwich Street (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST13-8/1/06	030624558-0008	Marriott Hotel, 38th Floor (roof level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST14-8/1/06	030624558-0009	West Face - South end at corner (scaffolding level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST15-8/1/06	030624558-0010	South Face - East end at corner (scaffolding level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST16-8/1/06	030624558-0011	East Face - North end at corner (scaffolding level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST17-8/1/06	030624558-0012	North Face - West end at corner (scaffolding level)	8/1/06	1	2.970	Asbestos	PCME	EMSL	8/2/06	< 0.00083	No	No	
ASBESTOS-ST1-8/2/06	030624728-0001	Southwest Area (sidewalk bridge level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST2-8/2/06	030624728-0002	Southeast Area (sidewalk bridge level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST4-8/2/06	030624728-0003	Northwest Area (street-level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST5-8/2/06	030624728-0004	Firehouse #10 (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST7-8/2/06	030624729-0001	Southeast Area (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST8-8/2/06	030624729-0002	Northeast Area (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST9-8/2/06	030624729-0003	Northwest Area (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST10-8/2/06	030624728-0005	North Side Sidewalk Bridge	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST11-8/2/06	030624728-0006	90 Trinity Place (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST12-8/2/06	030624728-0007	110 Greenwich Street (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST13-8/2/06	030624728-0008	Marriott Hotel, 38th Floor (roof level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST14-8/2/06	030624728-0009	West Face - South end at corner (scaffolding level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST15-8/2/06	030624728-0010	South Face - East end at corner (scaffolding level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST16-8/2/06	030624728-0011	East Face - North end at corner (scaffolding level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	
ASBESTOS-ST17-8/2/06	030624728-0012	North Face - West end at corner (scaffolding level)	8/2/06	1	2.970	Asbestos	PCME	EMSL	8/3/06	< 0.00083	No	No	

Note:

- Asbestos samples at Station 6 (Southwest Area [roof level]) on July 31, 2006 and August 2, 2006 were not available for analysis on account of instrument malfunction.