

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-8/19/09	030921677-0001	Southwest Area (sidewalk bridge level)	8/19/09	1	3.090	Asbestos	PCME	EMSL	8/20/09	< 0.00080	No	No	
ASBESTOS-ST2-8/19/09	030921677-0002	Southeast Area (sidewalk bridge level)	8/19/09	1	3.100	Asbestos	PCME	EMSL	8/20/09	< 0.00080	No	No	
ASBESTOS-ST4-8/19/09	030921677-0003	Northwest Area (street-level)	8/19/09	1	3.060	Asbestos	PCME	EMSL	8/20/09	< 0.00081	No	No	
ASBESTOS-ST5-8/19/09	030921677-0004	Firehouse #10 (roof level)	8/19/09	1	3.040	Asbestos	PCME	EMSL	8/20/09	< 0.00081	No	No	
ASBESTOS-ST10-8/19/09	030921677-0005	North Side Sidewalk Bridge	8/19/09	1	3.130	Asbestos	PCME	EMSL	8/20/09	< 0.00079	No	No	
ASBESTOS-ST11-8/19/09	030921677-0006	90 Trinity Place (roof level)	8/19/09	1	3.140	Asbestos	PCME	EMSL	8/20/09	< 0.00079	No	No	
ASBESTOS-ST12-8/19/09	030921677-0007	110 Greenwich Street (roof level)	8/19/09	1	3.070	Asbestos	PCME	EMSL	8/20/09	< 0.00080	No	No	
ASBESTOS-ST13-8/19/09	030921677-0008	Marriott Hotel, 38th Floor (roof level)	8/19/09	1	3.100	Asbestos	PCME	EMSL	8/20/09	< 0.00080	No	No	
ASBESTOS-ST1-8/20/09	030921780-0001	Southwest Area (sidewalk bridge level)	8/20/09	1	2.980	Asbestos	PCME	EMSL	8/21/09	< 0.00083	No	No	
ASBESTOS-ST2-8/20/09	030921780-0002	Southeast Area (sidewalk bridge level)	8/20/09	1	2.920	Asbestos	PCME	EMSL	8/21/09	< 0.00085	No	No	
ASBESTOS-ST4-8/20/09	030921780-0003	Northwest Area (street-level)	8/20/09	1	2.940	Asbestos	PCME	EMSL	8/21/09	< 0.00084	No	No	
ASBESTOS-ST5-8/20/09	030921780-0004	Firehouse #10 (roof level)	8/20/09	1	2.890	Asbestos	PCME	EMSL	8/21/09	< 0.00085	No	No	
ASBESTOS-ST10-8/20/09	030921780-0005	North Side Sidewalk Bridge	8/20/09	1	3.010	Asbestos	PCME	EMSL	8/21/09	< 0.00082	No	No	
ASBESTOS-ST100-8/20/09	030921780-0009	Station 10 Field Duplicate	8/20/09	1	2.980	Asbestos	PCME	EMSL	8/21/09	< 0.00083	No	No	
ASBESTOS-ST11-8/20/09	030921780-0006	90 Trinity Place (roof level)	8/20/09	1	3.010	Asbestos	PCME	EMSL	8/21/09	< 0.00082	No	No	
ASBESTOS-ST12-8/20/09	030921780-0007	110 Greenwich Street (roof level)	8/20/09	1	2.990	Asbestos	PCME	EMSL	8/21/09	< 0.00083	No	No	
ASBESTOS-ST13-8/20/09	030921780-0008	Marriott Hotel, 38th Floor (roof level)	8/20/09	1	3.060	Asbestos	PCME	EMSL	8/21/09	< 0.00081	No	No	
ASBESTOS-ST1-8/21/09	030921838-0001	Southwest Area (sidewalk bridge level)	8/21/09	1	3.050	Asbestos	PCME	EMSL	8/22/09	< 0.00081	No	No	
ASBESTOS-ST2-8/21/09	030921838-0002	Southeast Area (sidewalk bridge level)	8/21/09	1	2.980	Asbestos	PCME	EMSL	8/22/09	< 0.00083	No	No	
ASBESTOS-ST4-8/21/09	030921838-0003	Northwest Area (street-level)	8/21/09	1	3.000	Asbestos	PCME	EMSL	8/22/09	< 0.00082	No	No	
ASBESTOS-ST5-8/21/09	030921838-0004	Firehouse #10 (roof level)	8/21/09	1	3.100	Asbestos	PCME	EMSL	8/22/09	< 0.00080	No	No	
ASBESTOS-ST10-8/21/09	030921838-0005	North Side Sidewalk Bridge	8/21/09	1	3.000	Asbestos	PCME	EMSL	8/22/09	< 0.00082	No	No	
ASBESTOS-ST11-8/21/09	030921838-0006	90 Trinity Place (roof level)	8/21/09	1	3.020	Asbestos	PCME	EMSL	8/22/09	< 0.00082	No	No	
ASBESTOS-ST12-8/21/09	030921838-0007	110 Greenwich Street (roof level)	8/21/09	1	3.030	Asbestos	PCME	EMSL	8/22/09	< 0.00081	No	No	
ASBESTOS-ST13-8/21/09	030921838-0008	Marriott Hotel, 38th Floor (roof level)	8/21/09	1	2.990	Asbestos	PCME	EMSL	8/22/09	< 0.00083	No	No	