

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-8/21/06	030627337-0001	Southwest Area (sidewalk bridge level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST2-8/21/06	030627337-0002	Southeast Area (sidewalk bridge level)	8/21/06	1	3.060	Asbestos	PCME	EMSL	8/22/06	< 0.00081	No	No	
ASBESTOS-ST4-8/21/06	030627337-0003	Northwest Area (street-level)	8/21/06	1	3.060	Asbestos	PCME	EMSL	8/22/06	< 0.00081	No	No	
ASBESTOS-ST6-8/21/06	0306272340-0001	Southwest Area (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST7-8/21/06	0306272340-0002	Southeast Area (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST8-8/21/06	0306272340-0003	Northeast Area (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST9-8/21/06	0306272340-0004	Northwest Area (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST10-8/21/06	030627337-0004	North Side Sidewalk Bridge	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST11-8/21/06	030627337-0005	90 Trinity Place (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST12-8/21/06	030627337-0006	110 Greenwich Street (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST13-8/21/06	030627337-0007	Marriott Hotel, 38th Floor (roof level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST14-8/21/06	030627337-0008	West Face - South end at corner (scaffolding level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST15-8/21/06	030627337-0009	South Face - East end at corner (scaffolding level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST16-8/21/06	030627337-0010	East Face - North end at corner (scaffolding level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST17-8/21/06	030627337-0011	North Face - West end at corner (scaffolding level)	8/21/06	1	2.970	Asbestos	PCME	EMSL	8/22/06	< 0.00083	No	No	
ASBESTOS-ST1-8/22/06	030627487-0001	Southwest Area (sidewalk bridge level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST2-8/22/06	030627487-0002	Southeast Area (sidewalk bridge level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST4-8/22/06	030627487-0003	Northwest Area (street-level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST5-8/22/06	030627487-0004	Firehouse #10 (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST6-8/22/06	030627488-0001	Southwest Area (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST7-8/22/06	030627488-0002	Southeast Area (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST8-8/22/06	030627488-0003	Northeast Area (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST9-8/22/06	030627488-0004	Northwest Area (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST10-8/22/06	030627487-0005	North Side Sidewalk Bridge	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST11-8/22/06	030627487-0006	90 Trinity Place (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST12-8/22/06	030627487-0007	110 Greenwich Street (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST13-8/22/06	030627487-0008	Marriott Hotel, 38th Floor (roof level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST14-8/22/06	030627487-0009	West Face - South end at corner (scaffolding level)	8/22/06	1	3.020	Asbestos	PCME	EMSL	8/23/06	< 0.00082	No	No	
ASBESTOS-ST15-8/22/06	030627487-0010	South Face - East end at corner (scaffolding level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST16-8/22/06	030627487-0011	East Face - North end at corner (scaffolding level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST17-8/22/06	030627487-0012	North Face - West end at corner (scaffolding level)	8/22/06	1	2.970	Asbestos	PCME	EMSL	8/23/06	< 0.00083	No	No	
ASBESTOS-ST1-8/23/06	030627650-0001	Southwest Area (sidewalk bridge level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST2-8/23/06	030627650-0002	Southeast Area (sidewalk bridge level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST4-8/23/06	030627650-0003	Northwest Area (street-level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST5-8/23/06	030627650-0004	Firehouse #10 (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST6-8/23/06	030627653-0001	Southwest Area (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST7-8/23/06	030627653-0002	Southeast Area (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST8-8/23/06	030627653-0003	Northeast Area (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST9-8/23/06	030627653-0004	Northwest Area (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST10-8/23/06	030627650-0005	North Side Sidewalk Bridge	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST11-8/23/06	030627650-0006	90 Trinity Place (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST12-8/23/06	030627650-0007	110 Greenwich Street (roof level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST13-8/23/06	030627650-0008	Marriott Hotel, 38th Floor (roof level)	8/23/06	1	2.888	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST14-8/23/06	030627650-0009	West Face - South end at corner (scaffolding level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST15-8/23/06	030627650-0010	South Face - East end at corner (scaffolding level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST16-8/23/06	030627650-0011	East Face - North end at corner (scaffolding level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	
ASBESTOS-ST17-8/23/06	030627650-0012	North Face - West end at corner (scaffolding level)	8/23/06	1	2.970	Asbestos	PCME	EMSL	8/24/06	< 0.00083	No	No	

Note:

- Asbestos sample at Station 5 (Firehouse #10 [roof level]) on August 21, 2006 was not available for analysis on account of pump failure.