

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-8/26/08	030829851-0001	Southwest Area (sidewalk bridge level)	8/26/08	1	3.010	Asbestos	PCME	EMSL	8/27/08	< 0.00082	No	No	
ASBESTOS-ST2-8/26/08	030829851-0002	Southeast Area (sidewalk bridge level)	8/26/08	1	3.070	Asbestos	PCME	EMSL	8/27/08	< 0.00080	No	No	
ASBESTOS-ST4-8/26/08	030829851-0003	Northwest Area (street-level)	8/26/08	1	2.940	Asbestos	PCME	EMSL	8/27/08	< 0.00084	No	No	
ASBESTOS-ST5-8/26/08	030829851-0004	Firehouse #10 (roof level)	8/26/08	1	2.990	Asbestos	PCME	EMSL	8/27/08	< 0.00083	No	No	
ASBESTOS-ST10-8/26/08	030829851-0005	North Side Sidewalk Bridge	8/26/08	1	2.950	Asbestos	PCME	EMSL	8/27/08	< 0.00084	No	No	
ASBESTOS-ST11-8/26/08	030829851-0006	90 Trinity Place (roof level)	8/26/08	1	3.000	Asbestos	PCME	EMSL	8/27/08	< 0.00082	No	No	
ASBESTOS-ST12-8/26/08	030829851-0007	110 Greenwich Street (roof level)	8/26/08	1	3.010	Asbestos	PCME	EMSL	8/27/08	< 0.00082	No	No	
ASBESTOS-ST13-8/26/08	030829851-0008	Marriott Hotel, 38th Floor (roof level)	8/26/08	1	3.000	Asbestos	PCME	EMSL	8/27/08	< 0.00082	No	No	
ASBESTOS-ST14-8/26/08	030829851-0009	West Face - South end at corner (scaffolding level)	8/26/08	1	3.060	Asbestos	PCME	EMSL	8/27/08	< 0.00081	No	No	
ASBESTOS-ST15-8/26/08	030829851-0010	South Face - East end at corner (scaffolding level)	8/26/08	1	3.050	Asbestos	PCME	EMSL	8/27/08	< 0.00081	No	No	
ASBESTOS-ST16-8/26/08	030829851-0011	East Face - North end at corner (scaffolding level)	8/26/08	1	3.010	Asbestos	PCME	EMSL	8/27/08	< 0.00082	No	No	
ASBESTOS-ST17-8/26/08	030829851-0012	North Face - West end at corner (scaffolding level)	8/26/08	1	3.050	Asbestos	PCME	EMSL	8/27/08	< 0.00081	No	No	
ASBESTOS-ST1-8/27/08	030830038-0001	Southwest Area (sidewalk bridge level)	8/27/08	1	3.580	Asbestos	PCME	EMSL	8/28/08	< 0.00069	No	No	
ASBESTOS-ST2-8/27/08	030830038-0002	Southeast Area (sidewalk bridge level)	8/27/08	1	3.680	Asbestos	PCME	EMSL	8/28/08	< 0.00067	No	No	
ASBESTOS-ST4-8/27/08	030830038-0003	Northwest Area (street-level)	8/27/08	1	3.850	Asbestos	PCME	EMSL	8/28/08	< 0.00064	No	No	
ASBESTOS-ST5-8/27/08	030830038-0004	Firehouse #10 (roof level)	8/27/08	1	3.530	Asbestos	PCME	EMSL	8/28/08	< 0.00070	No	No	
ASBESTOS-ST10-8/27/08	030830038-0005	North Side Sidewalk Bridge	8/27/08	1	3.790	Asbestos	PCME	EMSL	8/28/08	< 0.00065	No	No	
ASBESTOS-ST11-8/27/08	030830038-0006	90 Trinity Place (roof level)	8/27/08	1	3.800	Asbestos	PCME	EMSL	8/28/08	< 0.00065	No	No	
ASBESTOS-ST12-8/27/08	030830038-0007	110 Greenwich Street (roof level)	8/27/08	1	3.890	Asbestos	PCME	EMSL	8/28/08	< 0.00063	No	No	
ASBESTOS-ST13-8/27/08	030830038-0008	Marriott Hotel, 38th Floor (roof level)	8/27/08	1	3.450	Asbestos	PCME	EMSL	8/28/08	< 0.00072	No	No	
ASBESTOS-ST14-8/27/08	030830038-0009	West Face - South end at corner (scaffolding level)	8/27/08	1	3.910	Asbestos	PCME	EMSL	8/28/08	< 0.00063	No	No	
ASBESTOS-ST15-8/27/08	030830038-0010	South Face - East end at corner (scaffolding level)	8/27/08	1	4.160	Asbestos	PCME	EMSL	8/28/08	< 0.00059	No	No	
ASBESTOS-ST16-8/27/08	030830038-0011	East Face - North end at corner (scaffolding level)	8/27/08	1	4.130	Asbestos	PCME	EMSL	8/28/08	< 0.00060	No	No	
ASBESTOS-ST17-8/27/08	030830038-0012	North Face - West end at corner (scaffolding level)	8/27/08	1	3.720	Asbestos	PCME	EMSL	8/28/08	< 0.00066	No	No	
ASBESTOS-ST1-8/28/08	030830230-0001	Southwest Area (sidewalk bridge level)	8/28/08	1	3.230	Asbestos	PCME	EMSL	8/29/08	< 0.00083	No	No	
ASBESTOS-ST2-8/28/08	030830230-0002	Southeast Area (sidewalk bridge level)	8/28/08	1	3.150	Asbestos	PCME	EMSL	8/29/08	< 0.00085	No	No	
ASBESTOS-ST4-8/28/08	030830230-0003	Northwest Area (street-level)	8/28/08	1	3.280	Asbestos	PCME	EMSL	8/29/08	< 0.00082	No	No	
ASBESTOS-ST5-8/28/08	030830230-0004	Firehouse #10 (roof level)	8/28/08	1	3.000	Asbestos	PCME	EMSL	8/29/08	< 0.00082	No	No	
ASBESTOS-ST10-8/28/08	030830230-0005	North Side Sidewalk Bridge	8/28/08	1	3.080	Asbestos	PCME	EMSL	8/29/08	< 0.00087	No	No	
ASBESTOS-ST100-8/28/08	030830230-0013	Station 10 Field Duplicate	8/28/08	1	3.050	Asbestos	PCME	EMSL	8/29/08	< 0.00081	No	No	
ASBESTOS-ST11-8/28/08	030830230-0006	90 Trinity Place (roof level)	8/28/08	1	3.110	Asbestos	PCME	EMSL	8/29/08	< 0.00087	No	No	
ASBESTOS-ST12-8/28/08	030830230-0007	110 Greenwich Street (roof level)	8/28/08	1	3.050	Asbestos	PCME	EMSL	8/29/08	< 0.00081	No	No	
ASBESTOS-ST13-8/28/08	030830230-0008	Marriott Hotel, 38th Floor (roof level)	8/28/08	1	3.080	Asbestos	PCME	EMSL	8/29/08	< 0.00087	No	No	
ASBESTOS-ST14-8/28/08	030830230-0009	West Face - South end at corner (scaffolding level)	8/28/08	1	3.270	Asbestos	PCME	EMSL	8/29/08	< 0.00082	No	No	
ASBESTOS-ST15-8/28/08	030830230-0010	South Face - East end at corner (scaffolding level)	8/28/08	1	3.080	Asbestos	PCME	EMSL	8/29/08	0.00087	No	No	
ASBESTOS-ST16-8/28/08	030830230-0011	East Face - North end at corner (scaffolding level)	8/28/08	1	3.160	Asbestos	PCME	EMSL	8/29/08	< 0.00085	No	No	
ASBESTOS-ST17-8/28/08	030830230-0012	North Face - West end at corner (scaffolding level)	8/28/08	1	3.110	Asbestos	PCME	EMSL	8/29/08	< 0.00087	No	No	
ASBESTOS-ST1-8/29/08	030830321-0001	Southwest Area (sidewalk bridge level)	8/29/08	1	3.110	Asbestos	PCME	EMSL	8/30/08	< 0.00087	No	No	
ASBESTOS-ST2-8/29/08	030830321-0002	Southeast Area (sidewalk bridge level)	8/29/08	1	3.100	Asbestos	PCME	EMSL	8/30/08	< 0.00087	No	No	
ASBESTOS-ST4-8/29/08	030830321-0003	Northwest Area (street-level)	8/29/08	1	3.030	Asbestos	PCME	EMSL	8/30/08	< 0.00081	No	No	
ASBESTOS-ST5-8/29/08	030830321-0004	Firehouse #10 (roof level)	8/29/08	1	3.080	Asbestos	PCME	EMSL	8/30/08	< 0.00087	No	No	
ASBESTOS-ST10-8/29/08	030830321-0005	North Side Sidewalk Bridge	8/29/08	1	3.020	Asbestos	PCME	EMSL	8/30/08	< 0.00082	No	No	
ASBESTOS-ST11-8/29/08	030830321-0006	90 Trinity Place (roof level)	8/29/08	1	3.070	Asbestos	PCME	EMSL	8/30/08	< 0.00088	No	No	
ASBESTOS-ST12-8/29/08	030830321-0007	110 Greenwich Street (roof level)	8/29/08	1	3.000	Asbestos	PCME	EMSL	8/30/08	< 0.00082	No	No	
ASBESTOS-ST13-8/29/08	030830321-0008	Marriott Hotel, 38th Floor (roof level)	8/29/08	1	3.060	Asbestos	PCME	EMSL	8/30/08	< 0.00081	No	No	
ASBESTOS-ST14-8/29/08	030830321-0009	West Face - South end at corner (scaffolding level)	8/29/08	1	2.880	Asbestos	PCME	EMSL	8/30/08	< 0.00086	No	No	
ASBESTOS-ST15-8/29/08	030830321-0010	South Face - East end at corner (scaffolding level)	8/29/08	1	2.900	Asbestos	PCME	EMSL	8/30/08	< 0.00085	No	No	
ASBESTOS-ST16-8/29/08	030830321-0011	East Face - North end at corner (scaffolding level)	8/29/08	1	2.820	Asbestos	PCME	EMSL	8/30/08	< 0.00088	No	No	
ASBESTOS-ST17-8/29/08	030830321-0012	North Face - West end at corner (scaffolding level)	8/29/08	1	2.850	Asbestos	PCME	EMSL	8/30/08	< 0.00087	No	No	