

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-9/1/09	030922867-0001	Southwest Area (sidewalk bridge level)	9/1/09	1	3.070	Asbestos	PCME	EMSL	9/2/09	< 0.00080	No	No	
ASBESTOS-ST2-9/1/09	030922867-0002	Southeast Area (sidewalk bridge level)	9/1/09	1	3.030	Asbestos	PCME	EMSL	9/2/09	< 0.00081	No	No	
ASBESTOS-ST4-9/1/09	030922867-0003	Northwest Area (street-level)	9/1/09	1	2.960	Asbestos	PCME	EMSL	9/2/09	< 0.00083	No	No	
ASBESTOS-ST5-9/1/09	030922867-0004	Firehouse #10 (roof level)	9/1/09	1	3.080	Asbestos	PCME	EMSL	9/2/09	< 0.00080	No	No	
ASBESTOS-ST10-9/1/09	030922867-0005	North Side Sidewalk Bridge	9/1/09	1	3.010	Asbestos	PCME	EMSL	9/2/09	< 0.00082	No	No	
ASBESTOS-ST11-9/1/09	030922867-0006	90 Trinity Place (roof level)	9/1/09	1	3.050	Asbestos	PCME	EMSL	9/2/09	< 0.00081	No	No	
ASBESTOS-ST12-9/1/09	030922867-0007	110 Greenwich Street (roof level)	9/1/09	1	2.980	Asbestos	PCME	EMSL	9/2/09	< 0.00083	No	No	
ASBESTOS-ST13-9/1/09	030922867-0008	Marriott Hotel, 38th Floor (roof level)	9/1/09	1	3.040	Asbestos	PCME	EMSL	9/2/09	< 0.00081	No	No	
ASBESTOS-ST1-9/2/09	030922975-0001	Southwest Area (sidewalk bridge level)	9/2/09	1	3.060	Asbestos	PCME	EMSL	9/3/09	< 0.00081	No	No	
ASBESTOS-ST2-9/2/09	030922975-0002	Southeast Area (sidewalk bridge level)	9/2/09	1	3.090	Asbestos	PCME	EMSL	9/3/09	< 0.00080	No	No	
ASBESTOS-ST4-9/2/09	030922975-0003	Northwest Area (street-level)	9/2/09	1	3.120	Asbestos	PCME	EMSL	9/3/09	< 0.00079	No	No	
ASBESTOS-ST5-9/2/09	030922975-0004	Firehouse #10 (roof level)	9/2/09	1	2.980	Asbestos	PCME	EMSL	9/3/09	< 0.00083	No	No	
ASBESTOS-ST10-9/2/09	030922975-0005	North Side Sidewalk Bridge	9/2/09	1	3.060	Asbestos	PCME	EMSL	9/3/09	< 0.00081	No	No	
ASBESTOS-ST11-9/2/09	030922975-0006	90 Trinity Place (roof level)	9/2/09	1	3.030	Asbestos	PCME	EMSL	9/3/09	< 0.00081	No	No	
ASBESTOS-ST12-9/2/09	030922975-0007	110 Greenwich Street (roof level)	9/2/09	1	2.990	Asbestos	PCME	EMSL	9/3/09	< 0.00083	No	No	
ASBESTOS-ST13-9/2/09	030922975-0008	Marriott Hotel, 38th Floor (roof level)	9/2/09	1	2.970	Asbestos	PCME	EMSL	9/3/09	< 0.00083	No	No	
ASBESTOS-ST1-9/3/09	030923085-0001	Southwest Area (sidewalk bridge level)	9/3/09	1	3.050	Asbestos	PCME	EMSL	9/4/09	< 0.00081	No	No	
ASBESTOS-ST2-9/3/09	030923085-0002	Southeast Area (sidewalk bridge level)	9/3/09	1	3.010	Asbestos	PCME	EMSL	9/4/09	< 0.00082	No	No	
ASBESTOS-ST4-9/3/09	030923085-0003	Northwest Area (street-level)	9/3/09	1	3.020	Asbestos	PCME	EMSL	9/4/09	< 0.00082	No	No	
ASBESTOS-ST5-9/3/09	030923085-0004	Firehouse #10 (roof level)	9/3/09	1	2.960	Asbestos	PCME	EMSL	9/4/09	< 0.00083	No	No	
ASBESTOS-ST10-9/3/09	030923085-0005	North Side Sidewalk Bridge	9/3/09	1	3.100	Asbestos	PCME	EMSL	9/4/09	< 0.00080	No	No	
ASBESTOS-ST11-9/3/09	030923085-0006	90 Trinity Place (roof level)	9/3/09	1	2.990	Asbestos	PCME	EMSL	9/4/09	< 0.00083	No	No	
ASBESTOS-ST12-9/3/09	030923085-0007	110 Greenwich Street (roof level)	9/3/09	1	3.020	Asbestos	PCME	EMSL	9/4/09	< 0.00082	No	No	
ASBESTOS-ST13-9/3/09	030923085-0008	Marriott Hotel, 38th Floor (roof level)	9/3/09	1	3.130	Asbestos	PCME	EMSL	9/4/09	< 0.00079	No	No	
ASBESTOS-ST1-9/4/09	030923144-0001	Southwest Area (sidewalk bridge level)	9/4/09	1	3.010	Asbestos	PCME	EMSL	9/5/09	< 0.00082	No	No	
ASBESTOS-ST2-9/4/09	030923144-0002	Southeast Area (sidewalk bridge level)	9/4/09	1	2.980	Asbestos	PCME	EMSL	9/5/09	< 0.00083	No	No	
ASBESTOS-ST4-9/4/09	030923144-0003	Northwest Area (street-level)	9/4/09	1	3.050	Asbestos	PCME	EMSL	9/5/09	< 0.00081	No	No	
ASBESTOS-ST5-9/4/09	030923144-0004	Firehouse #10 (roof level)	9/4/09	1	3.050	Asbestos	PCME	EMSL	9/5/09	< 0.00081	No	No	
ASBESTOS-ST10-9/4/09	030923144-0005	North Side Sidewalk Bridge	9/4/09	1	2.960	Asbestos	PCME	EMSL	9/5/09	< 0.00083	No	No	
ASBESTOS-ST11-9/4/09	030923144-0006	90 Trinity Place (roof level)	9/4/09	1	3.000	Asbestos	PCME	EMSL	9/5/09	< 0.00082	No	No	
ASBESTOS-ST12-9/4/09	030923144-0007	110 Greenwich Street (roof level)	9/4/09	1	2.940	Asbestos	PCME	EMSL	9/5/09	< 0.00084	No	No	
ASBESTOS-ST13-9/4/09	030923144-0008	Marriott Hotel, 38th Floor (roof level)	9/4/09	1	3.020	Asbestos	PCME	EMSL	9/5/09	< 0.00082	No	No	