

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments	
										0.0009				
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-9/3/08	030830836-0001	Southwest Area (sidewalk bridge level)	9/3/08	1	3.050	Asbestos	PCME	EMSL	9/4/08	< 0.00081	No	No		
ASBESTOS-ST2-9/3/08	030830836-0002	Southeast Area (sidewalk bridge level)	9/3/08	1	3.050	Asbestos	PCME	EMSL	9/4/08	< 0.00081	No	No		
ASBESTOS-ST4-9/3/08	030830836-0003	Northwest Area (street-level)	9/3/08	1	3.100	Asbestos	PCME	EMSL	9/4/08	< 0.00080	No	No		
ASBESTOS-ST5-9/3/08	030830836-0004	Firehouse #10 (roof level)	9/3/08	1	3.040	Asbestos	PCME	EMSL	9/4/08	< 0.00081	No	No		
ASBESTOS-ST10-9/3/08	030830836-0005	North Side Sidewalk Bridge	9/3/08	1	3.080	Asbestos	PCME	EMSL	9/4/08	< 0.00080	No	No		
ASBESTOS-ST11-9/3/08	030830836-0006	90 Trinity Place (roof level)	9/3/08	1	3.040	Asbestos	PCME	EMSL	9/4/08	< 0.00081	No	No		
ASBESTOS-ST12-9/3/08	030830836-0007	110 Greenwich Street (roof level)	9/3/08	1	3.080	Asbestos	PCME	EMSL	9/4/08	< 0.00080	No	No		
ASBESTOS-ST13-9/3/08	030830836-0008	Marriott Hotel, 38th Floor (roof level)	9/3/08	1	3.030	Asbestos	PCME	EMSL	9/4/08	< 0.00081	No	No		
ASBESTOS-ST14-9/3/08	030831011-0009	West Face - South end at corner (scaffolding level)	9/3/08	1	6.100	Asbestos	PCME	EMSL	9/5/08	< 0.00081	No	No	Note 1	
ASBESTOS-ST15-9/3/08	030831011-0010	South Face - East end at corner (scaffolding level)	9/3/08	1	6.110	Asbestos	PCME	EMSL	9/5/08	< 0.00081	No	No	Note 1	
ASBESTOS-ST16-9/3/08	030831011-0011	East Face - North end at corner (scaffolding level)	9/3/08	1	6.140	Asbestos	PCME	EMSL	9/5/08	< 0.00080	No	No	Note 1	
ASBESTOS-ST17-9/3/08	030831011-0012	North Face - West end at corner (scaffolding level)	9/3/08	1	6.300	Asbestos	PCME	EMSL	9/5/08	< 0.00078	No	No	Note 1	
ASBESTOS-ST1-9/4/08	030831011-0001	Southwest Area (sidewalk bridge level)	9/4/08	1	3.160	Asbestos	PCME	EMSL	9/5/08	< 0.00078	No	No		
ASBESTOS-ST2-9/4/08	030831011-0002	Southeast Area (sidewalk bridge level)	9/4/08	1	3.120	Asbestos	PCME	EMSL	9/5/08	< 0.00079	No	No		
ASBESTOS-ST4-9/4/08	030831011-0003	Northwest Area (street-level)	9/4/08	1	3.130	Asbestos	PCME	EMSL	9/5/08	< 0.00079	No	No		
ASBESTOS-ST5-9/4/08	030831011-0004	Firehouse #10 (roof level)	9/4/08	1	3.070	Asbestos	PCME	EMSL	9/5/08	< 0.00080	No	No		
ASBESTOS-ST10-9/4/08	030831011-0005	North Side Sidewalk Bridge	9/4/08	1	3.160	Asbestos	PCME	EMSL	9/5/08	< 0.00078	No	No		
ASBESTOS-ST11-9/4/08	030831011-0006	90 Trinity Place (roof level)	9/4/08	1	3.000	Asbestos	PCME	EMSL	9/5/08	< 0.00082	No	No		
ASBESTOS-ST12-9/4/08	030831011-0007	110 Greenwich Street (roof level)	9/4/08	1	3.060	Asbestos	PCME	EMSL	9/5/08	< 0.00081	No	No		
ASBESTOS-ST13-9/4/08	030831011-0008	Marriott Hotel, 38th Floor (roof level)	9/4/08	1	3.090	Asbestos	PCME	EMSL	9/5/08	< 0.00080	No	No		
ASBESTOS-ST1-9/5/08	030831106-0001	Southwest Area (sidewalk bridge level)	9/5/08	1	3.010	Asbestos	PCME	EMSL	9/6/08	< 0.00082	No	No		
ASBESTOS-ST2-9/5/08	030831106-0002	Southeast Area (sidewalk bridge level)	9/5/08	1	3.160	Asbestos	PCME	EMSL	9/6/08	< 0.00078	No	No		
ASBESTOS-ST4-9/5/08	030831106-0003	Northwest Area (street-level)	9/5/08	1	3.010	Asbestos	PCME	EMSL	9/6/08	< 0.00082	No	No		
ASBESTOS-ST5-9/5/08	030831106-0004	Firehouse #10 (roof level)	9/5/08	1	3.090	Asbestos	PCME	EMSL	9/6/08	< 0.00080	No	No		
ASBESTOS-ST10-9/5/08	030831106-0005	North Side Sidewalk Bridge	9/5/08	1	2.890	Asbestos	PCME	EMSL	9/6/08	< 0.00085	No	No		
ASBESTOS-ST100-9/5/08	030831106-0013	Station 10 Field Duplicate	9/5/08	1	2.910	Asbestos	PCME	EMSL	9/6/08	< 0.00085	No	No		
ASBESTOS-ST11-9/5/08	030831106-0006	90 Trinity Place (roof level)	9/5/08	1	3.040	Asbestos	PCME	EMSL	9/6/08	< 0.00081	No	No		
ASBESTOS-ST12-9/5/08	030831106-0007	110 Greenwich Street (roof level)	9/5/08	1	3.030	Asbestos	PCME	EMSL	9/6/08	< 0.00081	No	No		
ASBESTOS-ST13-9/5/08	030831106-0008	Marriott Hotel, 38th Floor (roof level)	9/5/08	1	3.050	Asbestos	PCME	EMSL	9/6/08	< 0.00081	No	No		
ASBESTOS-ST14-9/5/08	030831106-0009	West Face - South end at corner (scaffolding level)	9/5/08	1	2.960	Asbestos	PCME	EMSL	9/6/08	< 0.00083	No	No		
ASBESTOS-ST15-9/5/08	030831106-0010	South Face - East end at corner (scaffolding level)	9/5/08	1	2.870	Asbestos	PCME	EMSL	9/6/08	< 0.00086	No	No		
ASBESTOS-ST16-9/5/08	030831106-0011	East Face - North end at corner (scaffolding level)	9/5/08	1	2.970	Asbestos	PCME	EMSL	9/6/08	< 0.00083	No	No		
ASBESTOS-ST17-9/5/08	030831106-0012	North Face - West end at corner (scaffolding level)	9/5/08	1	2.940	Asbestos	PCME	EMSL	9/6/08	< 0.00084	No	No		
ASBESTOS-ST1-9/6/08	030831311-0001	Southwest Area (sidewalk bridge level)	9/6/08	1	2.990	Asbestos	PCME	EMSL	9/8/08	< 0.00083	No	No		
ASBESTOS-ST2-9/6/08	030831311-0002	Southeast Area (sidewalk bridge level)	9/6/08	1	2.990	Asbestos	PCME	EMSL	9/8/08	< 0.00083	No	No		
ASBESTOS-ST4-9/6/08	030831311-0003	Northwest Area (street-level)	9/6/08	1	2.960	Asbestos	PCME	EMSL	9/8/08	< 0.00083	No	No		
ASBESTOS-ST5-9/6/08	030831311-0004	Firehouse #10 (roof level)	9/6/08	1	3.150	Asbestos	PCME	EMSL	9/8/08	< 0.00078	No	No		
ASBESTOS-ST10-9/6/08	030831311-0005	North Side Sidewalk Bridge	9/6/08	1	3.080	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No		
ASBESTOS-ST11-9/6/08	030831311-0006	90 Trinity Place (roof level)	9/6/08	1	3.040	Asbestos	PCME	EMSL	9/8/08	< 0.00081	No	No		
ASBESTOS-ST12-9/6/08	030831311-0007	110 Greenwich Street (roof level)	9/6/08	1	3.070	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No		
ASBESTOS-ST13-9/6/08	030831311-0008	Marriott Hotel, 38th Floor (roof level)	9/6/08	1	3.070	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No		
ASBESTOS-ST14-9/6/08	030831311-0009	West Face - South end at corner (scaffolding level)	9/6/08	1	6.180	Asbestos	PCME	EMSL	9/8/08	< 0.00040	No	No	Note 2	
ASBESTOS-ST15-9/6/08	030831311-0010	South Face - East end at corner (scaffolding level)	9/6/08	1	6.200	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No	Note 2	
ASBESTOS-ST16-9/6/08	030831311-0011	East Face - North end at corner (scaffolding level)	9/6/08	1	6.420	Asbestos	PCME	EMSL	9/8/08	< 0.00077	No	No	Note 2	
ASBESTOS-ST17-9/6/08	030831311-0012	North Face - West end at corner (scaffolding level)	9/6/08	1	6.310	Asbestos	PCME	EMSL	9/8/08	< 0.00078	No	No	Note 2	
ASBESTOS-ST1-9/7/08	030831313-0001	Southwest Area (sidewalk bridge level)	9/7/08	1	3.190	Asbestos	PCME	EMSL	9/8/08	< 0.00077	No	No		
ASBESTOS-ST2-9/7/08	030831313-0002	Southeast Area (sidewalk bridge level)	9/7/08	1	3.000	Asbestos	PCME	EMSL	9/8/08	< 0.00082	No	No		
ASBESTOS-ST4-9/7/08	030831313-0003	Northwest Area (street-level)	9/7/08	1	3.070	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No		
ASBESTOS-ST5-9/7/08	030831313-0004	Firehouse #10 (roof level)	9/7/08	1	3.090	Asbestos	PCME	EMSL	9/8/08	< 0.00080	No	No		
ASBESTOS-ST10-9/7/08	030831313-0005	North Side Sidewalk Bridge	9/7/08	1	3.020	Asbestos	PCME	EMSL	9/8/08	< 0.00082	No	No		
ASBESTOS-ST11-9/7/08	030831313-0006	90 Trinity Place (roof level)	9/7/08	1	3.060	Asbestos	PCME	EMSL	9/8/08	< 0.00081	No	No		
ASBESTOS-ST12-9/7/08	030831313-0007	110 Greenwich Street (roof level)	9/7/08	1	2.970	Asbestos	PCME	EMSL	9/8/08	< 0.00083	No	No		
ASBESTOS-ST13-9/7/08	030831313-0008	Marriott Hotel, 38th Floor (roof level)	9/7/08	1	3.040	Asbestos	PCME	EMSL	9/8/08	< 0.00081	No	No		

Note:

1. Due to scaffolding accessibility restrictions, the asbestos samples at the scaffolding level stations on September 3, 2008 were not retrieved until September 5, 2008 and therefore represent 48-hour composite samples (September 3 through September 4).
2. Due to scaffolding accessibility restrictions, the asbestos samples at the scaffolding level stations on September 6, 2008 were not retrieved until September 8, 2008 and therefore represent 48-hour composite samples (September 6 through September 7).