

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-9/6/07	030730575-0001	Southwest Area (sidewalk bridge level)	9/6/07	1	3.040	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST2-9/6/07	030730575-0002	Southeast Area (sidewalk bridge level)	9/6/07	1	3.040	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST4-9/6/07	030730575-0003	Northwest Area (street-level)	9/6/07	1	3.090	Asbestos	PCME	EMSL	9/7/07	< 0.00080	No	No	
ASBESTOS-ST5-9/6/07	030730575-0004	Firehouse #10 (roof level)	9/6/07	1	3.020	Asbestos	PCME	EMSL	9/7/07	< 0.00082	No	No	
ASBESTOS-ST10-9/6/07	030730575-0005	North Side Sidewalk Bridge	9/6/07	1	3.090	Asbestos	PCME	EMSL	9/7/07	< 0.00080	No	No	
ASBESTOS-ST11-9/6/07	030730575-0006	90 Trinity Place (roof level)	9/6/07	1	2.960	Asbestos	PCME	EMSL	9/7/07	< 0.00083	No	No	
ASBESTOS-ST12-9/6/07	030730575-0007	110 Greenwich Street (roof level)	9/6/07	1	3.090	Asbestos	PCME	EMSL	9/7/07	< 0.00080	No	No	
ASBESTOS-ST13-9/6/07	030730575-0008	Marriott Hotel, 38th Floor (roof level)	9/6/07	1	3.030	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST14-9/6/07	030730575-0009	West Face - South end at corner (scaffolding level)	9/6/07	1	3.040	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST15-9/6/07	030730575-0010	South Face - East end at corner (scaffolding level)	9/6/07	1	3.070	Asbestos	PCME	EMSL	9/7/07	< 0.00080	No	No	
ASBESTOS-ST16-9/6/07	030730575-0011	East Face - North end at corner (scaffolding level)	9/6/07	1	3.040	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST17-9/6/07	030730575-0012	North Face - West end at corner (scaffolding level)	9/6/07	1	3.060	Asbestos	PCME	EMSL	9/7/07	< 0.00081	No	No	
ASBESTOS-ST1-9/7/07	030730704-0001	Southwest Area (sidewalk bridge level)	9/7/07	1	3.090	Asbestos	PCME	EMSL	9/8/07	< 0.00080	No	No	
ASBESTOS-ST2-9/7/07	030730704-0002	Southeast Area (sidewalk bridge level)	9/7/07	1	2.960	Asbestos	PCME	EMSL	9/8/07	< 0.00083	No	No	
ASBESTOS-ST4-9/7/07	030730704-0003	Northwest Area (street-level)	9/7/07	1	3.010	Asbestos	PCME	EMSL	9/8/07	< 0.00082	No	No	
ASBESTOS-ST5-9/7/07	030730704-0004	Firehouse #10 (roof level)	9/7/07	1	3.040	Asbestos	PCME	EMSL	9/8/07	< 0.00081	No	No	
ASBESTOS-ST10-9/7/07	030730704-0005	North Side Sidewalk Bridge	9/7/07	1	3.090	Asbestos	PCME	EMSL	9/8/07	< 0.00080	No	No	
ASBESTOS-ST11-9/7/07	030730704-0006	90 Trinity Place (roof level)	9/7/07	1	2.990	Asbestos	PCME	EMSL	9/8/07	< 0.00083	No	No	
ASBESTOS-ST12-9/7/07	030730704-0007	110 Greenwich Street (roof level)	9/7/07	1	3.040	Asbestos	PCME	EMSL	9/8/07	< 0.00081	No	No	
ASBESTOS-ST13-9/7/07	030730704-0008	Marriott Hotel, 38th Floor (roof level)	9/7/07	1	3.040	Asbestos	PCME	EMSL	9/8/07	< 0.00081	No	No	
ASBESTOS-ST14-9/7/07	030730704-0009	West Face - South end at corner (scaffolding level)	9/7/07	1	3.090	Asbestos	PCME	EMSL	9/8/07	< 0.00080	No	No	
ASBESTOS-ST15-9/7/07	030730704-0010	South Face - East end at corner (scaffolding level)	9/7/07	1	3.070	Asbestos	PCME	EMSL	9/8/07	< 0.00080	No	No	
ASBESTOS-ST16-9/7/07	030730704-0011	East Face - North end at corner (scaffolding level)	9/7/07	1	3.060	Asbestos	PCME	EMSL	9/8/07	< 0.00081	No	No	
ASBESTOS-ST17-9/7/07	030730704-0012	North Face - West end at corner (scaffolding level)	9/7/07	1	3.020	Asbestos	PCME	EMSL	9/8/07	< 0.00082	No	No	
ASBESTOS-ST1-9/8/07	030730838-0001	Southwest Area (sidewalk bridge level)	9/8/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST2-9/8/07	030730838-0002	Southeast Area (sidewalk bridge level)	9/8/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST4-9/8/07	030730838-0003	Northwest Area (street-level)	9/8/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST5-9/8/07	030730838-0004	Firehouse #10 (roof level)	9/8/07	1	3.030	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST10-9/8/07	030730838-0005	North Side Sidewalk Bridge	9/8/07	1	3.000	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST11-9/8/07	030730838-0006	90 Trinity Place (roof level)	9/8/07	1	2.940	Asbestos	PCME	EMSL	9/10/07	< 0.00084	No	No	
ASBESTOS-ST12-9/8/07	030730838-0007	110 Greenwich Street (roof level)	9/8/07	1	3.060	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST13-9/8/07	030730838-0008	Marriott Hotel, 38th Floor (roof level)	9/8/07	1	3.040	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST14-9/8/07	030730838-0009	West Face - South end at corner (scaffolding level)	9/8/07	1	3.030	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST15-9/8/07	030730838-0010	South Face - East end at corner (scaffolding level)	9/8/07	1	3.040	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST16-9/8/07	030730838-0011	East Face - North end at corner (scaffolding level)	9/8/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST17-9/8/07	030730838-0012	North Face - West end at corner (scaffolding level)	9/8/07	1	3.000	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST1-9/9/07	030730842-0001	Southwest Area (sidewalk bridge level)	9/9/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST2-9/9/07	030730842-0002	Southeast Area (sidewalk bridge level)	9/9/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST4-9/9/07	030730842-0003	Northwest Area (street-level)	9/9/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST5-9/9/07	030730842-0004	Firehouse #10 (roof level)	9/9/07	1	3.030	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST10-9/9/07	030730842-0005	North Side Sidewalk Bridge	9/9/07	1	3.000	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST11-9/9/07	030730842-0006	90 Trinity Place (roof level)	9/9/07	1	2.940	Asbestos	PCME	EMSL	9/10/07	< 0.00084	No	No	
ASBESTOS-ST12-9/9/07	030730842-0007	110 Greenwich Street (roof level)	9/9/07	1	3.060	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST13-9/9/07	030730842-0008	Marriott Hotel, 38th Floor (roof level)	9/9/07	1	3.040	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST14-9/9/07	030730842-0009	West Face - South end at corner (scaffolding level)	9/9/07	1	3.030	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST15-9/9/07	030730842-0010	South Face - East end at corner (scaffolding level)	9/9/07	1	3.040	Asbestos	PCME	EMSL	9/10/07	< 0.00081	No	No	
ASBESTOS-ST16-9/9/07	030730842-0011	East Face - North end at corner (scaffolding level)	9/9/07	1	3.020	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	
ASBESTOS-ST17-9/9/07	030730842-0012	North Face - West end at corner (scaffolding level)	9/9/07	1	3.000	Asbestos	PCME	EMSL	9/10/07	< 0.00082	No	No	