

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/9/09	030923389-0001	Southwest Area (sidewalk bridge level)	9/9/09	1	3.050	Asbestos	PCME	EMSL	9/10/09	< 0.00081	No	No	
ASBESTOS-ST4-9/9/09	030923389-0002	Northwest Area (street-level)	9/9/09	1	3.020	Asbestos	PCME	EMSL	9/10/09	< 0.00082	No	No	
ASBESTOS-ST5-9/9/09	030923389-0003	Firehouse #10 (roof level)	9/9/09	1	3.030	Asbestos	PCME	EMSL	9/10/09	< 0.00081	No	No	
ASBESTOS-ST10-9/9/09	030923389-0004	North Side Sidewalk Bridge	9/9/09	1	3.060	Asbestos	PCME	EMSL	9/10/09	< 0.00081	No	No	
ASBESTOS-ST11-9/9/09	030923389-0005	90 Trinity Place (roof level)	9/9/09	1	3.090	Asbestos	PCME	EMSL	9/10/09	< 0.00080	No	No	
ASBESTOS-ST12-9/9/09	030923389-0006	110 Greenwich Street (roof level)	9/9/09	1	2.930	Asbestos	PCME	EMSL	9/10/09	< 0.00084	No	No	
ASBESTOS-ST13-9/9/09	030923389-0007	Marriott Hotel, 38th Floor (roof level)	9/9/09	1	2.960	Asbestos	PCME	EMSL	9/10/09	< 0.00083	No	No	
ASBESTOS-ST1-9/10/09	030923535-0001	Southwest Area (sidewalk bridge level)	9/10/09	1	3.760	Asbestos	PCME	EMSL	9/12/09	< 0.00088	No	No	Note 3
ASBESTOS-ST2-9/10/09	030923535-0002	Southeast Area (sidewalk bridge level)	9/10/09	1	3.850	Asbestos	PCME	EMSL	9/12/09	< 0.00085	No	No	Note 3
ASBESTOS-ST4-9/10/09	030923535-0003	Northwest Area (street-level)	9/10/09	1	3.840	Asbestos	PCME	EMSL	9/12/09	< 0.00086	No	No	Note 3
ASBESTOS-ST5-9/10/09	030923535-0004	Firehouse #10 (roof level)	9/10/09	1	3.760	Asbestos	PCME	EMSL	9/12/09	< 0.00088	No	No	Note 3
ASBESTOS-ST10-9/10/09	030923535-0005	North Side Sidewalk Bridge	9/10/09	1	3.700	Asbestos	PCME	EMSL	9/12/09	< 0.00089	No	No	Note 3
ASBESTOS-ST11-9/10/09	030923535-0006	90 Trinity Place (roof level)	9/10/09	1	3.840	Asbestos	PCME	EMSL	9/12/09	< 0.00086	No	No	Note 3
ASBESTOS-ST12-9/10/09	030923535-0007	110 Greenwich Street (roof level)	9/10/09	1	3.860	Asbestos	PCME	EMSL	9/12/09	< 0.00085	No	No	Note 3
ASBESTOS-ST13-9/10/09	030923535-0008	Marriott Hotel, 38th Floor (roof level)	9/10/09	1	3.870	Asbestos	PCME	EMSL	9/12/09	< 0.00085	No	No	Note 3
ASBESTOS-ST1-9/11/09	030923529-0001	Southwest Area (sidewalk bridge level)	9/11/09	1	2.260	Asbestos	PCME	EMSL	9/12/09	< 0.00087	No	No	Note 4
ASBESTOS-ST2-9/11/09	030923529-0002	Southeast Area (sidewalk bridge level)	9/11/09	1	2.200	Asbestos	PCME	EMSL	9/12/09	< 0.00084	No	No	Note 4
ASBESTOS-ST4-9/11/09	030923529-0003	Northwest Area (street-level)	9/11/09	1	2.260	Asbestos	PCME	EMSL	9/12/09	< 0.00087	No	No	Note 4
ASBESTOS-ST10-9/11/09	030923529-0004	North Side Sidewalk Bridge	9/11/09	1	2.260	Asbestos	PCME	EMSL	9/12/09	< 0.00087	No	No	Note 4
ASBESTOS-ST11-9/11/09	030923529-0005	90 Trinity Place (roof level)	9/11/09	1	2.240	Asbestos	PCME	EMSL	9/12/09	< 0.00088	No	No	Note 4
ASBESTOS-ST12-9/11/09	030923529-0006	110 Greenwich Street (roof level)	9/11/09	1	2.270	Asbestos	PCME	EMSL	9/12/09	< 0.00087	No	No	Note 4
ASBESTOS-ST13-9/11/09	030923529-0007	Marriott Hotel, 38th Floor (roof level)	9/11/09	1	2.200	Asbestos	PCME	EMSL	9/12/09	< 0.00084	No	No	Note 4

Note:

1. The asbestos sample from Station 2 (Southeast Area [sidewalk bridge level]) on September 9, 2009 was not available for analysis on account of pump failure.
2. The asbestos sample from Station 5 (Firehouse #10 [roof level]) on September 11, 2009 was not available for analysis on account of damaged media.
3. The asbestos samples on September 10, 2009 had an increased volume as samples were collected for approximately 30 hours due to site access restrictions on September 11, 2009.
4. The asbestos samples on September 11, 2009 had a reduced volume as samples were collected for approximately 18 hours due to site access restrictions on September 11, 2009.