

| TRC Field Sample No.  | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method | Lab  | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3)     | Exceeds Target     | Exceeds EPA                  | Comments |
|-----------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|---|--------------------|------------------------------|----------|
|                       |                |   |                       |            |                                 |          |                   |      |                         | 0.0009                                  | Air Quality Levels | Site Specific Trigger Levels |          |
|                       |                |   |                       |            |                                 |          |                   |      |                         | NA                                      |                    |                              |          |
|                       |                |   |                       |            |                                 |          |                   |      |                         | <b>Target Air Quality Levels</b>        |                    |                              |          |
|                       |                |   |                       |            |                                 |          |                   |      |                         | <b>EPA Site Specific Trigger Levels</b> |                    |                              |          |
| ASBESTOS-ST1-9/10/07  | 030730931-0001 | Southwest Area (sidewalk bridge level)              | 9/10/07               | 1          | 2.970                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00083                               | No                 | No                           |          |
| ASBESTOS-ST2-9/10/07  | 030730931-0002 | Southeast Area (sidewalk bridge level)              | 9/10/07               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST4-9/10/07  | 030730931-0003 | Northwest Area (street-level)                       | 9/10/07               | 1          | 3.060                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST5-9/10/07  | 030730931-0004 | Firehouse #10 (roof level)                          | 9/10/07               | 1          | 3.060                           | Asbestos | SEM               | EMSL | 9/11/07                 | < 0.0009                                | No                 | No                           |          |
| ASBESTOS-ST10-9/10/07 | 030730931-0005 | North Side Sidewalk Bridge                          | 9/10/07               | 1          | 3.060                           | Asbestos | SEM               | EMSL | 9/11/07                 | < 0.0009                                | No                 | No                           |          |
| ASBESTOS-ST11-9/10/07 | 030730931-0006 | 90 Trinity Place (roof level)                       | 9/10/07               | 1          | 2.970                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00083                               | No                 | No                           |          |
| ASBESTOS-ST12-9/10/07 | 030730931-0007 | 110 Greenwich Street (roof level)                   | 9/10/07               | 1          | 2.920                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00085                               | No                 | No                           |          |
| ASBESTOS-ST13-9/10/07 | 030730931-0008 | Marriott Hotel, 38th Floor (roof level)             | 9/10/07               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 9/11/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST14-9/10/07 | 030731020-0013 | West Face - South end at corner (scaffolding level) | 9/10/07               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST15-9/10/07 | 030731020-0014 | South Face - East end at corner (scaffolding level) | 9/10/07               | 1          | 3.000                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00082                               | No                 | No                           |          |
| ASBESTOS-ST16-9/10/07 | 030731020-0015 | East Face - North end at corner (scaffolding level) | 9/10/07               | 1          | 3.040                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST17-9/10/04 | 030731020-0016 | North Face - West end at corner (scaffolding level) | 9/10/07               | 1          | 3.090                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00080                               | No                 | No                           |          |
| ASBESTOS-ST1-9/11/07  | 030731020-0001 | Southwest Area (sidewalk bridge level)              | 9/11/07               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST2-9/11/07  | 030731020-0002 | Southeast Area (sidewalk bridge level)              | 9/11/07               | 1          | 3.060                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST4-9/11/07  | 030731020-0003 | Northwest Area (street-level)                       | 9/11/07               | 1          | 3.000                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00082                               | No                 | No                           |          |
| ASBESTOS-ST5-9/11/07  | 030731020-0004 | Firehouse #10 (roof level)                          | 9/11/07               | 1          | 3.040                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST10-9/11/07 | 030731020-0005 | North Side Sidewalk Bridge                          | 9/11/07               | 1          | 3.060                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST11-9/11/07 | 030731020-0006 | 90 Trinity Place (roof level)                       | 9/11/07               | 1          | 2.850                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00087                               | No                 | No                           |          |
| ASBESTOS-ST12-9/11/07 | 030731020-0007 | 110 Greenwich Street (roof level)                   | 9/11/07               | 1          | 2.940                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00084                               | No                 | No                           |          |
| ASBESTOS-ST13-9/11/07 | 030731020-0008 | Marriott Hotel, 38th Floor (roof level)             | 9/11/07               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00081                               | No                 | No                           |          |
| ASBESTOS-ST14-9/11/07 | 030731020-0009 | West Face - South end at corner (scaffolding level) | 9/11/07               | 1          | 3.770                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00087                               | No                 | No                           |          |
| ASBESTOS-ST15-9/11/07 | 030731020-0010 | South Face - East end at corner (scaffolding level) | 9/11/07               | 1          | 3.780                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00087                               | No                 | No                           |          |
| ASBESTOS-ST16-9/11/07 | 030731020-0011 | East Face - North end at corner (scaffolding level) | 9/11/07               | 1          | 3.730                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00088                               | No                 | No                           |          |
| ASBESTOS-ST17-9/11/07 | 030731020-0012 | North Face - West end at corner (scaffolding level) | 9/11/07               | 1          | 3.790                           | Asbestos | PCME              | EMSL | 9/12/07                 | < 0.00087                               | No                 | No                           |          |