

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										<b>0.0027</b>	Air Quality Levels	Site Specific Trigger Levels	
										<b>NA</b>			
										<b>3 * Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-9/16/2005	030527800-0001	Southwest Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/16/2005	030527800-0002	Southeast Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST3-9/16/2005	030527800-0003	Northeast Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/16/2005	030527800-0004	Northwest Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/16/2005	030527800-0005	Firehouse #10 (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/16/2005	030527800-0006	Southwest Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/16/2005	030527800-0007	Southeast Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/16/2005	030527800-0008	Northeast Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/16/2005	030527800-0009	Northwest Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/17/05	030527795-0001	Southwest Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/17/05	030527795-0002	Southeast Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/17/05	030527795-0004	Northwest Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/17/05	030527795-0005	Firehouse #10 (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/17/05	030527795-0006	Southwest Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/17/05	030527795-0007	Southeast Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/17/05	030527795-0008	Northeast Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/17/05	030527795-0009	Northwest Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/17/05	030527795-0003	North Side Sidewalk Bridge	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/18/05	030527797-0001	Southwest Area (street-level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/18/05	030527797-0002	Southeast Area (street-level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/18/05	030527797-0003	Northwest Area (street-level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/18/05	030527797-0004	Firehouse #10 (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/18/05	030527797-0005	Southwest Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/18/05	030527797-0006	Southeast Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/18/05	030527797-0007	Northeast Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/18/05	030527797-0008	Northwest Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/18/05	030527797-0009	North Side Sidewalk Bridge	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/19/05 A	030527931-1	Southwest Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/19/05 A	030527931-2	Southeast Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/19/05 A	030527931-3	Northwest Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/19/05 A	030527931-4	Firehouse #10 (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/19/05 A	030527931-5	Southwest Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/19/05 A	030527931-6	Southeast Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/19/05 A	030527931-7	Northeast Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/19/05 A	030527931-8	Northwest Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/19/05 A	030527931-9	North Side Sidewalk Bridge	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/19/05 B	030527931-10	Southwest Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/19/05 B	030527931-11	Southeast Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/19/05 B	030527931-12	Northwest Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/19/05 B	030527931-13	Firehouse #10 (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/19/05 B	030527931-14	Southwest Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/19/05 B	030527931-15	Southeast Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/19/05 B	030527931-16	Northeast Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/19/05 B	030527931-17	Northwest Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/19/05 B	030527931-18	North Side Sidewalk Bridge	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/20/05A	030528110-0001	Southwest Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/20/05A	030528110-0002	Southeast Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/20/05A	030528110-0003	Northwest Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/20/05A	030528110-0004	Firehouse #10 (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/20/05A	030528110-0005	Southwest Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/20/05A	030528110-0006	Southeast Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/20/05A	030528110-0007	Northeast Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/20/05A	030528110-0008	Northwest Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/20/05A	030528110-0009	North Side Sidewalk Bridge	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/20/05B	030528110-0010	Southwest Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/20/05B	030528110-0011	Southeast Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/20/05B	030528110-0012	Northwest Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/20/05B	030528110-0013	Firehouse #10 (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/20/05B	030528110-0014	Southwest Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/20/05B	030528110-0015	Southeast Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/20/05B	030528110-0016	Northeast Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/20/05B	030528110-0017	Northwest Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/20/05B	030528110-0018	North Side Sidewalk Bridge	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	