

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|--|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| Target Air Quality Levels | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | |
| ASBESTOS-ST1-9/17/07 | 030731498-0001 | Southwest Area (sidewalk bridge level) | 9/17/07 | 1 | 2.940 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00084 | No | No | |
| ASBESTOS-ST2-9/17/07 | 030731498-0002 | Southeast Area (sidewalk bridge level) | 9/17/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00083 | No | No | |
| ASBESTOS-ST4-9/17/07 | 030731498-0003 | Northwest Area (street-level) | 9/17/07 | 1 | 2.950 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00084 | No | No | |
| ASBESTOS-ST5-9/17/07 | 030731498-0004 | Firehouse #10 (roof level) | 9/17/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00082 | No | No | |
| ASBESTOS-ST10-9/17/07 | 030731498-0005 | North Side Sidewalk Bridge | 9/17/07 | 1 | 2.990 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00083 | No | No | |
| ASBESTOS-ST11-9/17/07 | 030731498-0006 | 90 Trinity Place (roof level) | 9/17/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00080 | No | No | |
| ASBESTOS-ST12-9/17/07 | 030731498-0007 | 110 Greenwich Street (roof level) | 9/17/07 | 1 | 3.150 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00078 | No | No | |
| ASBESTOS-ST13-9/17/07 | 030731498-0008 | Marriott Hotel, 38th Floor (roof level) | 9/17/07 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00081 | No | No | |
| ASBESTOS-ST14-9/17/07 | 030731498-0009 | West Face - South end at corner (scaffolding level) | 9/17/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00081 | No | No | |
| ASBESTOS-ST15-9/17/07 | 030731498-0010 | South Face - East end at corner (scaffolding level) | 9/17/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00083 | No | No | |
| ASBESTOS-ST16-9/17/07 | 030731498-0011 | East Face - North end at corner (scaffolding level) | 9/17/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00083 | No | No | |
| ASBESTOS-ST17-9/17/07 | 030731498-0012 | North Face - West end at corner (scaffolding level) | 9/17/07 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/18/07 | < 0.00081 | No | No | |
| ASBESTOS-ST1-9/18/07 | 030731581-0001 | Southwest Area (sidewalk bridge level) | 9/18/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00081 | No | No | |
| ASBESTOS-ST2-9/18/07 | 030731581-0002 | Southeast Area (sidewalk bridge level) | 9/18/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00081 | No | No | |
| ASBESTOS-ST4-9/18/07 | 030731581-0003 | Northwest Area (street-level) | 9/18/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00081 | No | No | |
| ASBESTOS-ST5-9/18/07 | 030731581-0004 | Firehouse #10 (roof level) | 9/18/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00083 | No | No | |
| ASBESTOS-ST10-9/18/07 | 030731581-0005 | North Side Sidewalk Bridge | 9/18/07 | 1 | 3.110 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00079 | No | No | |
| ASBESTOS-ST11-9/18/07 | 030731581-0006 | 90 Trinity Place (roof level) | 9/18/07 | 1 | 3.120 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00079 | No | No | |
| ASBESTOS-ST12-9/18/07 | 030731581-0007 | 110 Greenwich Street (roof level) | 9/18/07 | 1 | 3.120 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00079 | No | No | |
| ASBESTOS-ST13-9/18/07 | 030731581-0008 | Marriott Hotel, 38th Floor (roof level) | 9/18/07 | 1 | 2.840 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00087 | No | No | |
| ASBESTOS-ST14-9/18/07 | 030731581-0009 | West Face - South end at corner (scaffolding level) | 9/18/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00081 | No | No | |
| ASBESTOS-ST15-9/18/07 | 030731581-0010 | South Face - East end at corner (scaffolding level) | 9/18/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00083 | No | No | |
| ASBESTOS-ST16-9/18/07 | 030731581-0011 | East Face - North end at corner (scaffolding level) | 9/18/07 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00081 | No | No | |
| ASBESTOS-ST17-9/18/07 | 030731581-0012 | North Face - West end at corner (scaffolding level) | 9/18/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 9/19/07 | < 0.00082 | No | No | |