

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-9/18/06	030630687-0001	Southwest Area (sidewalk bridge level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST2-9/18/06	030630687-0002	Southeast Area (sidewalk bridge level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST4-9/18/06	030630687-0003	Northwest Area (street-level)	9/18/06	1	3.150	Asbestos	PCME	EMSL	9/19/06	< 0.00078	No	No	
ASBESTOS-ST5-9/18/06	030630687-0004	Firehouse #10 (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST6-9/18/06	030630700-0001	Southwest Area (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST7-9/18/06	030630700-0002	Southeast Area (roof level)	9/18/06	1	3.060	Asbestos	PCME	EMSL	9/19/06	< 0.00081	No	No	
ASBESTOS-ST8-9/18/06	030630700-0003	Northwest Area (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST9-9/18/06	030630700-0004	Northwest Area (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST10-9/18/06	030630687-0005	North Side Sidewalk Bridge	9/18/06	1	3.090	Asbestos	PCME	EMSL	9/19/06	< 0.00080	No	No	
ASBESTOS-ST11-9/18/06	030630687-0006	90 Trinity Place (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST12-9/18/06	030630687-0007	110 Greenwich Street (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST13-9/18/06	030630687-0008	Marriott Hotel, 38th Floor (roof level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST14-9/18/06	030630687-0009	West Face - South end at corner (scaffolding level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST14-9/18/06	030630687-0010	West Face - South end at corner (scaffolding level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST16-9/18/06	030630687-0011	East Face - North end at corner (scaffolding level)	9/18/06	1	3.040	Asbestos	PCME	EMSL	9/19/06	< 0.00081	No	No	
ASBESTOS-ST17-9/18/06	030630687-0012	North Face - West end at corner (scaffolding level)	9/18/06	1	3.020	Asbestos	PCME	EMSL	9/19/06	< 0.00082	No	No	
ASBESTOS-ST1-9/19/06	030630806-0001	Southwest Area (sidewalk bridge level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST2-9/19/06	030630806-0002	Southeast Area (sidewalk bridge level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST4-9/19/06	030630806-0003	Northwest Area (street-level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST5-9/19/06	030630806-0004	Firehouse #10 (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST6-9/19/06	030630807-0001	Southwest Area (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST7-9/19/06	030630807-0002	Southeast Area (roof level)	9/19/06	1	3.050	Asbestos	PCME	EMSL	9/20/06	< 0.00081	No	No	
ASBESTOS-ST8-9/19/06	030630807-0003	Northeast Area (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST9-9/19/06	030630807-0004	Northwest Area (roof level)	9/19/06	1	3.060	Asbestos	PCME	EMSL	9/20/06	< 0.00081	No	No	
ASBESTOS-ST10-9/19/06	030630806-0005	North Side Sidewalk Bridge	9/19/06	1	2.960	Asbestos	PCME	EMSL	9/20/06	< 0.00083	No	No	
ASBESTOS-ST100-9/19/06	030630806-0013	Station 10 Field Duplicate	9/19/06	1	3.400	Asbestos	PCME	EMSL	9/20/06	< 0.00073	No	No	Note 1.
ASBESTOS-ST11-9/19/06	030630806-0006	90 Trinity Place (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST12-9/19/06	030630806-0007	110 Greenwich Street (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST13-9/19/06	030630806-0008	Marriott Hotel, 38th Floor (roof level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST14-9/19/06	030630806-0009	West Face - South end at corner (scaffolding level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST15-9/19/06	030630806-0010	South Face - East end at corner (scaffolding level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST16-9/19/06	030630806-0011	East Face - North end at corner (scaffolding level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	
ASBESTOS-ST17-9/19/06	030630806-0012	North Face - West end at corner (scaffolding level)	9/19/06	1	3.020	Asbestos	PCME	EMSL	9/20/06	< 0.00082	No	No	

Note:

1. Due to flow rate RPD exceedance (22.2%) for asbestos at Station 100 (Station 10 Field Duplicate) on September 19, 2006, the sample volume and subsequent sample result are estimated.