

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/19/08	030833077-0001	Southwest Area (sidewalk bridge level)	9/19/08	1	2.990	Asbestos	PCME	EMSL	9/20/08	< 0.00083	No	No	
ASBESTOS-ST2-9/19/08	030833077-0002	Southeast Area (sidewalk bridge level)	9/19/08	1	3.040	Asbestos	PCME	EMSL	9/20/08	< 0.00081	No	No	
ASBESTOS-ST4-9/19/08	030833077-0003	Northwest Area (street-level)	9/19/08	1	3.050	Asbestos	PCME	EMSL	9/20/08	< 0.00081	No	No	
ASBESTOS-ST5-9/19/08	030833077-0004	Firehouse #10 (roof level)	9/19/08	1	3.040	Asbestos	PCME	EMSL	9/20/08	< 0.00081	No	No	
ASBESTOS-ST10-9/19/08	030833077-0005	North Side Sidewalk Bridge	9/19/08	1	3.110	Asbestos	PCME	EMSL	9/20/08	< 0.00079	No	No	
ASBESTOS-ST11-9/19/08	030833077-0006	90 Trinity Place (roof level)	9/19/08	1	3.010	Asbestos	PCME	EMSL	9/20/08	< 0.00082	No	No	
ASBESTOS-ST12-9/19/08	030833077-0007	110 Greenwich Street (roof level)	9/19/08	1	3.040	Asbestos	PCME	EMSL	9/20/08	< 0.00081	No	No	
ASBESTOS-ST13-9/19/08	030833077-0008	Marriott Hotel, 38th Floor (roof level)	9/19/08	1	3.130	Asbestos	PCME	EMSL	9/20/08	< 0.00079	No	No	
ASBESTOS-ST14-9/19/08	030833077-0009	West Face - South end at corner (scaffolding level)	9/19/08	1	2.830	Asbestos	PCME	EMSL	9/20/08	< 0.00087	No	No	
ASBESTOS-ST15-9/19/08	030833077-0010	South Face - East end at corner (scaffolding level)	9/19/08	1	2.910	Asbestos	PCME	EMSL	9/20/08	< 0.00085	No	No	
ASBESTOS-ST16-9/19/08	030833077-0011	East Face - North end at corner (scaffolding level)	9/19/08	1	2.970	Asbestos	PCME	EMSL	9/20/08	< 0.00083	No	No	
ASBESTOS-ST17-9/19/08	030833077-0012	North Face - West end at corner (scaffolding level)	9/19/08	1	2.850	Asbestos	PCME	EMSL	9/20/08	< 0.00087	No	No	
ASBESTOS-ST1-9/20/08	030833237-0001	Southwest Area (sidewalk bridge level)	9/20/08	1	2.950	Asbestos	PCME	EMSL	9/22/08	< 0.00084	No	No	
ASBESTOS-ST2-9/20/08	030833237-0002	Southeast Area (sidewalk bridge level)	9/20/08	1	3.030	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST4-9/20/08	030833237-0003	Northwest Area (street-level)	9/20/08	1	2.990	Asbestos	PCME	EMSL	9/22/08	< 0.00083	No	No	
ASBESTOS-ST5-9/20/08	030833237-0004	Firehouse #10 (roof level)	9/20/08	1	3.050	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST10-9/20/08	030833237-0005	North Side Sidewalk Bridge	9/20/08	1	3.000	Asbestos	PCME	EMSL	9/22/08	< 0.00082	No	No	
ASBESTOS-ST11-9/20/08	030833237-0006	90 Trinity Place (roof level)	9/20/08	1	3.010	Asbestos	PCME	EMSL	9/22/08	< 0.00082	No	No	
ASBESTOS-ST12-9/20/08	030833237-0007	110 Greenwich Street (roof level)	9/20/08	1	3.040	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST13-9/20/08	030833237-0008	Marriott Hotel, 38th Floor (roof level)	9/20/08	1	2.980	Asbestos	PCME	EMSL	9/22/08	< 0.00083	No	No	
ASBESTOS-ST14-9/20/08	030833237-0009	West Face - South end at corner (scaffolding level)	9/20/08	1	3.030	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST15-9/20/08	030833237-0010	South Face - East end at corner (scaffolding level)	9/20/08	1	2.970	Asbestos	PCME	EMSL	9/22/08	< 0.00083	No	No	
ASBESTOS-ST16-9/20/08	030833237-0011	East Face - North end at corner (scaffolding level)	9/20/08	1	3.040	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST17-9/20/08	030833237-0012	North Face - West end at corner (scaffolding level)	9/20/08	1	3.020	Asbestos	PCME	EMSL	9/22/08	< 0.00082	No	No	
ASBESTOS-ST1-9/21/08	030833239-0001	Southwest Area (sidewalk bridge level)	9/21/08	1	3.150	Asbestos	PCME	EMSL	9/22/08	< 0.00085	No	No	
ASBESTOS-ST2-9/21/08	030833239-0002	Southeast Area (sidewalk bridge level)	9/21/08	1	3.030	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST4-9/21/08	030833239-0003	Northwest Area (street-level)	9/21/08	1	2.980	Asbestos	PCME	EMSL	9/22/08	< 0.00083	No	No	
ASBESTOS-ST5-9/21/08	030833239-0004	Firehouse #10 (roof level)	9/21/08	1	3.070	Asbestos	PCME	EMSL	9/22/08	< 0.00080	No	No	
ASBESTOS-ST10-9/21/08	030833239-0005	North Side Sidewalk Bridge	9/21/08	1	3.070	Asbestos	PCME	EMSL	9/22/08	< 0.00080	No	No	
ASBESTOS-ST11-9/21/08	030833239-0006	90 Trinity Place (roof level)	9/21/08	1	3.070	Asbestos	PCME	EMSL	9/22/08	< 0.00080	No	No	
ASBESTOS-ST12-9/21/08	030833239-0007	110 Greenwich Street (roof level)	9/21/08	1	3.110	Asbestos	PCME	EMSL	9/22/08	< 0.00087	No	No	
ASBESTOS-ST13-9/21/08	030833239-0008	Marriott Hotel, 38th Floor (roof level)	9/21/08	1	3.040	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST14-9/21/08	030833239-0009	West Face - South end at corner (scaffolding level)	9/21/08	1	3.320	Asbestos	PCME	EMSL	9/22/08	< 0.00081	No	No	
ASBESTOS-ST15-9/21/08	030833239-0010	South Face - East end at corner (scaffolding level)	9/21/08	1	3.190	Asbestos	PCME	EMSL	9/22/08	< 0.00084	No	No	
ASBESTOS-ST16-9/21/08	030833239-0011	East Face - North end at corner (scaffolding level)	9/21/08	1	3.280	Asbestos	PCME	EMSL	9/22/08	< 0.00082	No	No	
ASBESTOS-ST17-9/21/08	030833239-0012	North Face - West end at corner (scaffolding level)	9/21/08	1	3.190	Asbestos	PCME	EMSL	9/22/08	< 0.00084	No	No	