

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|------------------------------|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| Target Air Quality Levels | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | |
| ASBESTOS-ST1-9/21/07 | 030731990-0001 | Southwest Area (sidewalk bridge level) | 9/21/07 | 1 | 3.170 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00078 | No | No | |
| ASBESTOS-ST2-9/21/07 | 030731990-0002 | Southeast Area (sidewalk bridge level) | 9/21/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00083 | No | No | |
| ASBESTOS-ST4-9/21/07 | 030731990-0003 | Northwest Area (street-level) | 9/21/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00080 | No | No | |
| ASBESTOS-ST5-9/21/07 | 030731990-0004 | Firehouse #10 (roof level) | 9/21/07 | 1 | 3.590 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00069 | No | No | |
| ASBESTOS-ST10-9/21/07 | 030731990-0005 | North Side Sidewalk Bridge | 9/21/07 | 1 | 3.110 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00079 | No | No | |
| ASBESTOS-ST11-9/21/07 | 030731990-0006 | 90 Trinity Place (roof level) | 9/21/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00082 | No | No | |
| ASBESTOS-ST12-9/21/07 | 030731990-0007 | 110 Greenwich Street (roof level) | 9/21/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00081 | No | No | |
| ASBESTOS-ST13-9/21/07 | 030731990-0008 | Marriott Hotel, 38th Floor (roof level) | 9/21/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00081 | No | No | |
| ASBESTOS-ST14-9/21/07 | 030731990-0009 | West Face - South end at corner (scaffolding level) | 9/21/07 | 1 | 3.150 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00078 | No | No | |
| ASBESTOS-ST15-9/21/07 | 030731990-0010 | South Face - East end at corner (scaffolding level) | 9/21/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00082 | No | No | |
| ASBESTOS-ST16-9/21/07 | 030731990-0011 | East Face - North end at corner (scaffolding level) | 9/21/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00081 | No | No | |
| ASBESTOS-ST17-9/21/07 | 030731990-0012 | North Face - West end at corner (scaffolding level) | 9/21/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/23/07 | < 0.00082 | No | No | |
| ASBESTOS-ST1-9/22/07 | 030732037-0001 | Southwest Area (sidewalk bridge level) | 9/22/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST2-9/22/07 | 030732037-0002 | Southeast Area (sidewalk bridge level) | 9/22/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST4-9/22/07 | 030732037-0003 | Northwest Area (street-level) | 9/22/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00083 | No | No | |
| ASBESTOS-ST5-9/22/07 | 030732037-0004 | Firehouse #10 (roof level) | 9/22/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST10-9/22/07 | 030732037-0005 | North Side Sidewalk Bridge | 9/22/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST11-9/22/07 | 030732037-0006 | 90 Trinity Place (roof level) | 9/22/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00083 | No | No | |
| ASBESTOS-ST12-9/22/07 | 030732037-0007 | 110 Greenwich Street (roof level) | 9/22/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00083 | No | No | |
| ASBESTOS-ST13-9/22/07 | 030732037-0008 | Marriott Hotel, 38th Floor (roof level) | 9/22/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST14-9/22/07 | 030732037-0009 | West Face - South end at corner (scaffolding level) | 9/22/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00087 | No | No | |
| ASBESTOS-ST15-9/22/07 | 030732037-0010 | South Face - East end at corner (scaffolding level) | 9/22/07 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00088 | No | No | |
| ASBESTOS-ST16-9/22/07 | 030732037-0011 | East Face - North end at corner (scaffolding level) | 9/22/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00088 | No | No | |
| ASBESTOS-ST17-9/22/07 | 030732037-0012 | North Face - West end at corner (scaffolding level) | 9/22/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00088 | No | No | |
| ASBESTOS-ST1-9/23/07 | 030732039-0001 | Southwest Area (sidewalk bridge level) | 9/23/07 | 1 | 2.900 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00085 | No | No | |
| ASBESTOS-ST2-9/23/07 | 030732039-0002 | Southeast Area (sidewalk bridge level) | 9/23/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST4-9/23/07 | 030732039-0003 | Northwest Area (street-level) | 9/23/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00083 | No | No | |
| ASBESTOS-ST5-9/23/07 | 030732039-0004 | Firehouse #10 (roof level) | 9/23/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST10-9/23/07 | 030732039-0005 | North Side Sidewalk Bridge | 9/23/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00080 | No | No | |
| ASBESTOS-ST11-9/23/07 | 030732039-0006 | 90 Trinity Place (roof level) | 9/23/07 | 1 | 3.000 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST12-9/23/07 | 030732039-0007 | 110 Greenwich Street (roof level) | 9/23/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00083 | No | No | |
| ASBESTOS-ST13-9/23/07 | 030732039-0008 | Marriott Hotel, 38th Floor (roof level) | 9/23/07 | 1 | 3.000 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST14-9/23/07 | 030732039-0009 | West Face - South end at corner (scaffolding level) | 9/23/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00082 | No | No | |
| ASBESTOS-ST15-9/23/07 | 030732039-0010 | South Face - East end at corner (scaffolding level) | 9/23/07 | 1 | 3.050 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST16-9/23/07 | 030732039-0011 | East Face - North end at corner (scaffolding level) | 9/23/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |
| ASBESTOS-ST17-9/23/07 | 030732039-0012 | North Face - West end at corner (scaffolding level) | 9/23/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/24/07 | < 0.00081 | No | No | |