

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-9/23/05A	030528677-0001	Southwest Area (street-level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/23/05B	030528677-0010	Southwest Area (street-level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/23/05A	030528677-0002	Southeast Area (street-level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/23/05B	030528677-0011	Southeast Area (street-level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/23/05A	030528677-0003	Northwest Area (street-level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/23/05B	030528677-0012	Northwest Area (street-level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/23/05A	030528677-0004	Firehouse #10 (roof level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/23/05B	030528677-0013	Firehouse #10 (roof level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/23/05A	030528677-0005	Southwest Area (roof level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/23/05B	030528677-0014	Southwest Area (roof level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/23/05A	030528677-0006	Southeast Area (roof level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/23/05B	030528677-0015	Southeast Area (roof level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/23/05A	030528677-0007	Northeast Area (roof level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/23/05B	030528677-0016	Northeast Area (roof level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	0.00086	No	No	
ASBESTOS-ST9-9/23/05A	030528677-0008	Northwest Area (roof level)	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/23/05B	030528677-0017	Northwest Area (roof level)	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/23/05A	030528677-0009	North Side Sidewalk Bridge	9/23/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/23/05B	030528677-0018	North Side Sidewalk Bridge	9/23/2005	2	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/24/05	030528675-0001	Southwest Area (street-level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/24/05	030528675-0002	Southeast Area (street-level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/24/05	030528675-0003	Northwest Area (street-level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/24/05	030528675-0004	Firehouse #10 (roof level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/24/05	030528675-0005	Southwest Area (roof level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/24/05	030528675-0006	Southeast Area (roof level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/24/05	030528675-0007	Northeast Area (roof level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/24/05	030528675-0008	Northwest Area (roof level)	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/24/05	030528675-0009	North Side Sidewalk Bridge	9/24/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/25/05	030528674-0001	Southwest Area (street-level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/25/05	030528674-0002	Southeast Area (street-level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/25/05	030528674-0003	Northwest Area (street-level)	9/25/2005	1	8.640	Asbestos	PCME	EMSL	9/26/2005	< 0.00029	No	No	
ASBESTOS-ST5-9/25/05	030528674-0004	Firehouse #10 (roof level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/25/05	030528674-0005	Southwest Area (roof level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/25/05	030528674-0006	Southeast Area (roof level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/25/05	030528674-0007	Northeast Area (roof level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/25/05	030528674-0008	Northwest Area (roof level)	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/25/05	030528674-0009	North Side Sidewalk Bridge	9/25/2005	1	2.880	Asbestos	PCME	EMSL	9/26/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/26/05	030528805-0001	Southwest Area (street-level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/26/05	030528805-0002	Southeast Area (street-level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/26/05	030528805-0003	Northwest Area (street-level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/26/05	030528805-0004	Firehouse #10 (roof level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/26/05	030528805-0005	Southwest Area (roof level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/26/05	030528805-0006	Southeast Area (roof level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/26/05	030528805-0007	Northeast Area (roof level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	0.00158	Yes	No	The cumulative average (0.000838 f/cc) was below the Target Air Quality Level; therefore, no corrective action was required.
ASBESTOS-ST9-9/26/05	030528805-0008	Northwest Area (roof level)	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/26/05	030528805-0009	North Side Sidewalk Bridge	9/26/2005	1	4.680	Asbestos	PCME	EMSL	9/27/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/27/05	030528950-0001	Southwest Area (street-level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/27/05	030528950-0002	Southeast Area (street-level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/27/05	030528950-0003	Northwest Area (street-level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/27/05	030528950-0004	Firehouse #10 (roof level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/27/05	030528950-0005	Southwest Area (roof level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/27/05	030528950-0006	Southeast Area (roof level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/27/05	030528950-0007	Northeast Area (roof level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/27/05	030528950-0008	Northwest Area (roof level)	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/27/05	030528950-0009	North Side Sidewalk Bridge	9/27/2005	1	4.680	Asbestos	PCME	EMSL	9/28/2005	< 0.00079	No	No	