

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-9/24/07	030732145-0001	Southwest Area (sidewalk bridge level)	9/24/07	1	2.920	Asbestos	PCME	EMSL	9/25/07	< 0.00085	No	No	
ASBESTOS-ST2-9/24/07	030732145-0002	Southeast Area (sidewalk bridge level)	9/24/07	1	2.970	Asbestos	PCME	EMSL	9/25/07	< 0.00083	No	No	
ASBESTOS-ST4-9/24/07	030732145-0003	Northwest Area (street-level)	9/24/07	1	3.050	Asbestos	PCME	EMSL	9/25/07	< 0.00088	No	No	
ASBESTOS-ST5-9/24/07	030732145-0004	Firehouse #10 (roof level)	9/24/07	1	3.090	Asbestos	PCME	EMSL	9/25/07	< 0.00087	No	No	
ASBESTOS-ST10-9/24/07	030732145-0005	North Side Sidewalk Bridge	9/24/07	1	3.060	Asbestos	PCME	EMSL	9/25/07	< 0.00088	No	No	
ASBESTOS-ST11-9/24/07	030732145-0006	90 Trinity Place (roof level)	9/24/07	1	2.960	Asbestos	PCME	EMSL	9/25/07	< 0.00083	No	No	
ASBESTOS-ST12-9/24/07	030732145-0007	110 Greenwich Street (roof level)	9/24/07	1	3.000	Asbestos	PCME	EMSL	9/25/07	< 0.00082	No	No	
ASBESTOS-ST13-9/24/07	030732145-0008	Marriott Hotel, 38th Floor (roof level)	9/24/07	1	2.960	Asbestos	PCME	EMSL	9/25/07	< 0.00083	No	No	
ASBESTOS-ST14-9/24/07	030732145-0009	West Face - South end at corner (scaffolding level)	9/24/07	1	2.920	Asbestos	PCME	EMSL	9/25/07	< 0.00085	No	No	
ASBESTOS-ST15-9/24/07	030732145-0010	South Face - East end at corner (scaffolding level)	9/24/07	1	2.970	Asbestos	PCME	EMSL	9/25/07	< 0.00083	No	No	
ASBESTOS-ST16-9/24/07	030732145-0011	East Face - North end at corner (scaffolding level)	9/24/07	1	3.090	Asbestos	PCME	EMSL	9/25/07	< 0.00080	No	No	
ASBESTOS-ST17-9/24/07	030732145-0012	North Face - West end at corner (scaffolding level)	9/24/07	1	2.960	Asbestos	PCME	EMSL	9/25/07	< 0.00083	No	No	
ASBESTOS-ST1-9/25/07	030732270-0001	Southwest Area (sidewalk bridge level)	9/25/07	1	3.150	Asbestos	PCME	EMSL	9/26/07	< 0.00078	No	No	
ASBESTOS-ST2-9/25/07	030732270-0002	Southeast Area (sidewalk bridge level)	9/25/07	1	3.010	Asbestos	PCME	EMSL	9/26/07	< 0.00082	No	No	
ASBESTOS-ST4-9/25/07	030732270-0003	Northwest Area (street-level)	9/25/07	1	3.210	Asbestos	PCME	EMSL	9/26/07	< 0.00077	No	No	
ASBESTOS-ST5-9/25/07	030732270-0004	Firehouse #10 (roof level)	9/25/07	1	3.070	Asbestos	PCME	EMSL	9/26/07	< 0.00080	No	No	
ASBESTOS-ST10-9/25/07	030732270-0005	North Side Sidewalk Bridge	9/25/07	1	3.090	Asbestos	PCME	EMSL	9/26/07	< 0.00080	No	No	
ASBESTOS-ST11-9/25/07	030732270-0006	90 Trinity Place (roof level)	9/25/07	1	2.960	Asbestos	PCME	EMSL	9/26/07	< 0.00083	No	No	
ASBESTOS-ST12-9/25/07	030732270-0007	110 Greenwich Street (roof level)	9/25/07	1	3.100	Asbestos	PCME	EMSL	9/26/07	< 0.00080	No	No	
ASBESTOS-ST13-9/25/07	030732270-0008	Marriott Hotel, 38th Floor (roof level)	9/25/07	1	3.050	Asbestos	PCME	EMSL	9/26/07	< 0.00081	No	No	
ASBESTOS-ST14-9/25/07	030732270-0009	West Face - South end at corner (scaffolding level)	9/25/07	1	3.000	Asbestos	PCME	EMSL	9/26/07	< 0.00082	No	No	
ASBESTOS-ST15-9/25/07	030732270-0010	South Face - East end at corner (scaffolding level)	9/25/07	1	3.060	Asbestos	PCME	EMSL	9/26/07	< 0.00081	No	No	
ASBESTOS-ST16-9/25/07	030732270-0011	East Face - North end at corner (scaffolding level)	9/25/07	1	3.010	Asbestos	PCME	EMSL	9/26/07	< 0.00082	No	No	
ASBESTOS-ST17-9/25/07	030732270-0012	North Face - West end at corner (scaffolding level)	9/25/07	1	3.000	Asbestos	PCME	EMSL	9/26/07	< 0.00082	No	No	
ASBESTOS-ST1-9/26/07	030732360-0001	Southwest Area (sidewalk bridge level)	9/26/07	1	3.220	Asbestos	PCME	EMSL	9/27/07	< 0.00084	No	No	
ASBESTOS-ST2-9/26/07	030732360-0002	Southeast Area (sidewalk bridge level)	9/26/07	1	3.200	Asbestos	PCME	EMSL	9/27/07	< 0.00084	No	No	
ASBESTOS-ST4-9/26/07	030732360-0003	Northwest Area (street-level)	9/26/07	1	2.990	Asbestos	PCME	EMSL	9/27/07	< 0.00083	No	No	
ASBESTOS-ST5-9/26/07	030732360-0004	Firehouse #10 (roof level)	9/26/07	1	3.050	Asbestos	PCME	EMSL	9/27/07	< 0.00081	No	No	
ASBESTOS-ST10-9/26/07	030732360-0005	North Side Sidewalk Bridge	9/26/07	1	3.040	Asbestos	PCME	EMSL	9/27/07	< 0.00081	No	No	
ASBESTOS-ST11-9/26/07	030732360-0006	90 Trinity Place (roof level)	9/26/07	1	3.000	Asbestos	PCME	EMSL	9/27/07	< 0.00082	No	No	
ASBESTOS-ST12-9/26/07	030732360-0007	110 Greenwich Street (roof level)	9/26/07	1	2.960	Asbestos	PCME	EMSL	9/27/07	< 0.00083	No	No	
ASBESTOS-ST13-9/26/07	030732360-0008	Marriott Hotel, 38th Floor (roof level)	9/26/07	1	3.040	Asbestos	PCME	EMSL	9/27/07	< 0.00081	No	No	
ASBESTOS-ST14-9/26/07	030732360-0009	West Face - South end at corner (scaffolding level)	9/26/07	1	3.000	Asbestos	PCME	EMSL	9/27/07	< 0.00082	No	No	
ASBESTOS-ST15-9/26/07	030732360-0010	South Face - East end at corner (scaffolding level)	9/26/07	1	3.060	Asbestos	PCME	EMSL	9/27/07	< 0.00081	No	No	
ASBESTOS-ST16-9/26/07	030732360-0011	East Face - North end at corner (scaffolding level)	9/26/07	1	3.090	Asbestos	PCME	EMSL	9/27/07	< 0.00080	No	No	
ASBESTOS-ST17-9/26/07	030732360-0012	North Face - West end at corner (scaffolding level)	9/26/07	1	3.060	Asbestos	PCME	EMSL	9/27/07	< 0.00081	No	No	