

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-9/29/08	030834404-0001	Southwest Area (sidewalk bridge level)	9/29/08	1	3.000	Asbestos	PCME	EMSL	9/30/08	< 0.00082	No	No	
ASBESTOS-ST2-9/29/08	030834404-0002	Southeast Area (sidewalk bridge level)	9/29/08	1	3.010	Asbestos	PCME	EMSL	9/30/08	< 0.00082	No	No	
ASBESTOS-ST4-9/29/08	030834404-0003	Northwest Area (street-level)	9/29/08	1	3.030	Asbestos	PCME	EMSL	9/30/08	< 0.00081	No	No	
ASBESTOS-ST5-9/29/08	030834404-0004	Firehouse #10 (roof level)	9/29/08	1	3.070	Asbestos	PCME	EMSL	9/30/08	< 0.00080	No	No	
ASBESTOS-ST10-9/29/08	030834404-0005	North Side Sidewalk Bridge	9/29/08	1	3.010	Asbestos	PCME	EMSL	9/30/08	< 0.00082	No	No	
ASBESTOS-ST11-9/29/08	030834404-0006	90 Trinity Place (roof level)	9/29/08	1	3.090	Asbestos	PCME	EMSL	9/30/08	< 0.00080	No	No	
ASBESTOS-ST12-9/29/08	030834404-0007	110 Greenwich Street (roof level)	9/29/08	1	3.030	Asbestos	PCME	EMSL	9/30/08	< 0.00081	No	No	
ASBESTOS-ST13-9/29/08	030834404-0008	Marriott Hotel, 38th Floor (roof level)	9/29/08	1	3.000	Asbestos	PCME	EMSL	9/30/08	< 0.00082	No	No	
ASBESTOS-ST14-9/29/08	030834404-0009	West Face - South end at corner (scaffolding level)	9/29/08	1	3.080	Asbestos	PCME	EMSL	9/30/08	< 0.00080	No	No	
ASBESTOS-ST15-9/29/08	030834404-0010	South Face - East end at corner (scaffolding level)	9/29/08	1	3.120	Asbestos	PCME	EMSL	9/30/08	< 0.00079	No	No	
ASBESTOS-ST16-9/29/08	030834404-0011	East Face - North end at corner (scaffolding level)	9/29/08	1	3.070	Asbestos	PCME	EMSL	9/30/08	< 0.00080	No	No	
ASBESTOS-ST17-9/29/08	030834404-0012	North Face - West end at corner (scaffolding level)	9/29/08	1	3.130	Asbestos	PCME	EMSL	9/30/08	< 0.00079	No	No	
ASBESTOS-ST1-9/30/08	030834608-0001	Southwest Area (sidewalk bridge level)	9/30/08	1	2.990	Asbestos	PCME	EMSL	10/1/08	< 0.00083	No	No	
ASBESTOS-ST2-9/30/08	030834608-0002	Southeast Area (sidewalk bridge level)	9/30/08	1	2.900	Asbestos	PCME	EMSL	10/1/08	< 0.00085	No	No	
ASBESTOS-ST4-9/30/08	030834608-0003	Northwest Area (street-level)	9/30/08	1	3.050	Asbestos	PCME	EMSL	10/1/08	< 0.00081	No	No	
ASBESTOS-ST5-9/30/08	030834608-0004	Firehouse #10 (roof level)	9/30/08	1	2.880	Asbestos	PCME	EMSL	10/1/08	< 0.00086	No	No	
ASBESTOS-ST10-9/30/08	030834608-0005	North Side Sidewalk Bridge	9/30/08	1	2.840	Asbestos	PCME	EMSL	10/1/08	< 0.00087	No	No	
ASBESTOS-ST11-9/30/08	030834608-0006	90 Trinity Place (roof level)	9/30/08	1	3.130	Asbestos	PCME	EMSL	10/1/08	< 0.00086	No	No	
ASBESTOS-ST12-9/30/08	030834608-0007	110 Greenwich Street (roof level)	9/30/08	1	3.010	Asbestos	PCME	EMSL	10/1/08	< 0.00082	No	No	
ASBESTOS-ST13-9/30/08	030834608-0008	Marriott Hotel, 38th Floor (roof level)	9/30/08	1	3.050	Asbestos	PCME	EMSL	10/1/08	< 0.00081	No	No	
ASBESTOS-ST14-9/30/08	030834608-0009	West Face - South end at corner (scaffolding level)	9/30/08	1	2.970	Asbestos	PCME	EMSL	10/1/08	< 0.00083	No	No	
ASBESTOS-ST15-9/30/08	030834608-0010	South Face - East end at corner (scaffolding level)	9/30/08	1	3.090	Asbestos	PCME	EMSL	10/1/08	< 0.00087	No	No	
ASBESTOS-ST16-9/30/08	030834608-0011	East Face - North end at corner (scaffolding level)	9/30/08	1	3.040	Asbestos	PCME	EMSL	10/1/08	< 0.00081	No	No	
ASBESTOS-ST17-9/30/08	030834608-0012	North Face - West end at corner (scaffolding level)	9/30/08	1	3.100	Asbestos	PCME	EMSL	10/1/08	< 0.00087	No	No	