

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/8/08	030835755-0001	Southwest Area (sidewalk bridge level)	10/8/08	1	3.060	Asbestos	PCME	EMSL	10/9/08	< 0.00081	No	No	
ASBESTOS-ST2-10/8/08	030835755-0002	Southeast Area (sidewalk bridge level)	10/8/08	1	3.090	Asbestos	PCME	EMSL	10/9/08	< 0.00080	No	No	
ASBESTOS-ST4-10/8/08	030835755-0003	Northwest Area (street-level)	10/8/08	1	3.070	Asbestos	PCME	EMSL	10/9/08	< 0.00080	No	No	
ASBESTOS-ST5-10/8/08	030835755-0004	Firehouse #10 (roof level)	10/8/08	1	3.010	Asbestos	PCME	EMSL	10/9/08	< 0.00082	No	No	
ASBESTOS-ST10-10/8/08	030835755-0005	North Side Sidewalk Bridge	10/8/08	1	3.120	Asbestos	PCME	EMSL	10/9/08	< 0.00079	No	No	
ASBESTOS-ST11-10/8/08	030835755-0006	90 Trinity Place (roof level)	10/8/08	1	2.960	Asbestos	PCME	EMSL	10/9/08	< 0.00083	No	No	
ASBESTOS-ST12-10/8/08	030835755-0007	110 Greenwich Street (roof level)	10/8/08	1	2.990	Asbestos	PCME	EMSL	10/9/08	< 0.00083	No	No	
ASBESTOS-ST13-10/8/08	030835755-0008	Marriott Hotel, 38th Floor (roof level)	10/8/08	1	3.030	Asbestos	PCME	EMSL	10/9/08	< 0.00081	No	No	
ASBESTOS-ST14-10/8/08	030835755-0009	West Face - South end at corner (scaffolding level)	10/8/08	1	3.070	Asbestos	PCME	EMSL	10/9/08	< 0.00080	No	No	
ASBESTOS-ST15-10/8/08	030835755-0010	South Face - East end at corner (scaffolding level)	10/8/08	1	3.100	Asbestos	PCME	EMSL	10/9/08	< 0.00080	No	No	
ASBESTOS-ST16-10/8/08	030835755-0011	East Face - North end at corner (scaffolding level)	10/8/08	1	3.090	Asbestos	PCME	EMSL	10/9/08	< 0.00080	No	No	
ASBESTOS-ST17-10/8/08	030835755-0012	North Face - West end at corner (scaffolding level)	10/8/08	1	3.130	Asbestos	PCME	EMSL	10/9/08	< 0.00079	No	No	
ASBESTOS-ST1-10/9/08	030835884-0001	Southwest Area (sidewalk bridge level)	10/9/08	1	3.080	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST2-10/9/08	030835884-0002	Southeast Area (sidewalk bridge level)	10/9/08	1	3.100	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST4-10/9/08	030835884-0003	Northwest Area (street-level)	10/9/08	1	3.090	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST5-10/9/08	030835884-0004	Firehouse #10 (roof level)	10/9/08	1	2.960	Asbestos	PCME	EMSL	10/10/08	< 0.00083	No	No	
ASBESTOS-ST10-10/9/08	030835884-0005	North Side Sidewalk Bridge	10/9/08	1	3.110	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST100-10/9/08	030835884-0013	Station 10 Field Duplicate	10/9/08	1	3.060	Asbestos	PCME	EMSL	10/10/08	< 0.00088	No	No	
ASBESTOS-ST11-10/9/08	030835884-0006	90 Trinity Place (roof level)	10/9/08	1	3.080	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST12-10/9/08	030835884-0007	110 Greenwich Street (roof level)	10/9/08	1	3.030	Asbestos	PCME	EMSL	10/10/08	< 0.00081	No	No	
ASBESTOS-ST13-10/9/08	030835884-0008	Marriott Hotel, 38th Floor (roof level)	10/9/08	1	3.090	Asbestos	PCME	EMSL	10/10/08	< 0.00087	No	No	
ASBESTOS-ST14-10/9/08	030835884-0009	West Face - South end at corner (scaffolding level)	10/9/08	1	3.030	Asbestos	PCME	EMSL	10/10/08	< 0.00081	No	No	
ASBESTOS-ST15-10/9/08	030835884-0010	South Face - East end at corner (scaffolding level)	10/9/08	1	3.040	Asbestos	PCME	EMSL	10/10/08	< 0.00081	No	No	
ASBESTOS-ST16-10/9/08	030835884-0011	East Face - North end at corner (scaffolding level)	10/9/08	1	3.120	Asbestos	PCME	EMSL	10/10/08	< 0.00086	No	No	
ASBESTOS-ST17-10/9/08	030835884-0012	North Face - West end at corner (scaffolding level)	10/9/08	1	3.160	Asbestos	PCME	EMSL	10/10/08	< 0.00085	No	No	
ASBESTOS-ST1-10/10/08	030836033-0001	Southwest Area (sidewalk bridge level)	10/10/08	1	3.000	Asbestos	PCME	EMSL	10/11/08	< 0.00082	No	No	
ASBESTOS-ST2-10/10/08	030836033-0002	Southeast Area (sidewalk bridge level)	10/10/08	1	3.040	Asbestos	PCME	EMSL	10/11/08	< 0.00081	No	No	
ASBESTOS-ST4-10/10/08	030836033-0003	Northwest Area (street-level)	10/10/08	1	3.020	Asbestos	PCME	EMSL	10/11/08	< 0.00082	No	No	
ASBESTOS-ST5-10/10/08	030836033-0004	Firehouse #10 (roof level)	10/10/08	1	3.030	Asbestos	PCME	EMSL	10/11/08	< 0.00081	No	No	
ASBESTOS-ST10-10/10/08	030836033-0005	North Side Sidewalk Bridge	10/10/08	1	3.030	Asbestos	PCME	EMSL	10/11/08	< 0.00081	No	No	
ASBESTOS-ST11-10/10/08	030836033-0006	90 Trinity Place (roof level)	10/10/08	1	2.970	Asbestos	PCME	EMSL	10/11/08	< 0.00083	No	No	
ASBESTOS-ST12-10/10/08	030836033-0007	110 Greenwich Street (roof level)	10/10/08	1	2.990	Asbestos	PCME	EMSL	10/11/08	< 0.00083	No	No	
ASBESTOS-ST13-10/10/08	030836033-0008	Marriott Hotel, 38th Floor (roof level)	10/10/08	1	3.060	Asbestos	PCME	EMSL	10/11/08	< 0.00081	No	No	
ASBESTOS-ST14-10/10/08	030836033-0009	West Face - South end at corner (scaffolding level)	10/10/08	1	2.950	Asbestos	PCME	EMSL	10/11/08	< 0.00084	No	No	
ASBESTOS-ST15-10/10/08	030836033-0010	South Face - East end at corner (scaffolding level)	10/10/08	1	2.910	Asbestos	PCME	EMSL	10/11/08	< 0.00085	No	No	
ASBESTOS-ST16-10/10/08	030836033-0011	East Face - North end at corner (scaffolding level)	10/10/08	1	2.840	Asbestos	PCME	EMSL	10/11/08	< 0.00087	No	No	
ASBESTOS-ST17-10/10/08	030836033-0012	North Face - West end at corner (scaffolding level)	10/10/08	1	2.740	Asbestos	PCME	EMSL	10/11/08	< 0.00083	No	No	