

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-10/10/07	030733573-0001	Southwest Area (sidewalk bridge level)	10/10/07	1	3.070	Asbestos	PCME	EMSL	10/11/07	< 0.00080	No	No	
ASBESTOS-ST2-10/10/07	030733573-0002	Southeast Area (sidewalk bridge level)	10/10/07	1	2.990	Asbestos	PCME	EMSL	10/11/07	< 0.00083	No	No	
ASBESTOS-ST4-10/10/07	030733573-0003	Northwest Area (street-level)	10/10/07	1	2.990	Asbestos	PCME	EMSL	10/11/07	< 0.00083	No	No	
ASBESTOS-ST5-10/10/07	030733573-0004	Firehouse #10 (roof level)	10/10/07	1	2.960	Asbestos	PCME	EMSL	10/11/07	< 0.00083	No	No	
ASBESTOS-ST10-10/10/07	030733573-0005	North Side Sidewalk Bridge	10/10/07	1	2.970	Asbestos	PCME	EMSL	10/11/07	< 0.00083	No	No	
ASBESTOS-ST11-10/10/07	030733573-0006	90 Trinity Place (roof level)	10/10/07	1	3.000	Asbestos	PCME	EMSL	10/11/07	< 0.00082	No	No	
ASBESTOS-ST12-10/10/07	030733573-0007	110 Greenwich Street (roof level)	10/10/07	1	3.050	Asbestos	PCME	EMSL	10/11/07	< 0.00081	No	No	
ASBESTOS-ST13-10/10/07	030733573-0008	Marriott Hotel, 38th Floor (roof level)	10/10/07	1	2.940	Asbestos	PCME	EMSL	10/11/07	< 0.00084	No	No	
ASBESTOS-ST14-10/10/07	030733573-0009	West Face - South end at corner (scaffolding level)	10/10/07	1	3.060	Asbestos	PCME	EMSL	10/11/07	< 0.00081	No	No	
ASBESTOS-ST15-10/10/07	030733573-0010	South Face - East end at corner (scaffolding level)	10/10/07	1	3.120	Asbestos	PCME	EMSL	10/11/07	< 0.00079	No	No	
ASBESTOS-ST16-10/10/07	030733573-0011	East Face - North end at corner (scaffolding level)	10/10/07	1	3.060	Asbestos	PCME	EMSL	10/11/07	< 0.00081	No	No	
ASBESTOS-ST17-10/10/07	030733573-0012	North Face - West end at corner (scaffolding level)	10/10/07	1	2.990	Asbestos	PCME	EMSL	10/11/07	< 0.00083	No	No	
ASBESTOS-ST1-10/11/07	030733690-0001	Southwest Area (sidewalk bridge level)	10/11/07	1	2.980	Asbestos	PCME	EMSL	10/12/07	< 0.00083	No	No	
ASBESTOS-ST4-10/11/07	030733690-0002	Northwest Area (street-level)	10/11/07	1	2.800	Asbestos	PCME	EMSL	10/12/07	< 0.00088	No	No	
ASBESTOS-ST5-10/11/07	030733690-0003	Firehouse #10 (roof level)	10/11/07	1	2.960	Asbestos	PCME	EMSL	10/12/07	< 0.00083	No	No	
ASBESTOS-ST10-10/11/07	030733690-0004	North Side Sidewalk Bridge	10/11/07	1	3.040	Asbestos	PCME	EMSL	10/12/07	< 0.00081	No	No	
ASBESTOS-ST11-10/11/07	030733690-0005	90 Trinity Place (roof level)	10/11/07	1	3.020	Asbestos	PCME	EMSL	10/12/07	< 0.00082	No	No	
ASBESTOS-ST12-10/11/07	030733690-0006	110 Greenwich Street (roof level)	10/11/07	1	3.020	Asbestos	PCME	EMSL	10/12/07	< 0.00082	No	No	
ASBESTOS-ST14-10/11/07	030733690-0007	West Face - South end at corner (scaffolding level)	10/11/07	1	2.970	Asbestos	PCME	EMSL	10/12/07	< 0.00083	No	No	
ASBESTOS-ST15-10/11/07	030733690-0008	South Face - East end at corner (scaffolding level)	10/11/07	1	3.050	Asbestos	PCME	EMSL	10/12/07	< 0.00081	No	No	
ASBESTOS-ST16-10/11/07	030733690-0009	East Face - North end at corner (scaffolding level)	10/11/07	1	3.010	Asbestos	PCME	EMSL	10/12/07	< 0.00082	No	No	
ASBESTOS-ST17-10/11/07	030733690-0010	North Face - West end at corner (scaffolding level)	10/11/07	1	2.940	Asbestos	PCME	EMSL	10/12/07	< 0.00084	No	No	
ASBSETOS-ST1-10/12/07	030733780-0001	Southwest Area (sidewalk bridge level)	10/12/07	1	3.000	Asbestos	PCME	EMSL	10/13/07	< 0.00082	No	No	
ASBSETOS-ST2-10/12/07	030733780-0002	Southeast Area (sidewalk bridge level)	10/12/07	1	2.620	Asbestos	PCME	EMSL	10/13/07	< 0.00087	No	No	
ASBSETOS-ST4-10/12/07	030733780-0003	Northwest Area (street-level)	10/12/07	1	2.920	Asbestos	PCME	EMSL	10/13/07	< 0.00085	No	No	
ASBSETOS-ST5-10/12/07	030733780-0004	Firehouse #10 (roof level)	10/12/07	1	3.150	Asbestos	PCME	EMSL	10/13/07	< 0.00078	No	No	
ASBSETOS-ST10-10/12/07	030733780-0005	North Side Sidewalk Bridge	10/12/07	1	2.860	Asbestos	PCME	EMSL	10/13/07	< 0.00086	No	No	
ASBSETOS-ST11-10/12/07	030733780-0006	90 Trinity Place (roof level)	10/12/07	1	3.000	Asbestos	PCME	EMSL	10/13/07	< 0.00082	No	No	
ASBSETOS-ST12-10/12/07	030733780-0007	110 Greenwich Street (roof level)	10/12/07	1	3.010	Asbestos	PCME	EMSL	10/13/07	< 0.00082	No	No	
ASBSETOS-ST13-10/12/07	030733780-0008	Marriott Hotel, 38th Floor (roof level)	10/12/07	1	2.960	Asbestos	PCME	EMSL	10/13/07	< 0.00083	No	No	
ASBSETOS-ST14-10/12/07	030733780-0009	West Face - South end at corner (scaffolding level)	10/12/07	1	3.010	Asbestos	PCME	EMSL	10/13/07	< 0.00082	No	No	
ASBSETOS-ST15-10/12/07	030733780-0010	South Face - East end at corner (scaffolding level)	10/12/07	1	3.000	Asbestos	PCME	EMSL	10/13/07	< 0.00082	No	No	
ASBSETOS-ST16-10/12/07	030733780-0011	East Face - North end at corner (scaffolding level)	10/12/07	1	3.030	Asbestos	PCME	EMSL	10/13/07	< 0.00081	No	No	
ASBSETOS-ST17-10/12/07	030733780-0012	North Face - West end at corner (scaffolding level)	10/12/07	1	2.980	Asbestos	PCME	EMSL	10/13/07	< 0.00083	No	No	

Note:

1. Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on October 11, 2007 was not available for analysis on account of power failure.
2. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on October 11, 2007 was not available for analysis on account of sample damage.