

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-10/14/05	030530982-0001	Southwest Area (street-level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/14/05	030530982-0002	Southeast Area (sidewalk bridge level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/14/05	030530982-0003	Northwest Area (street-level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/14/05	030530982-0004	Firehouse #10 (roof level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/14/05	030530982-0005	North Side Sidewalk Bridge	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/14/05	030530982-0006	90 Trinity Place (roof level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/14/05	030530982-0007	110 Greenwich Street (roof level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/14/05	030530982-0008	Marriott Hotel, 38th Floor (roof level)	10/14/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/15/05	030530984-0001	Southwest Area (street-level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/15/05	030530984-0002	Southeast Area (sidewalk bridge level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/15/05	030530984-0003	Northwest Area (street-level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/15/05	030530984-0004	Firehouse #10 (roof level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/15/05	030530984-0005	North Side Sidewalk Bridge	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST100-10/15/05	030530984-0009	Station 10 Field Duplicate	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/15/05	030530984-0006	90 Trinity Place (roof level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/15/05	030530984-0007	110 Greenwich Street (roof level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/15/05	030530984-0008	Marriott Hotel, 38th Floor (roof level)	10/15/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/16/05	030530986-0001	Southwest Area (street-level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/16/05	030530986-0002	Southeast Area (sidewalk bridge level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/16/05	030530986-0003	Northwest Area (street-level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/16/05	030530986-0004	Firehouse #10 (roof level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/16/05	030530986-0005	North Side Sidewalk Bridge	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/16/05	030530986-0006	90 Trinity Place (roof level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/16/05	030530986-0007	110 Greenwich Street (roof level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/16/05	030530986-0008	Marriott Hotel, 38th Floor (roof level)	10/16/2005	1	2.890	Asbestos	PCME	EMSL	10/17/2005	0.00085	No	No	
ASBESTOS-ST1-10/17/05	030531094-0001	Southwest Area (street-level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/17/05	030531094-0002	Southeast Area (sidewalk bridge level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/17/05	030531094-0003	Northwest Area (street-level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/17/05	030531094-0004	Firehouse #10 (roof level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/17/05	030531094-0005	North Side Sidewalk Bridge	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/17/05	030531094-0006	90 Trinity Place (roof level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/17/05	030531094-0007	110 Greenwich Street (roof level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/17/05	030531094-0008	Marriott Hotel, 38th Floor (roof level)	10/17/2005	1	2.890	Asbestos	PCME	EMSL	10/18/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/18/05	030531234-0001	Southwest Area (street-level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/18/05	030531234-0002	Southeast Area (sidewalk bridge level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/18/05	030531234-0003	Northwest Area (street-level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/18/05	030531234-0004	Firehouse #10 (roof level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/18/05	030531234-0005	North Side Sidewalk Bridge	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/18/05	030531234-0006	90 Trinity Place (roof level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/18/05	030531234-0007	110 Greenwich Street (roof level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/18/05	030531234-0008	Marriott Hotel, 38th Floor (roof level)	10/18/2005	1	2.890	Asbestos	PCME	EMSL	10/19/2005	< 0.00085	No	No	